

Pre-Demolition Asbestos- Containing Materials Survey Report

E-COMM Buildings 2, 3, 4, 6 and the Former Mission Building

Albany, New York

CHA Project Number: 16433.1200.1106

Prepared for:

*Albany Convention Center Authority
The R.B. Wing Building
386 Broadway
Albany, New York 12207*

Prepared by:




*III Winner's Circle
Albany, New York 12205
(518) 453-4500*

April 15, 2010

QUALIFICATIONS AND CERTIFICATION STATEMENT


This Pre-Demolition Asbestos-Containing Materials Survey Report was compiled by a qualified environmental scientist who is also a NYS certified asbestos inspector employed by CHA. This report has been prepared expressly for the use of the Albany Convention Center Authority. No other entities are entitled to rely upon this report unless our express written consent is first obtained. All conclusions drawn were based on CHA's review of available historical data, field inspection and analytical results from sampling performed during the course of this project. Recommendations are submitted based on CHA's knowledge, experience, and professional judgment.

Inspection and Report Completed By:



James Morey
Scientist II

Report Reviewed By:



Seth H. Fowler, CHMM
Associate

TABLE OF CONTENTS

1.0	INTRODUCTION	1
2.0	SCOPE OF WORK	1
2.1	ASBESTOS-CONTAINING MATERIALS SURVEY	1
2.2	LIMITATIONS	2
3.0	ASBESTOS-CONTAINING MATERIALS SURVEY	2
3.1	RECORD REVIEW	2
3.2	E-COMM BUILDING 2	2
3.3	E-COMM BUILDING 3	4
3.4	E-COMM BUILDING 4	4
3.5	E-COMM BUILDING 6	4
3.6	FORMER MISSION BUILDING	4
4.0	RESULTS	5
5.0	CONCLUSIONS AND RECOMMENDATIONS	6

FIGURES

FIGURE 1:	Sample Location Plan – Building 2 – Basement, First, Second and Third Floors
FIGURE 2:	Sample Location Plan – Building 2 – Fourth Floor and Roof Level
FIGURE 3:	Sample Location Plan – Building 3 – First and Second Floors
FIGURE 4:	Sample Location Plan – Building 3 – Third and Fourth Floors
FIGURE 5:	Sample Location Plan – Building 3 – Penthouse and Roof Level
FIGURE 6:	Sample Location Plan – Building 4 – Basement, First, Second and Third Floors
FIGURE 7:	Sample Location Plan – Building 4 – Fourth Floor and Roof Level
FIGURE 8:	Sample Location Plan – Building 6 – Basement and First Floor
FIGURE 9:	Sample Location Plan – Building 6 – Second and Third Floors
FIGURE 10:	Sample Location Plan – Building 6 – Fourth Floor and Roof Level
FIGURE 11:	Sample Location Plan – Mission Building

TABLES

TABLE 1:	Confirmed Asbestos-Containing Material Summary
TABLE 2:	Asbestos Bulk Sample Summary
TABLE 2:	Room By Room Asbestos-Containing Material Inventory

APPENDICES

APPENDIX A:	Asbestos Bulk Sample Analysis
APPENDIX B:	Personnel and Laboratory Licenses

1.0 INTRODUCTION

CHA was retained by the Albany Convention Center Authority to complete a Pre-Demolition Asbestos-Containing Material (ACM) Survey of E-COMM Square Buildings and the Former Mission Building located on Broadway and Hudson Streets in Albany, New York. CHA visited Buildings 2-4, Building 6 and the Former Mission Building during the weeks of March 15-19th and 22-26th, 2010 and inspected all accessible interior and exterior areas of the subject buildings including the roof systems, mechanical spaces and ceiling spaces. The objective of the survey was to identify and characterize suspect ACM associated with the subject buildings prior to their planned demolition.

This survey report consists of five sections. The first of which is this Introduction. Section 2.0 presents the Scope of Work which outlines the parameters by which this project was performed and the limitations that were encountered. Section 3.0 – Asbestos-Containing Materials Survey, is a brief discussion of historical information and data available to CHA in completing the assessment and discusses the findings of the asbestos inspection while Section 4.0 provides an overview of all analytical results. Section 5.0 presents CHA's Conclusions and Recommendations regarding the status of the building that was inspected.

2.0 SCOPE OF WORK

2.1 ASBESTOS-CONTAINING MATERIALS SURVEY

The asbestos-containing materials survey was performed according to the scope of work provided below. All work has been completed in accordance with federal, state, and local regulations.

1. A New York State Department of Labor (NYSDOL)-certified asbestos building inspector performed a site visit and room by room survey to identify and assess the condition, location, friability and quantity of suspect asbestos-containing materials associated with the subject buildings.
2. The inspector reviewed any and all available drawings for the subject buildings as well as any complete or partial asbestos inspections or abatement documentation previously completed.
3. Following the review of available drawings, the inspector collected bulk samples of identified suspect asbestos-containing materials following the protocols referenced in 40 CFR Part 763.86 Subpart E (ASHERA).
4. All bulk samples collected by CHA were analyzed by AmeriSci Boston, a laboratory accredited by the New York State Department of Health (NYSDOH) under its Environmental Laboratory Approval Program (ELAP) for the analysis of asbestos bulk samples.

2.2 LIMITATIONS

1. The conclusions presented in this report are based on information gathered in accordance with the Scope of Work defined in this section of the report.
2. The figures provided in this report were digitized from building floor plans provided prior to the survey fieldwork and field-verified. The figures are drafted to an approximate scale.
3. Asbestos sample collection is a destructive process by nature. As such, only minimally destructive investigations (impacting walls and floors in corners and away from high traffic areas) were utilized to the extent practicable by inspectors in Building 4, Building 6 and the Former Mission Building as these are unoccupied buildings scheduled for demolition. Buildings 2 and 3 were largely occupied by building tenants during the site visits thus destructive investigations were not utilized in these buildings. CHA attempted to inspect for concealed suspect materials beneath carpets, behind sheetrock walls and within chases in unoccupied office spaces within Building 2 and 3 whenever possible. Due to the occupied nature of Buildings 2 and 3, concealed plumbing chases and suspect materials often times found beneath carpets and behind sheetrock walls may not have been identified and may exist.
4. CHA did not enter the first floor chapel portion of the Mission Building due to the lack of structurally sound floors. Materials listed on Table 3 for this room were observed from the threshold and additional suspect materials may exist that were not able to be observed from this vantage point.

3.0 ASBESTOS-CONTAINING MATERIAL SURVEY

As discussed in Sections 1.0 and 2.0 of this report, the objective of this survey was to identify and sample all suspect asbestos-containing materials. The following subsections detail the observations made and samples collected during the site inspections. See Figures 1 through 10 for the suspect asbestos-containing material bulk sample locations.

3.1 RECORD REVIEW

A limited set of building plans were provided to CHA prior to the survey site visit which were used to draft the figures provided in this report. These drawings were schematic in nature, lacked many interior walls and building sections, and were specifically associated with renovations rather than original construction drawings. No historical asbestos-containing material surveys or analytical data was provided prior to the survey site visits or during the preparation of this report.

3.2 E-COMM BUILDING 2

Building 2 is a four-story brick office building connected to Building 3 by an enclosed breezeway. A full basement extends the entire footprint of the building and consists of two large

storage rooms, an electrical service room, elevator machine room and mechanical room. Concrete floors, concrete block walls and wood floor trusses and planking were observed throughout. Suspect conduit penetration grout was observed in the electrical service room adjacent to the junction boxes. This grout was quantified and sampled per Section 2.1 of this report.

The upper floors of Building 2 consist of individual office suites, common bathrooms, an electrical service room and a custodial closet. The office suites and kitchens consisted largely of carpeted floors with limited areas of vinyl tile with vinyl cove base (and their respective mastics and leveling compound), sheetrock walls (and associated joint compound) and 2' x 2' drop ceiling tiles with wood trusses above. The carpet mastic, vinyl tiles and cove bases (and their mastic and leveling compound), sheetrock and joint compound, and ceiling tiles are all considered suspect for asbestos and were quantified and sampled for laboratory analysis. An undercoating material was observed on kitchen sinks throughout Building 2. The undercoating is considered a suspect ACM and was quantified and sampled for asbestos analysis. The bathrooms throughout Building 2 have 1"x 1" ceramic tile floors and walls with sheetrock ceilings. The ceramic tile and grout were quantified and sampled for asbestos laboratory analysis.

The roof level of Building 2 is one elevation that is accessible from the west stairwell. A suspect asbestos-containing multi-layer built-up roofing system was observed to overlay a wood deck. Additionally, the entire roof is covered with a suspect silvercoat material and has suspect black roof patch and sealant applied periodically over roof field and flashing areas as well as the parapet walls. Pitch pockets which anchor roof-mounted mechanical equipment and seal electrical conduit entrances into the building were observed as well. These pitch pockets are also considered suspect for asbestos. The parapet walls are capped with coping stones sealed to one another along the perimeter of the roof with suspect asbestos-containing grout. The silvercoat, layers of built-up roofing, flashings, roof patch and sealant, pitch pockets, and coping stone grout were quantified and sampled for asbestos laboratory analysis.

The window systems are consistent throughout the building and are sealed along their exterior by suspect asbestos-containing glazing compound. This glazing compound was quantified by system and sampled for asbestos laboratory analysis.

As stated in Section 2.2, Building 2 was occupied by tenants during this pre-demolition asbestos-containing material survey. Due to this circumstance, CHA was unable to employ destructive investigations to inspect for concealed suspect ACM's.

3.3 E-COMM BUILDING 3

Building 3 is a four-story slab-on-grade brick building with a penthouse level and attic space. Much like Building 2, Building 3 consists of separate office suites connected by common corridors and shared bathrooms. The office spaces and kitchens have typical finishes consisting of carpeting (with mastic), vinyl flooring and cove base (and associated mastics and leveling compound), sheetrock walls (with joint compound), and drop ceiling tiles; all of which are suspect for asbestos. The kitchens have the same type of suspect sink undercoating as was

observed in Building 2. The bathrooms are typical throughout and have suspect ceramic tile floors and walls with grout, limited areas of suspect linoleum flooring and sheetrock ceilings. All suspect materials were quantified and sampled for laboratory analysis.

Sheetrock walls within the elevator lobbies on each floor and the penthouse are coated with a textured wall paint that is considered suspect for asbestos. This wall paint was quantified in each area it was observed and was sampled for asbestos analysis.

Building three consists of three separate roofs; two lower sections separated by an expansion joint and a penthouse roof. The lower roofs on Building 3 consist of rubber roofing over an older multi-layered built-up roofing system with various pitch pockets and seam sealants. The penthouse roof and smaller elevator roof consists just of the multi-layered built-up roofing with one location of rolled roofing patch along the southwest corner. One wall on the penthouse roof has remnants of suspect caulk running vertically up the brick wall. Suspect flashing sealant was also observed along the east parapet wall. The built-up roofing layers, seam sealant, pitch pockets, rolled roof patch, and caulk were quantified and sampled for asbestos laboratory analysis.

The window systems are consistent throughout the building and are sealed along their exterior by suspect asbestos-containing glazing compound. This glazing compound was quantified by system and sampled for asbestos laboratory analysis.

As stated in Section 2.2, Building 3 was occupied by tenants during this pre-demolition asbestos-containing material survey. Due to this circumstance, CHA was unable to employ destructive investigations to inspect for concealed suspect ACM's.

3.4 E-COMM BUILDING 4

Building 4 is an unoccupied four-story brick office building located along Broadway. The basement consists of concrete floors, concrete block and field stone walls, and wood trusses, wood floorboards and fiberglass batt insulation overhead. The fiberglass insulation has suspect mastic along one side of the insulation paper. One linear foot of suspect pipe wrap was observed on one pipe within the basement. This fiberglass insulation paper and the pipe wrap were sampled for asbestos analysis.

The first floor consists of a vacant restaurant, common bathrooms, electrical panel room and conference room. The majority of the floors throughout are suspect ceramic and/or clay tile with grout, with limited areas of suspect linoleum and vinyl floor tiles over leveling compound. The walls and ceilings throughout are suspect sheetrock (and joint compound) and 2' x 2' drop ceiling tiles. An older wood ceiling exists above the drop ceiling system which has a suspect insulation paper. All suspect building materials were quantified and sampled for asbestos analysis.

The upper floors consist solely of office space. These offices are carpeted with leveling compound on wood subfloors. Sheetrock walls (with joint compound) and ceilings with limited

areas of drop ceiling systems were observed throughout. Suspect sink undercoating and vinyl flooring were observed in the office kitchens and were sampled for analysis. The bathrooms are consistent throughout and consist of suspect 1"x 1" ceramic floor and wall tiles with suspect grout and suspect sheetrock ceilings.

The exterior of Building 4 has a lightweight concrete patch along its concrete foundation that is suspect for asbestos. The first floor windows and doors are sealed with suspect glazing compound. These suspect materials were quantified and sampled for analysis.

The roof over Building 4 is a rubber membrane system on fiberboard overlaying a wood plank deck. Various suspect asbestos-containing sealants coat the flashings and rubber roof seams and suspect pitch pockets anchor the roof mounted mechanical units. The sealants, fiberboard, and pitch pockets were quantified and sampled per Section 2.1.

3.5 E-COMM BUILDING 6

Building 6 is an unoccupied four-story brick building consisting of first floor retail storefronts and storage space and manufacturing and warehouse space on the upper floors. The basement level of the building extends from the east end of the building approximately halfway to the west end of the building (see Figure 5). The basement has four rooms: two large storage rooms, a boiler room and the basement landing. The floors and walls are concrete and brick throughout and the ceiling consists of the wood floor boards of the first floor. The boiler room has transite panels lining the wood floor directly above the boiler. These panels are suspect for asbestos and were quantified and sampled for asbestos analysis. The boiler itself is covered with a suspect packed insulation which was also sampled for analysis. The boiler breaching insulation is assumed to contain asbestos and is comingled with aircell debris throughout the boiler room. The remainder of the rooms throughout the basement have suspect sheetrock remnants on the floorboards overhead. Fiberglass-insulated pipes run throughout the basement. The outer paper jacket of the fiberglass insulation is adhered with a black mastic which is a suspect ACM. In addition to the non-suspect fiberglass insulation, aircell pipe insulation is present running throughout the basement and is suspect ACM. Pipe insulation debris was observed throughout each room in the basement. A sample of sheetrock debris leading up the stairs to the first floor was collected to delineate the extent of contamination to the basement level.

The east (Broadway) side of the building consists of two storefronts that have suspect vinyl floor tile and mastic and suspect ceramic floor tile and grout, suspect sheetrock walls and 2' x 4' drop ceiling tiles. A central hallway connects the east portion of the building with the west portion and has suspect asbestos-containing pipe insulation running above the ceiling tiles. This pipe insulation was quantified and sampled for asbestos laboratory analysis along with the other suspect materials observed in this portion of the building. The west half of the first floor that is currently used for storage, is an open area with two bathrooms and a freight elevator. The floors throughout are suspect ceramic tile (and grout) and the walls are a combination of sheetrock and plaster, both of which are considered suspect ACMs. The ceiling in this area consists of metal ceilings with suspect fireproof paneling above them nailed to the wood cross-beams. (See Figure

5 for location of this material). Suspect pipe and fitting insulation was observed in this area as well which was quantified and is detailed in Table 3 of this report.

The upper floors are accessed from a common staircase entered from the Broadway side of the building and consist of large warehouse space and deteriorated mechanical rooms and bathrooms along the south wall. There are wood floors throughout with limited areas of vinyl floor tile and mastic and leveling compound, and clay floors in the bathrooms. The walls consist of plaster and brick while the ceilings are a combination of plaster and wood. The floor tiles, mastic, leveling compound, plaster and clay flooring are all considered suspect for asbestos and were quantified and sampled for laboratory analysis. No suspect pipe and fitting insulation was observed during the survey site visit.

The roof which was, accessed from a hatch on the fourth floor, is in deteriorated condition and was observed to have a rotted wood decking beneath the roof system itself. CHA observed a suspect built-up roofing system on wood deck with flashings and suspect sealant extending up the parapet wall which is capped with 2' long coping stones grouted to each other. The layers of built-up roofing and flashing sealant, and coping stone grout were quantified separately and sampled for asbestos analysis. The windows along the exterior of Building 6 are sealed with an exterior window glazing compound which is suspect for asbestos. The glazing compound was also sampled for laboratory analysis.

3.6 FORMER MISSION BUILDING

The Former Mission Building is located along Hudson Street and was observed to be in deteriorating condition throughout. The wood subfloors on each floor are saturated with water and have evidence of significant rotting. CHA did not inspect into the chapel portion of the first floor of the Mission as the wood floor in this area was collapsed in areas and unstable. The basement consists of two main rooms, both with concrete floors, stone foundation walls and wood floorboards overhead. No suspect thermal system insulation was observed in the hot water heater room or any other area of the basement as all pipes were un-insulated.

The upper floors of the Mission typically have wood floors with suspect plaster walls and ceilings. Limited areas of suspect stucco ceiling finish and sheetrock were observed on the second and third floors and ceramic tiles and grout were observed within the bathrooms. Suspect linoleum flooring was observed in the bathrooms as well. All suspect materials were quantified by material and space and were sampled for asbestos laboratory analysis.

There are two roofs on the Former Mission Building; a high roof and low roof. Both roofs have a silvercoat type paint coating a multi-layer built-up roofing system. Roof patch material was observed at damaged locations along both roofs. The silvercoat, built-up roofing layers, and roof patch are all considered suspect for asbestos and were sampled for laboratory analysis. The windows are sealed along their exterior with a window glazing compound which is suspect for asbestos. The glazing compound was also sampled for laboratory analysis.

4.0 RESULTS

CHA identified 229 suspect asbestos-containing materials during the pre-demolition asbestos inspection of the 5 subject buildings and a total of 509 individual bulk samples were collected. Of the 229 suspect asbestos-containing materials identified, 34 asbestos-containing materials were confirmed through laboratory analysis and summarized in Table 1 below.

Table 1
Confirmed Asbestos-Containing Materials

Material	Location(s)	Estimated Quantity	Friability
Building 2			
Roofing Materials	Roof Level	6,350 sf	Non-Friable
Sink Undercoating	Kitchens Throughout	4 sinks	Non-Friable
Building 3			
Gray 12”x 12” Floor Tile and Mastic	3 rd and 4 th Floors	3,179 sf	Non-Friable
Penthouse Wall Caulk	Penthouse Roof Level	26 lf	Non-Friable
Pitch Pockets		10 ea.	
Penthouse Roofing		3,650 sf	
Building 4			
Exterior Window Caulk	First Floor Windows	192 lf	Non-Friable
Exterior Door Caulk	Broadway Entrance	24 lf	Non-Friable
Pipe Wrap	Basement	1 sf	Non-Friable
Sink Undercoating	2 nd and 4 th Floors	2 sinks	Non-Friable
Rubber Roof Seam Sealant	Roof Level	3,500 lf	Non-Friable
Building 6			
Aircell Pipe Insulation	Basement	160 lf	Friable
Pipe Insulation Debris		3,600 sf	
Mudded Fitting Insulation		37 ea	
Vinyl Floor Tiles	4 th Floor	300 sf	Non-Friable
Red Clay Flooring	2 nd and 3 rd Floors	450 sf	Non-Friable
Wall Glue	First Floor	250 sf	Non-Friable
Ceiling Insulation Board	First Floor	3000 sf	Friable
Transite Heat Shield	Boiler Room	144 sf	Non-Friable
Built-Up Roofing	Main Roof Level and Small Roof	8,685 sf	Non-Friable
Flashing Sealant on Roof	Roof Level	500 lf	Non-Friable
Flashing Sealant on Exterior Wall	South Wall	125 lf	Non-Friable
Former Mission Building			
Brown Linoleum Flooring	3 rd Floor	50 sf	Non-Friable
Roofing Materials	High and Low Roofs	3,525 sf	Non-Friable

All of the bulk samples that were collected are summarized in Table 2, which is attached to this report. Table 2 lists each bulk sample, the location from which it was collected, and also provides the analytical result for each sample. Table 2 is not intended to outline all locations within the buildings where those ACMs exist. Table 3, the Room by Room Inventory, summarizes all suspect and confirmed asbestos materials observed. For each suspect material in each room, the asbestos content is provided. If the asbestos content is greater than 1.0% asbestos by weight the material is considered an asbestos-containing material. A quantity is provided in Table 3 for each confirmed or assumed asbestos-containing material present in each area.

5.0 CONCLUSIONS AND RECOMMENDATIONS

Based upon CHA's review of the analytical results and observations made during the inspection, the following conclusions and recommendations have been developed.


- The confirmed asbestos-containing materials must be removed and legally disposed of by a licensed asbestos abatement contractor in accordance with all local, state and federal regulations prior to any demolition activities.
- Asbestos-containing pipe insulation debris was visually confirmed within all rooms of the basement of Building 6. Quantities of specific areas of visible asbestos-containing debris are provided in Table 3 of this report and are conservative estimates based on field observations and through collection of bulk debris. NYS Code Rule 56 Section 1.5 entitled "Responsibility for Cleanup of Uncontrolled Disturbance" states that "if there is an incidental disturbance or other disturbance (not as part of a controlled asbestos project) of ACM...at a building or structure, upon discovery of the disturbance, the property owner shall be responsible for contracting with a licensed asbestos abatement contractor for immediate isolation of the disturbance and cleanup in accordance with all provisions of this Part." The subject building is unoccupied and all windows and doors are locked, preventing entry into this building. Prior to entry for abatement of the contamination, a variance must be applied for from the NYSDOL to outline the owner's/contractor's plan moving forward. CHA would be happy to provide a proposal to assist with the preparation of such a variance through our certified asbestos designer,...
- Buildings 2 and 3 were occupied by office tenants during the fieldwork portion of this survey. As such, destructive investigations were not employed to inspect behind walls, within chases and beneath floors for hidden suspect ACMs and such materials may be present. Any additional suspect ACMs that are identified during the demolition must be assumed to be ACMs and handled as such unless bulk sample analysis shows that the materials are non-asbestos containing.
- Per New York State Code Rule 56-5.1(g) *Transmittal of Building/Structure Asbestos Survey Information*, information from the building survey shall be immediately transmitted by the owner or owner's representative to the local government entity charged with issuing a permit for demolition under applicable State or local laws. As this

is a demolition project, it is also the building owner's responsibility to transmit this report to the local asbestos control bureau district office.

Asbestos Control Bureau District Office
New York State Department of Labor
Division of Safety and Health
State Office Campus, Room 157
Albany, New York 12240



- This inspection report shall not solely serve as an asbestos abatement design document for obtaining bids from abatement contractors. It is recommended that specific abatement design documents be prepared in order to specify procedures and protocols that must be observed in order to insure that abatement activities are completed in a manner consistent with local, state and federal regulations and requirements.

FIGURES



SAMPLE LOCATION PLAN
FOURTH FLOOR AND ROOF LEVEL
BUILDING 2
ALBANY CONVENTION CENTER AUTHORITY
ALBANY, NEW YORK

PROJECT NO.
16433
DATE: 04/15/10
FIGURE 2



LEGEND

01A • BULK SAMPLE LOCATION

Drawing Copyright © 2008 Clough Harbour & Associates LLP




III Winners Circle, PO Box 5269 • Albany, NY 12205-0269
Main: (518) 453-4500 • www.chocompanies.com



SAMPLE LOCATION PLAN
FIRST AND SECOND FLOORS
BUILDING 3
ALBANY CONVENTION CENTER AUTHORITY
ALBANY, NEW YORK

PROJECT NO.
16433


DATE: 04/15/10

FIGURE 3





PENTHOUSE



ROOF LEVELS

LEGEND

01A

—

•

BULK SAMPLE LOCATION

Drawing Copyright © 2008 Clough Harbour & Associates LLP

III Winans Circle, PO Box 5289, Albany, NY 12205-0289
Main: (518) 453-4500 • www.cloughharbour.com

SAMPLE LOCATION PLAN

PENTHOUSE AND ROOF LEVEL

BUILDING 3


ALBANY CONVENTION CENTER AUTHORITY

ALBANY, NEW YORK


PROJECT NO.
16433

DATE: 04/15/10


FIGURE 5




BASEMENT



FIRST FLOOR



THIRD FLOOR



SECOND FLOOR

LEGEND

01A — BULK SAMPLE LOCATION

Drawing Copyright © 2008 Gough Harkour & Associates LLP



III Winners Circle, PO Box 5289, Albany, NY 12205-0289
Main: (518) 453-4500 • www.dhacorp.net/gha


SAMPLE LOCATION PLAN

BASEMENT, FIRST, SECOND AND THIRD
FLOOR – BUILDING 4
ALBANY CONVENTION CENTER AUTHORITY
ALBANY, NEW YORK


PROJECT NO.
16433

DATE: 04/15/10

FIGURE 6



FOURTH FLOOR



ROOF LEVEL

LEGEND

01A BULK SAMPLE LOCATION

Drawing Copyright © 2008 Clough Harbour & Associates LLP



III Winners Circle, PO Box 5269 • Albany, NY 12205-0269
Main: (518) 453-4500 • www.chacompanies.com


SAMPLE LOCATION PLAN

FOURTH FLOOR AND ROOF LEVEL
BUILDING 4
ALBANY CONVENTION CENTER AUTHORITY
ALBANY, NEW YORK


PROJECT NO.
16433

DATE: 04/15/10

FIGURE 7



FIRST FLOOR



BASEMENT

LEGEND

○01A● BULK SAMPLE LOCATION

Drawing Copyright © 2008 Clough Harbour & Associates LLP



111 Winslow Circle, PO Box 6288 Albany, NY 12205-0288
Phone: (518) 452-4500 • www.cloughharbour.com

SAMPLE LOCATION PLAN
BASEMENT AND FIRST FLOOR
BUILDING 6
ALBANY CONVENTION CENTER AUTHORITY
ALBANY, NEW YORK

PROJECT NO.
16433

DATE: 04/15/10

FIGURE 8



LEGEND

○10A—• BULK SAMPLE LOCATION

Drawing Copyright © 2008 Clough Harbour & Associates LLP



III Winans Circle, PO Box 6289 · Albany, NY 12205-0289
Main: (518) 453-4500 · www.chaconsultants.com

SAMPLE LOCATION PLAN
SECOND AND THIRD FLOORS
BUILDING 6
ALBANY CONVENTION CENTER AUTHORITY
ALBANY, NEW YORK

PROJECT NO.
16433

DATE: 04/15/10

FIGURE 9




LEGEND


OTA

—•

BULK SAMPLE LOCATION



ROOF LEVEL



FOURTH FLOOR

Drawing Copyright © 2008 Douglas Harbour & Associates LLP



Ill Winters Circle, PO Box 5289 · Albany, NY 12205-0289
Main: (518) 453-4500 · www.douglaspeninsula.com

SAMPLE LOCATION PLAN

FOURTH FLOOR AND ROOF LEVEL

BUILDING 6

ALBANY CONVENTION CENTER AUTHORITY

ALBANY, NEW YORK

PROJECT NO.

16433

DATE: 04/15/10

FIGURE 10

TABLES

TABLE 2
ASBESTOS CONTAINING MATERIAL SAMPLE SUMMARY
ECOMM Building 2
Albany, New York

SAMPLE NUMBER	SUSPECT MATERIAL DESCRIPTION	SAMPLE LOCATION	ASBESTOS CONTENT (%)
AS032410JM-01A	Coping Stone Grout	Roof Level	NAD
AS032410JM-01B	Coping Stone Grout	Roof Level	NAD
AS032410JM-02A	Silvercoat	Roof Level	3.7%
AS032410JM-02B	Silvercoat	Roof Level	2.3%
AS032410JM-03A	Built-Up Roofing - Bottom Layer	Roof Level	NAD
AS032410JM-03B	Built-Up Roofing - 7th Layer	Roof Level	NAD
AS032410JM-03C	Built-Up Roofing - 6th Layer	Roof Level	NAD
AS032410JM-03D	Built-Up Roofing - 5th Layer	Roof Level	NAD
AS032410JM-03E	Built-Up Roofing - 4th Layer	Roof Level	NAD
AS032410JM-03F	Built-Up Roofing - 3rd Layer	Roof Level	NAD
AS032410JM-03G	Built-Up Roofing - 2nd Layer	Roof Level	NAD
AS032410JM-03H	Built-Up Roofing - Top Layer	Roof Level	Trace
AS032410JM-04A	Black Roof Patch	Roof Level	5.3%
AS032410JM-04B	Black Roof Patch	Roof Level	3.2%
AS032410JM-05A	Roof Flashing - Tar	Roof Level	NAD
AS032410JM-05B	Roof Flashing - Tar	Roof Level	NAD
AS032410JM-06	Roof Flashing - Bottom Layer	Roof Level	9.0%
AS032410JM-07	Roof Flashing - Top Layer	Roof Level	2.9%
AS032410JM-08A	Gray Flashing Sealant	Roof Level	11.0%
AS032410JM-08B	Gray Flashing Sealant	Roof Level	11.1%
AS032410JM-09A	Pitch Pocket	Roof Level	Trace
AS032410JM-09B	Pitch Pocket	Roof Level	Trace
AS032410JM-10A	Exterior Window Glazing Compound	Exterior of Building	NAD
AS032410JM-10B	Exterior Window Glazing Compound	Exterior of Building	Trace
AS032410JM-11A	2' x 2' Ceiling Tile	3rd Floor	NAD
AS032410JM-11B	2' x 2' Ceiling Tile	3rd Floor	NAD
AS032410JM-12A	2' x 2' Ceiling Tile	4th Floor	NAD
AS032410JM-12B	2' x 2' Ceiling Tile	4th Floor	NAD
AS032410JM-13A	2' x 4' Ceiling Tile	2nd Floor	NAD
AS032410JM-13B	2' x 4' Ceiling Tile	2nd Floor	NAD
AS032410JM-14A	Sheetrock	3rd Floor	NAD
AS032410JM-14B	Sheetrock	3rd Floor	NAD
AS032410JM-15A	Sheetrock	4th Floor	NAD
AS032410JM-15B	Sheetrock	4th Floor	NAD
AS032410JM-16A	Joint Compound	3rd Floor	NAD
AS032410JM-16B	Joint Compound	3rd Floor	NAD
AS032410JM-17A	Joint Compound	4th Floor	NAD
AS032410JM-17B	Joint Compound	4th Floor	NAD
AS032410JM-18A	Tar Paper Beneath Wood Floor	4th Floor	NAD
AS032410JM-18B	Tar Paper Beneath Wood Floor	4th Floor	NAD
AS032410JM-19A	Sink Undercoating	4th Floor - Kitchen	5.6%
AS032410JM-19B	Sink Undercoating	4th Floor - Kitchen	5.5%
AS032410JM-20A	Pipe Penetration Grout	Basement	NAD
AS032410JM-20B	Pipe Penetration Grout	Basement	NAD
AS032410JM-21A	Mastic Puck	4th Floor - Elec. Closet	NAD
AS032410JM-21B	Mastic Puck	4th Floor - Elec. Closet	NAD
AS032410JM-22A	1"x 1" Gray Ceramic Tile	4th Floor - Bathroom	NAD
AS032410JM-22B	1"x 1" Gray Ceramic Tile	4th Floor - Bathroom	NAD
AS032410JM-23	Grout to Gray Ceramic Tile	4th Floor - Bathroom	NAD

TABLE 2
ASBESTOS CONTAINING MATERIAL SAMPLE SUMMARY
ECOMM Building 2
Albany, New York

SAMPLE NUMBER	SUSPECT MATERIAL DESCRIPTION	SAMPLE LOCATION	ASBESTOS CONTENT (%)
AS032410JM-24A	Leveling Compound	3rd Floor	NAD
AS032410JM-24B	Leveling Compound	3rd Floor	NAD
AS032410JM-25A	Leveling Compound	4th Floor	NAD
AS032410JM-25B	Leveling Compound	4th Floor	NAD
AS032410JM-26A	Light Gray 12"x 12" Floor Tile	4th Floor	NAD
AS032410JM-26B	Light Gray 12"x 12" Floor Tile	4th Floor	NAD
AS032410JM-27A	Dark Gray 12"x 12" Floor Tile	4th Floor	NAD
AS032410JM-27B	Dark Gray 12"x 12" Floor Tile	4th Floor	NAD
AS032410JM-28A	Gray 12"x 12" Floor Tile	4th Floor - Stairwell	NAD
AS032410JM-28B	Gray 12"x 12" Floor Tile	4th Floor - Stairwell	NAD
AS032410JM-29A	Mastic to Gray 12"x 12" Floor Tile	4th Floor - Stairwell	NAD
AS032410JM-29B	Mastic to Gray 12"x 12" Floor Tile	4th Floor - Stairwell	NAD
AS032410JM-30A	Beige 12"x 12" Floor Tile	3rd Floor	NAD
AS032410JM-30B	Beige 12"x 12" Floor Tile	3rd Floor	NAD
AS032410JM-31A	Blue Linoleum Flooring	4th Floor - Kitchen	NAD
AS032410JM-31B	Blue Linoleum Flooring	4th Floor - Kitchen	NAD
AS032410JM-32A	Mastic Beneath Linoleum	4th Floor - Kitchen	NAD
AS032410JM-32B	Mastic Beneath Linoleum	4th Floor - Kitchen	NAD
AS032410JM-33A	Blue Carpet Mastic	3rd Floor	NAD
AS032410JM-33B	Blue Carpet Mastic	3rd Floor	NAD
AS032410JM-34A	Gray Carpet Mastic	4th Floor	NAD
AS032410JM-34B	Gray Carpet Mastic	4th Floor	NAD
AS032410JM-35A	Brown Carpet Mastic	3rd Floor	NAD
AS032410JM-35B	Brown Carpet Mastic	3rd Floor	NAD
AS032410JM-36A	Light Blue Carpet Mastic	3rd Floor	NAD
AS032410JM-36B	Light Blue Carpet Mastic	3rd Floor	NAD
AS032410JM-37A	Green Carpet Mastic	3rd Floor	NAD
AS032410JM-37B	Green Carpet Mastic	3rd Floor	NAD
AS032410JM-38A	Blue Carpet Mastic	3rd Floor	NAD
AS032410JM-38B	Blue Carpet Mastic	3rd Floor	NAD
AS032410JM-39A	Tan 4" Cove Base	4th Floor	NAD
AS032410JM-39B	Tan 4" Cove Base	4th Floor	NAD
AS032410JM-40A	Mastic to Tan 4" Cove Base	4th Floor	NAD
AS032410JM-40B	Mastic to Tan 4" Cove Base	4th Floor	NAD
AS032410JM-41A	Blue 4" Cove Base	3rd Floor	NAD
AS032410JM-41B	Blue 4" Cove Base	3rd Floor	NAD
AS032410JM-42A	Mastic to Blue 4" Cove Base	3rd Floor	NAD
AS032410JM-42B	Mastic to Blue 4" Cove Base	3rd Floor	NAD
AS032410JM-43A	Green 4" Cove Base	3rd Floor	NAD
AS032410JM-43B	Green 4" Cove Base	3rd Floor	NAD
AS032410JM-44A	Mastic to Green 4" Cove Base	3rd Floor	NAD
AS032410JM-44B	Mastic to Green 4" Cove Base	3rd Floor	NAD
AS032410JM-45A	Tan 4" Cove Base	3rd Floor - Kitchen	NAD
AS032410JM-45B	Tan 4" Cove Base	3rd Floor - Kitchen	NAD
AS032410JM-46A	Mastic to Tan 4" Cove Base	3rd Floor - Kitchen	NAD
AS032410JM-46B	Mastic to Tan 4" Cove Base	3rd Floor - Kitchen	NAD
AS032410JM-47A	4" Brown Cove Base	3rd Floor	NAD
AS032410JM-47B	4" Brown Cove Base	3rd Floor	NAD
AS032410JM-48A	Mastic to Brown 4" Cove Base	3rd Floor	NAD

TABLE 2
ASBESTOS CONTAINING MATERIAL SAMPLE SUMMARY
ECOMM Building 2
Albany, New York

SAMPLE NUMBER	SUSPECT MATERIAL DESCRIPTION	SAMPLE LOCATION	ASBESTOS CONTENT (%)
AS032410JM-48B	Mastic to Brown 4" Cove Base	3rd Floor	NAD
AS032410JM-49A	4" Black Cove Base	3rd Floor	NAD
AS032410JM-49B	4" Black Cove Base	3rd Floor	NAD
AS032410JM-50A	Mastic to 4" Black Cove Base	3rd Floor	NAD
AS032410JM-50B	Mastic to 4" Black Cove Base	3rd Floor	NAD
NAD = No Asbestos Detected			
NVA = No Visible Fiber			
NA / PS = Not Analyzed / Positive Stop			

TABLE 2
ASBESTOS CONTAINING MATERIAL SAMPLE SUMMARY
ECOMM Building 3
Albany, New York

SAMPLE NUMBER	SUSPECT MATERIAL DESCRIPTION	SAMPLE LOCATION	ASBESTOS CONTENT (%)
AS032610JM-01A	Sheetrock	Penthouse	NAD
AS032610JM-01B	Sheetrock	Penthouse	NAD
AS032610JM-01C	Sheetrock	1st Floor - Behind PM's Office	NAD
AS032610JM-01D	Sheetrock	1st Floor - Behind PM's Office	NAD
AS032610JM-01E	Sheetrock	2nd Floor Mechanical Room	NAD
AS032610JM-01F	Sheetrock	2nd Floor Mechanical Room	NAD
AS032610JM-02A	Joint Compound	Penthouse	NAD
AS032610JM-02B	Joint Compound	Penthouse	NAD
AS032610JM-02C	Joint Compound	1st Floor - Behind PM's Office	NAD
AS032610JM-02D	Joint Compound	1st Floor - Behind PM's Office	NAD
AS032610JM-02E	Joint Compound	2nd Floor Mechanical Room	NAD
AS032610JM-02F	Joint Compound	2nd Floor Mechanical Room	NAD
AS032610JM-03A	Sheetrock Tape	2nd Floor Mechanical Room	NAD
AS032610JM-03B	Sheetrock Tape	1st Floor - Behind PM's Office	NAD
AS032610JM-04A	Sink Undercoating	4th Floor Kitchen	NAD
AS032610JM-04B	Sink Undercoating	4th Floor Kitchen	NAD
AS032610JM-05A	Fiberboard	Penthouse	NAD
AS032610JM-05B	Fiberboard	Penthouse	NAD
AS032610JM-06A	2' x 2' Ceiling Tile	3rd Floor	NAD
AS032610JM-06B	2' x 2' Ceiling Tile	3rd Floor	NAD
AS032610JM-07A	Textured Wall Paint	Penthouse	NAD
AS032610JM-07B	Textured Wall Paint	Penthouse	NAD
AS032610JM-07C	Textured Wall Paint	Penthouse	NAD
AS032610JM-07D	Textured Wall Paint	Penthouse	NAD
AS032610JM-07E	Textured Wall Paint	Penthouse	NAD
AS032610JM-08	1' x 1' Ceramic Floor Tile	First Floor - Vestibule	NAD
AS032610JM-09	Grout to 1' x 1' Ceramic Floor Tile	First Floor - Vestibule	NAD
AS032610JM-10A	Grout at Penetration	First Floor - Elect. Room	NAD
AS032610JM-10B	Grout at Penetration	First Floor - Elect. Room	NAD
AS032610JM-11A	2"x 2" Gray Ceramic Floor Tile	Bathroom	NAD
AS032610JM-11B	2"x 2" Gray Ceramic Floor Tile	Bathroom	NAD
AS032610JM-12A	Grout to 2"x 2" Ceramic Tile	Bathroom	NAD
AS032610JM-12B	Grout to 2"x 2" Ceramic Tile	Bathroom	NAD
AS032610JM-13A	Marble Floor Grout	Penthouse	NAD
AS032610JM-13B	Marble Floor Grout	Penthouse	NAD
AS032610JM-14A	Leveling Compound	3rd Floor - Storage Room	NAD
AS032610JM-14B	Leveling Compound	3rd Floor - Storage Room	NAD
AS032610JM-15A	White Linoleum	1st Floor - Bathroom	NAD
AS032610JM-15B	White Linoleum	1st Floor - Bathroom	NAD
AS032610JM-16A	Tan Linoleum	First Floor - Group Therapy	NAD
AS032610JM-16B	Tan Linoleum	First Floor - Group Therapy	NAD
AS032610JM-17A	Light Tan Linoleum	1st Floor - Wellcare	NAD
AS032610JM-17B	Light Tan Linoleum	1st Floor - Wellcare	NAD
AS032610JM-18A	Maroon Carpet Mastic	4th Floor	NAD
AS032610JM-18B	Maroon Carpet Mastic	4th Floor	NAD
AS032610JM-19A	Blue Carpet Mastic	Penthouse	NAD
AS032610JM-19B	Blue Carpet Mastic	Penthouse	NAD
AS032610JM-20A	Maroon Carpet	3rd Floor	NAD
AS032610JM-20B	Maroon Carpet	3rd Floor	NAD

TABLE 2
ASBESTOS CONTAINING MATERIAL SAMPLE SUMMARY
ECOMM Building 3
Albany, New York

SAMPLE NUMBER	SUSPECT MATERIAL DESCRIPTION	SAMPLE LOCATION	ASBESTOS CONTENT (%)
AS032610JM-21A	Gray Carpet Mastic	3rd Floor	NAD
AS032610JM-21B	Gray Carpet Mastic	3rd Floor	NAD
AS032610JM-22A	Black Carpet Mastic	3rd Floor	NAD
AS032610JM-22B	Black Carpet Mastic	3rd Floor	NAD
AS032610JM-23A	Green Carpet Mastic	1st Floor	NAD
AS032610JM-23B	Green Carpet Mastic	1st Floor	NAD
AS032610JM-24A	Brown (box-patterned) Carpet Mastic	1st Floor	NAD
AS032610JM-24B	Brown (box-patterned) Carpet Mastic	1st Floor	NAD
AS032610JM-25A	Tan Carpet Mastic	1st Floor	NAD
AS032610JM-25B	Tan Carpet Mastic	1st Floor	NAD
AS032610JM-26A	White 12"x 12" Floor Tile	4th Floor	NAD
AS032610JM-26B	White 12"x 12" Floor Tile	4th Floor	NAD
AS032610JM-27A	Gray 12"x 12" Floor Tile	4th Floor	1.5%
AS032610JM-27B	Gray 12"x 12" Floor Tile	4th Floor	NA/PS
AS032610JM-28A	Mastic to White and Gray Floor Tiles	4th Floor	3.5%
AS032610JM-28B	Mastic to White and Gray Floor Tiles	4th Floor	NA/PS
AS032610JM-29A	Beige 12"x 12" Floor Tile - No Mastic	1st Floor	NAD
AS032610JM-29B	Beige 12"x 12" Floor Tile - No Mastic	1st Floor	NAD
AS032610JM-30A	Blue 12"x 12" Floor Tile	3rd Floor	NAD
AS032610JM-30B	Blue 12"x 12" Floor Tile	3rd Floor	NAD
AS032610JM-31A	White 12"x 12" Floor Tile	3rd Floor	NAD
AS032610JM-31B	White 12"x 12" Floor Tile	3rd Floor	NAD
AS032610JM-32	Mastic to Blue and White Floor Tiles	3rd Floor	NAD
AS032610JM-33A	Light Blue 12"x 12" Floor Tile	3rd Floor	NAD
AS032610JM-33B	Light Blue 12"x 12" Floor Tile	3rd Floor	NAD
AS032610JM-34A	Off-White 12"x 12" Floor Tile	1st Floor	NAD
AS032610JM-34B	Off-White 12"x 12" Floor Tile	1st Floor	NAD
AS032610JM-35	Mastic to Off-White 12"x 12" Floor Tile	1st Floor	NAD
AS032610JM-36A	4" Brown Cove Base	1st Floor	NAD
AS032610JM-36B	4" Brown Cove Base	1st Floor	NAD
AS032610JM-37A	Mastic to 4" Brown Cove Base	1st Floor	NAD
AS032610JM-37B	Mastic to 4" Brown Cove Base	1st Floor	NAD
AS032610JM-38	Carpet Mastic	1st Floor	NAD
AS032610JM-39A	4" Black Cove Base	Penthouse	NAD
AS032610JM-39B	4" Black Cove Base	Penthouse	NAD
AS032610JM-40A	Mastic to Black Cove Base	Penthouse	NAD
AS032610JM-40B	Mastic to Black Cove Base	Penthouse	NAD
AS032610JM-41A	4" Blue Cove Base	4th Floor	NAD
AS032610JM-41B	4" Blue Cove Base	4th Floor	NAD
AS032610JM-42A	Mastic to Blue Cove Base	4th Floor	NAD
AS032610JM-42B	Mastic to Blue Cove Base	4th Floor	NAD
AS032610JM-43A	3" White Cove Base	3rd Floor	NAD
AS032610JM-43B	3" White Cove Base	3rd Floor	NAD
AS032610JM-44A	Mastic to 3" White Cove Base	3rd Floor	NAD
AS032610JM-44B	Mastic to 3" White Cove Base	3rd Floor	NAD
AS032610JM-45A	4" Green Cove Base	1st Floor Corridor	NAD
AS032610JM-45B	4" Green Cove Base	1st Floor Corridor	NAD
AS032610JM-46A	Mastic to 4" Green Cove Base	1st Floor Corridor	NAD
AS032610JM-46B	Mastic to 4" Green Cove Base	1st Floor Corridor	NAD

TABLE 2
ASBESTOS CONTAINING MATERIAL SAMPLE SUMMARY
ECOMM Building 3
Albany, New York

SAMPLE NUMBER	SUSPECT MATERIAL DESCRIPTION	SAMPLE LOCATION	ASBESTOS CONTENT (%)
AS032610JM-47A	Dark Blue 4" Cove Base	1st Floor	NAD
AS032610JM-47B	Dark Blue 4" Cove Base	1st Floor	NAD
AS032610JM-48A	Mastic to Dark Blue 4" Cove Base	1st Floor	NAD
AS032610JM-48B	Mastic to Dark Blue 4" Cove Base	1st Floor	NAD
AS032610JM-49A	4" Tan Cove Base	1st Floor - AHU Room	NAD
AS032610JM-49B	4" Tan Cove Base	1st Floor - AHU Room	NAD
AS032610JM-50	Mastic to 4" Tan Cove Base	1st Floor - AHU Room	NAD
AS032610JM-51A	4" Tan Cove Base	2nd Floor Kitchen	NAD
AS032610JM-51B	4" Tan Cove Base	2nd Floor Kitchen	NAD
AS032610JM-52A	Mastic to 4" Tan Cove Base	2nd Floor Kitchen	NAD
AS032610JM-52B	Mastic to 4" Tan Cove Base	2nd Floor Kitchen	NAD
AS032610JM-53A	Exterior Window Glazing Compound	Exterior - Penthouse Elevation	NAD
AS032610JM-53B	Exterior Window Glazing Compound	Exterior - Penthouse Elevation	NAD
AS032610JM-54A	Penthouse Wall Caulk	Penthouse Roof	4.7%
AS032610JM-54B	Penthouse Wall Caulk	Penthouse Roof	5.7%
AS032610JM-55A	Seam Sealant	Roof #1	NAD
AS032610JM-55B	Seam Sealant	Roof #1	NAD
AS032610JM-56A	Pitch Pocket	Roof #1	3.0%
AS032610JM-56B	Pitch Pocket	Roof #1	NA/PS
AS032610JM-57A	Built-Up Roofing - Bottom Layer	Roof #1	Trace
AS032610JM-57B	Built-Up Roofing - 3rd Layer	Roof #1	NAD
AS032610JM-57C	Built-Up Roofing - 2nd Layer	Roof #1	NAD
AS032610JM-57D	Built-Up Roofing - Top Layer	Roof #1	Trace
AS032610JM-58A	Built-Up Roofing - Bottom Layer	Roof #2	Trace
AS032610JM-58B	Built-Up Roofing - Middle Layer	Roof #2	NAD
AS032610JM-58C	Built-Up Roofing - Bottom Layer	Roof #2	NAD
AS032610JM-59A	Built-Up Roofing - Flashing - Bottom Layer	Roof #1	Trace
AS032610JM-59B	Built-Up Roofing - Flashing - Top Layer	Roof #1	Trace
AS032610JM-60A	Built-Up Roofing - Bottom Layer	Penthouse Roof	Trace
AS032610JM-60B	Built-Up Roofing - Top Layer	Penthouse Roof	7.4%
AS032610JM-61A	Built-Up Roofing - Middle Layer	Penthouse Roof	NA/PS
AS032610JM-61B	Built-Up Roofing - Bottom Layer	Penthouse Roof	NA/PS
AS032610JM-61C	Built-Up Roofing - Top Layer	Penthouse Roof	NA/PS
AS032610JM-62	Built-Up Roofing	Small Roof on Penthouse Roof	Trace
AS032610JM-63	Roof Patch Area - Rolled Roofing	Penthouse Roof	NAD
AS032610JM-64	Flashing Sealant	Penthouse Roof	1.9%
NAD = No Asbestos Detected			
NA / PS = Not Analyzed / Positive Stop			

TABLE 2
ASBESTOS CONTAINING MATERIAL SAMPLE SUMMARY
ECOMM Building 4
Albany, New York

SAMPLE NUMBER	SUSPECT MATERIAL DESCRIPTION	SAMPLE LOCATION	ASBESTOS CONTENT (%)
AS031810JM-01A	Patch on Exterior Wall	Exterior of Building	NAD
AS031810JM-01B	Patch on Exterior Wall	Exterior of Building	NAD
AS031810JM-01C	Patch on Exterior Wall	Exterior of Building	NAD
AS031810JM-02A	Exterior Window Caulk	Exterior of Building	3.8%
AS031810JM-02B	Exterior Window Caulk	Exterior of Building	4.8%
AS031810JM-03A	Exterior Door Caulk	Exterior of Building	4.2%
AS031810JM-03B	Exterior Door Caulk	Exterior of Building	4.2%
AS031810JM-04A	Sheetrock	Kitchen	NAD
AS031810JM-04B	Sheetrock	Kitchen	NAD
AS031810JM-05A	Joint Compound	Kitchen	NAD
AS031810JM-05B	Joint Compound	Kitchen	NAD
AS031810JM-06A	Laminant Wall Panel	Electrical Closet	Trace
AS031810JM-06B	Laminant Wall Panel	Electrical Closet	NAD
AS031810JM-07A	Mastic to Laminant Wall Panel	Electrical Closet	NAD
AS031810JM-07B	Mastic to Laminant Wall Panel	Electrical Closet	NAD
AS031810JM-08A	Fiberglass Paper	Basement	NAD
AS031810JM-08B	Fiberglass Paper	Basement	NAD
AS031810JM-09A	Pipe Wrap (white)	Basement	4.4%
AS031810JM-09B	Pipe Wrap (white)	Basement	4.9%
AS031810JM-09C	Pipe Wrap (white)	Basement	5.1%
AS031810JM-10A	Sink Undercoating	2nd Floor	5.3%
AS031810JM-10B	Sink Undercoating	2nd Floor	4.8%
AS031810JM-11A	Paper Above Wood Ceiling	1st Floor Kitchen	NAD
AS031810JM-11B	Paper Above Wood Ceiling	1st Floor Kitchen	NAD
AS031810JM-12A	12"x 12" Marble-Style Linoleum	First Floor	NAD
AS031810JM-12B	12"x 12" Marble-Style Linoleum	First Floor	NAD
AS031810JM-13A	12"x 12" Black Floor Tile	Dining Room	NAD
AS031810JM-13B	12"x 12" Black Floor Tile	Dining Room	NAD
AS031810JM-14A	12"x 12" Beige Floor Tile	Dining Room	NAD
AS031810JM-14B	12"x 12" Beige Floor Tile	Dining Room	NAD
AS031810JM-15A	Mastic to Beige and Black Floor Tile	Dining Room	NAD
AS031810JM-15B	Mastic to Beige and Black Floor Tile	Dining Room	NAD
AS031810JM-16A	Linoleum Flooring	4th Floor - Kitchen	NAD
AS031810JM-16B	Linoleum Flooring	4th Floor - Kitchen	NAD
AS031810JM-17A	Floor Leveling Compound	First Floor	NAD
AS031810JM-17B	Floor Leveling Compound	First Floor	NAD
AS031810JM-18A	Gray Carpet Mastic	2nd Floor	NAD
AS031810JM-18B	Gray Carpet Mastic	2nd Floor	NAD
AS031810JM-19A	Green Tile Carpet Mastic	4th Floor	NAD
AS031810JM-19B	Green Tile Carpet Mastic	4th Floor	NAD
AS031810JM-20A	Green / Beige Carpet Mastic	4th Floor	NAD
AS031810JM-20B	Green / Beige Carpet Mastic	4th Floor	NAD
AS031810JM-21A	Green Carpet Mastic	4th Floor	NAD
AS031810JM-21B	Green Carpet Mastic	4th Floor	NAD
AS031810JM-22A	Blue Carpet Mastic	2nd Floor	NAD
AS031810JM-22B	Blue Carpet Mastic	2nd Floor	NAD
AS031810JM-23A	Purple Carpet Mastic	3rd Floor	NAD
AS031810JM-23B	Purple Carpet Mastic	3rd Floor	NAD
AS031810JM-24A	12"x 12" Ceramic Tile - Beige	1st Floor	NAD

TABLE 2
ASBESTOS CONTAINING MATERIAL SAMPLE SUMMARY
ECOMM Building 4
Albany, New York

SAMPLE NUMBER	SUSPECT MATERIAL DESCRIPTION	SAMPLE LOCATION	ASBESTOS CONTENT (%)
AS031810JM-24B	12"x 12" Ceramic Tile - Beige	1st Floor	NAD
AS031810JM-25A	Grout to 12"x 12" Ceramic Tile	1st Floor	NAD
AS031810JM-25B	Grout to 12"x 12" Ceramic Tile	1st Floor	NAD
AS031810JM-26A	Clay Floor Tile	1st Floor - Kitchen	NAD
AS031810JM-26B	Clay Floor Tile	1st Floor - Kitchen	NAD
AS031810JM-27A	Grout to Clay Floor Tile	1st Floor - Kitchen	NAD
AS031810JM-27B	Grout to Clay Floor Tile	1st Floor - Kitchen	NAD
AS031810JM-28A	4" White Ceramic Wall Tile	1st Floor - Kitchen	NAD
AS031810JM-28B	4" White Ceramic Wall Tile	1st Floor - Kitchen	NAD
AS031810JM-29A	Grout to 4" White Ceramic Wall Tile	1st Floor - Kitchen	NAD
AS031810JM-29B	Grout to 4" White Ceramic Wall Tile	1st Floor - Kitchen	NAD
AS031810JM-30A	Mastic to 4" White Ceramic Wall Tile	1st Floor - Kitchen	NAD
AS031810JM-30B	Mastic to 4" White Ceramic Wall Tile	1st Floor - Kitchen	NAD
AS031810JM-31A	1'x 1' Black Ceramic Tile	1st Floor	NAD
AS031810JM-31B	1'x 1' Black Ceramic Tile	1st Floor	NAD
AS031810JM-32A	Grout to 1'x 1' Black Ceramic Tile	1st Floor	NAD
AS031810JM-32B	Grout to 1'x 1' Black Ceramic Tile	1st Floor	NAD
AS031810JM-33A	1"x 1" Black Ceramic Tile	1st Floor Bathroom	NAD
AS031810JM-33B	1"x 1" Black Ceramic Tile	1st Floor Bathroom	NAD
AS031810JM-34A	Grout to 1"x 1" Black Ceramic Tile	1st Floor Bathroom	NAD
AS031810JM-34B	Grout to 1"x 1" Black Ceramic Tile	1st Floor Bathroom	NAD
AS031810JM-35A	Tan (glazed) Clay Tile	4th Floor	NAD
AS031810JM-35B	Tan (glazed) Clay Tile	4th Floor	NAD
AS031810JM-36A	Grout to Clay Floor Tile	4th Floor	NAD
AS031810JM-36B	Grout to Clay Floor Tile	4th Floor	NAD
AS031810JM-37A	Mortar to Clay Tile	4th Floor	NAD
AS031810JM-37B	Mortar to Clay Tile	4th Floor	NAD
AS031810JM-38A	Fiberglass Paper	1st Floor Wall Opening	NAD
AS031810JM-38B	Fiberglass Paper	1st Floor Wall Opening	NAD
AS031810JM-39	Roof Field Fiberboard	Roof Level	NAD
AS031810JM-40A	Pitch Pocket	Roof Level	NAD
AS031810JM-40B	Pitch Pocket	Roof Level	NAD
AS031810JM-41A	Flashing Caulk	Roof Level	NAD
AS031810JM-41B	Flashing Caulk	Roof Level	NAD
AS031810JM-42A	Gray Sealant	Roof Level	NAD
AS031810JM-42B	Gray Sealant	Roof Level	NAD
AS031810JM-43A	Rubber Roof Seam Sealant	Roof Level	2.1%
AS031810JM-43B	Rubber Roof Seam Sealant	Roof Level	1.7%
NAD = No Asbestos Detected			
NA / PS = Not Analyzed / Positive Stop			

TABLE 2
ASBESTOS CONTAINING MATERIAL SAMPLE SUMMARY
Former Mission Building
Albany, New York

SAMPLE NUMBER	SUSPECT MATERIAL DESCRIPTION	SAMPLE LOCATION	ASBESTOS CONTENT (%)
AS032210JM-01A	Textured Ceiling Paint	2nd Floor	NAD
AS032210JM-01B	Textured Ceiling Paint	2nd Floor	NAD
AS032210JM-01C	Textured Ceiling Paint	2nd Floor	NAD
AS032210JM-02A	Ceiling Plaster - Skimcoat	2nd Floor	NAD
AS032210JM-02B	Ceiling Plaster - Skimcoat	2nd Floor	NAD
AS032210JM-02C	Ceiling Plaster - Skimcoat	2nd Floor	NAD
AS032210JM-02D	Ceiling Plaster - Skimcoat	3rd Floor	NAD
AS032210JM-02E	Ceiling Plaster - Skimcoat	3rd Floor	NAD
AS032210JM-03A	Ceiling Plaster - Subcoat	2nd Floor	NAD
AS032210JM-03B	Ceiling Plaster - Subcoat	2nd Floor	NAD
AS032210JM-03C	Ceiling Plaster - Subcoat	2nd Floor	NAD
AS032210JM-03D	Ceiling Plaster - Subcoat	3rd Floor	NAD
AS032210JM-03E	Ceiling Plaster - Subcoat	3rd Floor	NAD
AS032210JM-04A	Wall Plaster - Skimcoat	2nd Floor	NAD
AS032210JM-04B	Wall Plaster - Skimcoat	2nd Floor	NAD
AS032210JM-04C	Wall Plaster - Skimcoat	2nd Floor	NAD
AS032210JM-04D	Wall Plaster - Skimcoat	3rd Floor	NAD
AS032210JM-04E	Wall Plaster - Skimcoat	3rd Floor	NAD
AS032210JM-04F	Wall Plaster - Skimcoat	3rd Floor	NAD
AS032210JM-04G	Wall Plaster - Skimcoat	3rd Floor	NAD
AS032210JM-05A	Wall Plaster - Subcoat	2nd Floor	NAD
AS032210JM-05B	Wall Plaster - Subcoat	2nd Floor	NAD
AS032210JM-05C	Wall Plaster - Subcoat	2nd Floor	NAD
AS032210JM-05D	Wall Plaster - Subcoat	3rd Floor	NAD
AS032210JM-05E	Wall Plaster - Subcoat	3rd Floor	NAD
AS032210JM-05F	Wall Plaster - Subcoat	3rd Floor	NAD
AS032210JM-05G	Wall Plaster - Subcoat	3rd Floor	NAD
AS032210JM-06A	Sheetrock	1st Floor	NAD
AS032210JM-06B	Sheetrock	1st Floor	NAD
AS032210JM-07A	Joint Compound	1st Floor	NAD
AS032210JM-07B	Joint Compound	1st Floor	NAD
AS032210JM-08A	2' x 2' Ceiling Tile	3rd Floor Bathroom	NAD
AS032210JM-08B	2' x 2' Ceiling Tile	3rd Floor Bathroom	NAD
AS032210JM-09A	Clay Floor Tile	1st Floor - Kitchen	NAD
AS032210JM-09B	Clay Floor Tile	1st Floor - Kitchen	NAD
AS032210JM-10A	Grout to Clay Floor Tile	1st Floor - Kitchen	NAD
AS032210JM-10B	Grout to Clay Floor Tile	1st Floor - Kitchen	NAD
AS032210JM-11A	White Ceramic Floor Tile	2nd Floor - Bathroom	NAD
AS032210JM-11B	White Ceramic Floor Tile	2nd Floor - Bathroom	NAD
AS032210JM-12A	Grout to White Ceramic Floor Tile	2nd Floor - Bathroom	NAD
AS032210JM-12B	Grout to White Ceramic Floor Tile	2nd Floor - Bathroom	NAD
AS032210JM-13A	Black Ceramic Floor Tile	3rd Floor - Bathroom	NAD
AS032210JM-13B	Black Ceramic Floor Tile	3rd Floor - Bathroom	NAD
AS032210JM-14A	Grout to Black Ceramic Floor Tile	3rd Floor - Bathroom	NAD
AS032210JM-14B	Grout to Black Ceramic Floor Tile	3rd Floor - Bathroom	NAD
AS032210JM-15A	Clay Floor Tile	3rd Floor - Bathroom	NAD
AS032210JM-15B	Clay Floor Tile	3rd Floor - Bathroom	NAD
AS032210JM-16A	Grout to Clay Floor Tile	3rd Floor - Bathroom	NAD
AS032210JM-16B	Grout to Clay Floor Tile	3rd Floor - Bathroom	NAD

TABLE 2
ASBESTOS CONTAINING MATERIAL SAMPLE SUMMARY
Former Mission Building
Albany, New York

SAMPLE NUMBER	SUSPECT MATERIAL DESCRIPTION	SAMPLE LOCATION	ASBESTOS CONTENT (%)
AS032210JM-17A	Sheetrock Tape	First Floor	NAD
AS032210JM-17B	Sheetrock Tape	Third Floor	NAD
AS032210JM-18A	Wall Panel Glue	First Floor	NAD
AS032210JM-18B	Wall Panel Glue	First Floor	NAD
AS032210JM-19A	Laminant Countertop	First Floor - Check In	NAD
AS032210JM-19B	Laminant Countertop	First Floor - Check In	NAD
AS032210JM-20A	12"x 12" Textured Floor Tile	First Floor - Check In	NAD
AS032210JM-20B	12"x 12" Textured Floor Tile	First Floor - Check In	NAD
AS032210JM-21A	Beige 12"x 12" Floor Tile	First Floor - Check In	NAD
AS032210JM-21A	Mastic to Beige 12"x 12" Floor Tile (split at lab)	First Floor - Check In	Trace
AS032210JM-21B	Beige 12"x 12" Floor Tile	First Floor - Check In	NAD
AS032210JM-21B	Mastic to Beige 12"x 12" Floor Tile (split at lab)	First Floor - Check In	Trace
AS032210JM-22A	White 12"x 12" Floor Tile	First Floor - Check In	NAD
AS032210JM-22A	Mastic to White 12"x 12" Floor Tile (split at lab)	First Floor - Check In	Trace
AS032210JM-22B	White 12"x 12" Floor Tile	First Floor - Check In	NAD
AS032210JM-22B	Mastic to White 12"x 12" Floor Tile (split at lab)	First Floor - Check In	Trace
AS032210JM-23A	Gray 12"x 12" Floor Tile	2nd Floor	NAD
AS032210JM-23B	Gray 12"x 12" Floor Tile	2nd Floor	NAD
AS032210JM-24A	Streaked 12"x 12" Floor Tile	2nd Floor	NAD
AS032210JM-24B	Streaked 12"x 12" Floor Tile	2nd Floor	NAD
AS032210JM-25A	Brown Linoleum Flooring	Bathroom	10.0%
AS032210JM-25B	Brown Linoleum Flooring	Bathroom	8.4%
AS032210JM-26A	Gray Linoleum Flooring	2nd Floor Bathroom	NAD
AS032210JM-26B	Gray Linoleum Flooring	2nd Floor Bathroom	NAD
AS032210JM-27A	Beige Linoleum Floor	2nd Floor Bathroom	NAD
AS032210JM-27B	Beige Linoleum Floor	2nd Floor Bathroom	NAD
AS032210JM-28A	Exterior Window Glazing Compound	Exterior of Building	NAD
AS032210JM-28B	Exterior Window Glazing Compound	Exterior of Building	NAD
AS032210JM-29A	Stucco Finish	Exterior of Building	NAD
AS032210JM-29B	Stucco Finish	Exterior of Building	NAD
AS032210JM-29C	Stucco Finish	Exterior of Building	NAD
AS032210JM-29D	Stucco Finish	Exterior of Building	NAD
AS032210JM-29E	Stucco Finish	Exterior of Building	NAD
AS032210JM-30A	Built-Up Roofing	High Roof	8.6%
AS032210JM-30B	Built-Up Roofing	Low Roof	5.2%
AS032210JM-31A	Roof Tar	Low Roof	1.9%
AS032210JM-31B	Roof Tar	Low Roof	3.1%
AS032210JM-32A	Silvercoat	Low Roof	8.2%
AS032210JM-32B	Silvercoat	Low Roof	3.0%

NAD = No Asbestos Detected

NA / PS = Not Analyzed / Positive Stop

TABLE 2
ASBESTOS CONTAINING MATERIAL SAMPLE SUMMARY
ECOMM Building 6
Albany, New York

SAMPLE NUMBER	SUSPECT MATERIAL DESCRIPTION	SAMPLE LOCATION	ASBESTOS CONTENT (%)
AS031810JM-01A	Aircell Pipe Insulation	First Floor	44.4%
AS031810JM-01B	Aircell Pipe Insulation	First Floor	NA/PS
AS031810JM-01C	Aircell Pipe Insulation	First Floor	NA/PS
AS031810JM-02A	Mudded Fitting Insulation	First Floor	18.2%
AS031810JM-02B	Mudded Fitting Insulation	First Floor	22.2%
AS031810JM-02C	Mudded Fitting Insulation	First Floor	20.0%
AS031810JM-03A	Fiberglass Insulation Paper	First Floor	NAD
AS031810JM-03B	Fiberglass Insulation Paper	First Floor	NAD
AS031810JM-04A	Exterior Window Glazing Compound	Exterior Of Building	Trace
AS031810JM-04B	Exterior Window Glazing Compound	Exterior Of Building	NAD
AS031810JM-05A	Floor Leveling Compound	4th Floor	NAD
AS031810JM-05B	Floor Leveling Compound	4th Floor	NAD
AS031810JM-06A	Green Linoleum Flooring	Stair Landing	NAD
AS031810JM-06B	Green Linoleum Flooring	Stair Landing	NAD
AS031810JM-07A	White 12"x 12" Floor Tile	4th Floor	4.9%
AS031810JM-07B	White 12"x 12" Floor Tile	4th Floor	7.2%
AS031810JM-08A	Beige 12"x 12" Floor Tile	4th Floor	5.9%
AS031810JM-08B	Beige 12"x 12" Floor Tile	4th Floor	4.7%
AS031810JM-09A	Underlayment Beneath Beige 12"x 12" Floor Tile	4th Floor	3.8%
AS031810JM-09B	Underlayment Beneath Beige 12"x 12" Floor Tile	4th Floor	2.9%
AS031810JM-10A	Floor Paper	3rd Floor	NAD
AS031810JM-10B	Floor Paper	3rd Floor	NAD
AS031810JM-11A	Gray 12"x 12" Floor Tile	4th Floor	7.8%
AS031810JM-11B	Gray 12"x 12" Floor Tile	4th Floor	5.4%
AS031810JM-12A	Green 12"x 12" Floor Tile	4th Floor	10.5%
AS031810JM-12B	Green 12"x 12" Floor Tile	4th Floor	11.4%
AS031810JM-13A	4" Gray Cove Base	1st Floor	NAD
AS031810JM-13B	4" Gray Cove Base	1st Floor	NAD
AS031810JM-14A	Mastic to 4" Gray Cove Base	1st Floor	NAD
AS031810JM-14B	Mastic to 4" Gray Cove Base	1st Floor	NAD
AS031810JM-15A	4" Brown Cove Base	1st Floor	NAD
AS031810JM-15B	4" Brown Cove Base	1st Floor	NAD
AS031810JM-16A	Mastic to 4" Brown Cove Base	1st Floor	NAD
AS031810JM-16B	Mastic to 4" Brown Cove Base	1st Floor	NAD
AS031810JM-17A	Tan Clay Tile	1st Floor	NAD
AS031810JM-17B	Brown Clay Tile	1st Floor	NAD
AS031810JM-18A	Grout to Clay Tiles	1st Floor	NAD
AS031810JM-18B	Grout to Clay Tiles	1st Floor	NAD
AS031810JM-19A	Red Clay Flooring	2nd Floor	1.3%
AS031810JM-19B	Red Clay Flooring	2nd Floor	1.5%
AS031810JM-20A	Brown Ceramic Tile	1st Floor	NAD
AS031810JM-20B	Brown Ceramic Tile	1st Floor	NAD
AS031810JM-21A	Grout to Brown Ceramic Tile	1st Floor	NAD
AS031810JM-21B	Grout to Brown Ceramic Tile	1st Floor	NAD
AS031810JM-22A	1' x 1' Ceiling Tile	2nd Floor	NAD
AS031810JM-22B	1' x 1' Ceiling Tile	2nd Floor	NAD
AS031810JM-23A	Wall Glue	1st Floor	2.8%
AS031810JM-23B	Wall Glue	1st Floor	3.0%

TABLE 2
ASBESTOS CONTAINING MATERIAL SAMPLE SUMMARY
ECOMM Building 6
Albany, New York

SAMPLE NUMBER	SUSPECT MATERIAL DESCRIPTION	SAMPLE LOCATION	ASBESTOS CONTENT (%)
AS031810JM-24A	Ceiling Insulation Board	Storage Area	66.7%
AS031810JM-24B	Ceiling Insulation Board	Storage Area	66.7%
AS031810JM-25A	Sheetrock	1st Floor	NAD
AS031810JM-25B	Sheetrock	1st Floor	NAD
AS031810JM-26A	Joint Compound	1st Floor	NAD
AS031810JM-26B	Joint Compound	1st Floor	NAD
AS031810JM-27A	Ceiling Plaster	First Floor - Bathroom	NAD
AS031810JM-27B	Ceiling Plaster	First Floor - Bathroom	NAD
AS031810JM-27C	Ceiling Plaster	First Floor - Bathroom	NAD
AS031810JM-27D	Ceiling Plaster	First Floor - Bathroom	NAD
AS031810JM-27E	Ceiling Plaster	First Floor - Bathroom	NAD
AS031810JM-28A	Wall Plaster	First Floor - Bathroom	0.3%
AS031810JM-28B	Wall Plaster	First Floor - Bathroom	Trace
AS031810JM-28C	Wall Plaster	First Floor - Bathroom	0.3%
AS031810JM-28D	Wall Plaster	First Floor - Bathroom	0.3%
AS031810JM-28E	Wall Plaster	First Floor - Bathroom	0.3%
AS031810JM-29A	Structural Column Plaster	First Floor	NAD
AS031810JM-29B	Structural Column Plaster	First Floor	NAD
AS031810JM-29C	Structural Column Plaster	First Floor	NAD
AS031810JM-30A	Structural Column Plaster	First Floor	NAD
AS031810JM-30B	Structural Column Plaster	First Floor	NAD
AS031810JM-30C	Structural Column Plaster	First Floor	NAD
AS031810JM-31	Sheetrock	First Floor	NAD
AS031810JM-32	Sheetrock Remnant Debris	Basement Stairs to First Floor	NAD
AS031810JM-33A	Aircell Pipe Insulation	Basement	57.1%
AS031810JM-33B	Aircell Pipe Insulation	Basement	66.7%
AS031810JM-33C	Aircell Pipe Insulation	Basement	66.7%
AS031810JM-34A	Mudded Fitting Insulation	Basement	36.4%
AS031810JM-34B	Mudded Fitting Insulation	Basement	33.3%
AS031810JM-34C	Mudded Fitting Insulation	Basement	36.4%
AS031810JM-35A	Fiberglass Insulation Paper	Basement	NAD
AS031810JM-35B	Fiberglass Insulation Paper	Basement	NAD
AS031810JM-35C	Fiberglass Insulation Paper	Basement	NAD
AS031810JM-36A	Boiler Packing Insulation	Basement	NAD
AS031810JM-36B	Boiler Packing Insulation	Basement	NAD
AS031810JM-36C	Boiler Packing Insulation	Basement	NAD
AS031810JM-37A	Transite Heat Shield	Basement	66.7%
AS031810JM-37B	Transite Heat Shield	Basement	66.7%
AS031810JM-38A	Black Damp-Proofing	Basement	NAD
AS031810JM-38B	Black Damp-Proofing	Basement	NAD
AS031810JM-39A	Built-Up Roofing - Bottom Layer	Roof Level	14.4%

TABLE 2
 ASBESTOS CONTAINING MATERIAL SAMPLE SUMMARY
 ECOMM Building 6
 Albany, New York

SAMPLE NUMBER	SUSPECT MATERIAL DESCRIPTION	SAMPLE LOCATION	ASBESTOS CONTENT (%)
AS031810JM-39B	Built-Up Roofing - 3rd Layer	Roof Level	13%
AS031810JM-39C	Built-Up Roofing - 2nd Layer	Roof Level	15.2%
AS031810JM-39D	Built-Up Roofing - Top Layer	Roof Level	12.7%
AS031810JM-40A	Built-Up Roof Flashing - Pitch Layer	Roof Level	1.9%
AS031810JM-40B	Built-Up Roof Flashing - Bottom Layer	Roof Level	13.5%
AS031810JM-40C	Built-Up Roof Flashing - 3rd Layer	Roof Level	NAD
AS031810JM-40D	Built-Up Roof Flashing - 2nd Layer	Roof Level	9.8%
AS031810JM-40E	Built-Up Roof Flashing - Top Layer	Roof Level	6.6%
AS031810JM-41A	Flashing Sealant	Roof Level	5.1%
AS031810JM-41B	Flashing Sealant	Roof Level	12.7%
AS031810JM-42A	Coping Stone Grout	Roof Level	NAD
AS031810JM-42B	Coping Stone Grout	Roof Level	NAD
NAD = No Asbestos Detected			
NA / PS = Not Analyzed / Positive Stop			

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 2
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Exterior							
Roof Level	Coping Stone Grout	NAD					
	Built-Up Roofing - Field	NAD					
	Silvercoat - Entire Roof Field	3.7%					6,000 sf
	Built-Up Roofing - Flashing	9.0%					
	Black Roof Patch	5.3%					
	Roof Flashing Tar	NAD					
	Gray Flashing Sealant	11.1%					1/2" Wide Strip Along Entire Perimeter (350')
	Pitch Pocket	NAD					
Exterior Windows	Exterior Window Glazing Compound	Trace					
Interior							
Room 001	Sheetrock	NAD					
	Wall Penetration Grout	NAD					
Room 002	Sheetrock	NAD					
Room 003	Sheetrock	NAD					
Room 004	Sheetrock	NAD					
Room 100	Sheetrock	NAD					
	Joint Compound	NAD					
	Wood Floor Paper	NAD					
Room 101	Square-Patterned Linoleum Flooring	NAD					
	Wood Floor Paper	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 102	Square-Patterned Linoleum Flooring	NAD					
	Wood Floor Paper	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 103	Sheetrock	NAD					
	Joint Compound	NAD					
	4" Gray Cove Base	NAD					
	Mastic to Gray Cove Base	NAD					
	Blue Carpet Mastic	NAD					
	Wood Floor Paper	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 2
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 104	Sheetrock	NAD					
	Joint Compound	NAD					
	4" Gray Cove Base	NAD					
	Mastic to Gray Cove Base	NAD					
	Blue Carpet Mastic	NAD					
	Wood Floor Paper	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 105	Sheetrock	NAD					
	Joint Compound	NAD					
	4" Gray Cove Base	NAD					
	Mastic to Gray Cove Base	NAD					
	Blue Carpet Mastic	NAD					
	Wood Floor Paper	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 105A	Sheetrock	NAD					
	Joint Compound	NAD					
	4" Gray Cove Base	NAD					
	Mastic to Gray Cove Base	NAD					
	Blue Carpet Mastic	NAD					
	Wood Floor Paper	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 106	Sheetrock	NAD					
	Joint Compound	NAD					
	4" Gray Cove Base	NAD					
	Mastic to Gray Cove Base	NAD					
	Blue Carpet Mastic	NAD					
	Wood Floor Paper	NAD					
Room 107	Sheetrock	NAD					
	Joint Compound	NAD					
	4" Gray Cove Base	NAD					
	Mastic to Gray Cove Base	NAD					
	Sink Undercoating	5.6%					1 sink
	Square-Patterned Linoleum Flooring	NAD					
	Wood Floor Paper	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 2
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 108	Gray 12"x 12" Floor Tile	NAD					
	Mastic to Gray 12"x 12" Floor Tile	NAD					
	2' x 2' Ceiling Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	4" Gray Cove Base	NAD					
Room 109	Mastic to Gray Cove Base	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	4" Gray Cove Base	NAD					
	Mastic to Gray Cove Base	NAD					
	Blue Carpet Mastic	NAD					
Room 110	Wood Floor Paper	NAD					
	2' x 2' Ceiling Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	4" Gray Cove Base	NAD					
	Mastic to Gray Cove Base	NAD					
Room 111	Blue Carpet Mastic	NAD					
	Wood Floor Paper	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 112	1" Gray Ceramic Tiles	NAD					
	Grout to 1"x 1" Gray Ceramic Tiles	NAD					
	Blue Carpet Mastic	NAD					
	Wood Floor Paper	NAD					
Room 200	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	1" Gray Ceramic Tiles	NAD					
Room 201	Grout to 1"x 1" Gray Ceramic Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 2
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 202	Brown Cove Base	NAD					
	Mastic to Brown Cove Base	NAD					
	Brown Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2'x 4' Ceiling Tiles	NAD					
Room 203 (Offices)	Brown Cove Base	NAD					
	Mastic to Brown Cove Base	NAD					
	Brown Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2'x 4' Ceiling Tiles	NAD					
Room 204	Brown Cove Base	NAD					
	Mastic to Brown Cove Base	NAD					
	Sink Undercoating	5.6%					1 sink
	Sheetrock	NAD					
	Joint Compound	NAD					
	Beige 12"x 12" Floor Tile	NAD					
	Mastic to Beige 12"x 12" Floor Tile	NAD					
	2' x 4' Ceiling Tile	NAD					
Room 205	Brown Cove Base	NAD					
	Mastic to Brown Cove Base	NAD					
	Brown Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2'x 4' Ceiling Tiles	NAD					
Room 206	Gray 12"x 12" Floor Tile	NAD					
	Mastic to Gray 12"x 12" Floor Tile	NAD					
	2'x 4' Ceiling Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 207	Gray 12"x 12" Floor Tile	NAD					
	Mastic to Gray 12"x 12" Floor Tile	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 2
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 208	Gray 12"x 12" Floor Tile	NAD					
	Mastic to Gray 12"x 12" Floor Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 209	Brown Cove Base	NAD					
	Mastic to Brown Cove Base	NAD					
	Brown Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2'x 4' Ceiling Tiles	NAD					
Room 210	Brown Cove Base	NAD					
	Mastic to Brown Cove Base	NAD					
	Brown Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2'x 4' Ceiling Tiles	NAD					
Room 300	Gray 12"x 12" Floor Tile	NAD					
	Mastic to Gray 12"x 12" Floor Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 301	Gray 12"x 12" Floor Tile	NAD					
	Mastic to Gray 12"x 12" Floor Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 302	Gray 12"x 12" Floor Tile	NAD					
	Mastic to Gray 12"x 12" Floor Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					
	Sink Undercoating	5.6%					1 sink

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 2
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 303	1"x 1" Gray Ceramic Tiles	NAD					
	Grout to 1"x 1" Gray Ceramic Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2'x 2' Ceiling Tile	NAD					
Room 304	1"x 1" Gray Ceramic Tiles	NAD					
	Grout to 1"x 1" Gray Ceramic Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2'x 2' Ceiling Tile	NAD					
Room 305	Brown Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2'x 2' Ceiling Tile	NAD					
	Black Cove Base	NAD					
Room 306	Cove Base Mastic	NAD					
	Dark Blue Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2'x 2' Ceiling Tile	NAD					
Room 307	Blue Cove Base	NAD					
	Cove Base Mastic	NAD					
	Beige 12"x 12" Floor Tile	NAD					
	Floor Tile Mastic	NAD					
	Sheetrock	NAD					
Room 308	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
	Dark Blue Carpet Mastic	NAD					
Room 308	Beige 12"x 12" Floor Tile	NAD					
	Floor Tile Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 308	Blue Cove Base	NAD					
	Cove Base Mastic	NAD					
	Dark Blue Carpet Mastic	NAD					
	Beige 12"x 12" Floor Tile	NAD					
	Floor Tile Mastic	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 2
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 309	Blue Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 310	Gray 12"x 12" Floor Tile	NAD					
	Floor Tile Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2'x 2' Ceiling Tile	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 311	Blue Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 312	Blue Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 313	Blue Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 314	Blue Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 2
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 315	Gray 12"x 12" Floor Tile	NAD					
	Floor Tile Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 400	Sheetrock	NAD					
	Joint Compound	NAD					
	Blue Carpet Mastic	NAD					
	Wood Floor Paper	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 401	Gray Carpet Mastic	NAD					
	Wood Floor Paper	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 402	Sheetrock	NAD					
	Joint Compound	NAD					
	Blue Carpet Mastic	NAD					
	Wood Floor Paper	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 403	Gray 12"x 12" Floor Tile	NAD					
	Floor Tile Mastic	NAD					
	Wood Floor Paper	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 404	Light Gray 12"x 12" Floor Tile	NAD					
	Dark Gray 12"x 12" Floor Tile	NAD					
	Mastic to Floor Tiles	NAD					
	Mastic Pucks	NAD					
	Wood Floor Paper	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 2
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 405	Blue Linoleum	NAD					
	Blue Carpet Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
	Wood Floor Paper	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Sink Undercoating	5.6%					1 sink
Room 406	Blue Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Wood Floor Paper	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 407	Blue Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Wood Floor Paper	NAD					
	2' x 2' Ceiling Tile	NAD					
	Tan Cove Base	NAD					
Room 408	Cove Base Mastic	NAD					
	Blue Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Wood Floor Paper	NAD					
	Tan Cove Base	NAD					
Room 409	Cove Base Mastic	NAD					
	Blue Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Wood Floor Paper	NAD					
	2' x 2' Ceiling Tile	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 2
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 410	Blue Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Wood Floor Paper	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 411	Blue Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Wood Floor Paper	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 412 (occupied office)	Blue Carpet Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
Rooms 412 and 413	1"x 1" Gray Ceramic Tiles	NAD					
	Grout to 1"x 1" Gray Ceramic Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2'x 2' Ceiling Tile	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Exterior							
Roof Level	Rubber Roof Seam Sealant	NAD					
	Pitch Pockets	3.0%					10 pitch pockets
	Low Roof - Built-Up Roofing - Field	NAD					
	Low Roof - Built-Up Roofing - Flashing	NAD					
	Penthouse Flashing Sealant	1.9%					3,650 sf
	Penthouse Roof - Built-Up Roofing - Field	7.4%					
	Penthouse Roof - Built-Up Roofing - Flashing	NA/PS					
	Rolled Roofing Patch	NAD					
	Penthouse Wall Caulk	5.70%					26 lf
Exterior Windows	Exterior Window Glazing Compound	NAD					
Interior							
Room 100	Maroon Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 101	Maroon Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 102	Inaccessible (Secured Storage)	NAD					
Room 103	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 104	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 105	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 106	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 107	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 108	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 109	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 110	Blue 12"x 12" Floor Tile	NAD					
	Floor Tile Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Blue Cove Base	NAD					
	Cove Base Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 111	Blue 12"x 12" Floor Tile	NAD					
	Floor Tile Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Blue Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 112	2' x 2' Ceiling Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 113	Penetration Grout	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 114	Penetration Grout	NAD					
	Maroon Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Cove Base	NAD					
Room 115	Cove Base Mastic	NAD					
	Gray Carpet Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Black Cove Base	NAD					
Room 116	Cove Base Mastic	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Blue 12"x 12" Floor Tile	NAD					
	White 12"x 12" Floor Tile	NAD					
Room 117	Mastic to 12"x 12" Floor Tiles	NAD					
	Sheetrock	NAD					
Room 117	Joint Compound	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 118	Carpet Mastic	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 119	Green Carpet Mastic	NAD					
	Green Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 120A through 120D	Sheetrock	NAD					
	Joint Compound	NAD					
	Gray Carpet Mastic	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 121	Storage Room - Inaccessible	NAD					
Room 122	Sheetrock	NAD					
	Joint Compound	NAD					
Room 123	Gray Carpet Mastic	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 124	Green Carpet Mastic	NAD					
	Green Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 125	Green Carpet Mastic	NAD					
	Green Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 126	Maroon Carpet Mastic	NAD					
	Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 127	Gray Carpet Mastic	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 128	Gray Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 129	Gray Carpet Mastic	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 130	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 131	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 132	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 133	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 134	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 135	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 136A through 136D	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 137	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 138	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 139	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 140	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 141	Brown-Box Patterned Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Brown Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 142	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 143	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 144	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 145	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 146A and 146B	White Linoleum	NAD					
	1"x 1" Gray Ceramic Tile	NAD					
	Grout to 1"x 1" Ceramic Tile	NAD					
	2'x 2' Ceiling Tile	NAD					
Room 147	Sheetrock	NAD					
	Joint Compound	NAD					
Room 200	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 201	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 202	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 203	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 204	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 205	Off-White 12"x 12" Floor Tile	NAD					
	Floor Tile Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 206	Off-White 12"x 12" Floor Tile	NAD					
	Floor Tile Mastic	NAD					
	Maroon Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 207	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 208	Sheetrock	NAD					
	Joint Compound	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 209	Gray Carpet Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 210	Green Carpet Mastic	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 211	Green Carpet Mastic	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 212	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 213A and 213B	Blue Carpet Mastic	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 214	Green Carpet Mastic	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 215	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 216	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 217	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 218	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
	Tan Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 219	Blue Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 220	White 12"x 12" Floor Tile	NAD					
	Floor Tile Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Gray Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 221	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2'x 2' Ceiling Tile	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 222	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2'x 2' Ceiling Tile	NAD					
Room 223	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2'x 2' Ceiling Tile	NAD					
Room 224	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2'x 2' Ceiling Tile	NAD					
Room 225	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2'x 2' Ceiling Tile	NAD					
Room 226	Tan Carpet Mastic	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 227	Gray Carpet Mastic	NAD					
	Green Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 228	Gray Carpet Mastic	NAD					
	Green Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 229	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 230	Beige 12"x 12" Floor Tile	NAD					
	Floor Tile Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 231	Blue Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 232	1"x 1" Gray Ceramic Tile	NAD					
	Grout to 1"x 1" Ceramic Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 233	1"x 1" Gray Ceramic Tile	NAD					
	Grout to 1"x 1" Ceramic Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 234A and 234B	Off-White 12"x 12" Floor Tile	NAD					
	Floor Tile Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 235	Sheetrock	NAD					
	Joint Compound	NAD					
	Blue Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 236	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 300	Black Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	3" White Cove Base	NAD					
	Cove Base Mastic	NAD					
Rooms 301 through 310	Black Carpet Mastic	NAD					
	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	3" White Cove Base	NAD					
	Cove Base Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 311	Inaccessible (Secured Storage)	NAD					
Room 312	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 313	White 12"x 12" Floor Tile	NAD					
	Blue 12"x 12" Floor Tile	NAD					
	Mastic to 12"x 12" Floor Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	3" White Cove Base	NAD					
Room 314	Cove Base Mastic	NAD					
	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 315	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 316	2' x 2' Ceiling Tile	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
Room 317	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Gray Carpet Mastic	NAD					
Room 318	Gray and White 12"x 12" Floor Tiles	1.5%	110				
	Floor Tile Mastic	3.5%					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 319	Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 320	4" White Cove Base	NAD					
	Cove Base Mastic	NAD					
	Blue Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 321	Off-White 12"x 12" Floor Tile	NAD					
	Floor Tile Mastic	NAD					
	4" White Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 322	2' x 2' Ceiling Tile	NAD					
	Gray and White 12"x 12" Floor Tiles	1.5%	115				
	Floor Tile Mastic	3.5%					
	Sheetrock	NAD					
Room 323 through 333	Joint Compound	NAD					
	Blue Carpet Mastic	NAD					
	4" White Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
Room 334	Joint Compound	NAD					
	Gray Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Rooms 335 through 339	2' x 2' Ceiling Tile	NAD					
	Gray Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
Room 340	Joint Compound	NAD					
	Gray Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 341	Gray Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
Room 342	Gray Carpet Mastic	NAD					
	3" Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 343	Gray Carpet Mastic	NAD					
	3" Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 344	Maroon Carpet Mastic	NAD					
	3" Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Rooms 345A and 345B	2"x 2" Gray Ceramic Tiles	NAD					
	Grout to 2"x 2" Ceramic Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 346	Gray Carpet Mastic	NAD					
	3" Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 347	Mastic to Marble Floor Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 348	Sheetrock	NAD					
	Joint Compound	NAD					
Room 349	Sheetrock	NAD					
	Joint Compound	NAD					
	White 12"x 12" Floor Tile	NAD					
	Floor Tile Mastic	NAD					
Room 400	Grout to Marble Floor Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Stucco Wall Finish	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 401	Grout to Marble Floor Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Stucco Wall Finish	NAD					
Rooms 402 through 406	Blue Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Black Cove Base	NAD					
Room 407	Cove Base Mastic	NAD					
	Blue Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 408	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					
	Gray and White 12"x 12" Floor Tiles	1.5%	65				
Room 409	Floor Tile Mastic	3.5%					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2'x 2' Ceiling Tile	NAD					
Room 410	3" White Cove Base	NAD					
	Cove Base Mastic	NAD					
	Blue Carpet Mastic	NAD					
	Sheetrock	NAD					
Room 411	Joint Compound	NAD					
	Blue Cove Base	NAD					
	Cove Base Mastic	NAD					
	Blue Carpet Mastic	NAD					
Room 412 through 415	Sheetrock	NAD					
	Joint Compound	NAD					
	Blue Cove Base	NAD					
	Cove Base Mastic	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 416	Blue Carpet Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 417	Gray and White 12"x 12" Floor Tiles	1.5%	24				
	Floor Tile Mastic	3.5%					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 418	Gray and White 12"x 12" Floor Tiles	1.5%	110				
	Floor Tile Mastic	3.5%					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 419	Blue Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 420	Gray and White 12"x 12" Floor Tiles	1.5%	200				
	Floor Tile Mastic	3.5%					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 421 through 434	Gray Carpet Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 435	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 436	White 12"x 12" Floor Tile	NAD					
	Floor Tile Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 437	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Gray and White 12"x 12" Floor Tiles	1.5%	225				
	Floor Tile Mastic	3.5%					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 438	Gray Carpet Mastic	NAD	250				
	Gray and White 12"x 12" Floor Tiles	1.5%					
	Floor Tile Mastic	3.5%					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Tan Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 439	Gray and White 12"x 12" Floor Tiles	1.5%	440				
	Floor Tile Mastic	3.5%					
	Maroon Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Gray Cove Base	NAD					
	Cove Base Mastic	NAD					
Rooms 440 through 444	Gray and White 12"x 12" Floor Tiles	1.5%	850				
	Floor Tile Mastic	3.5%					
	Maroon Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Gray Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 445 and 446	Gray and White 12"x 12" Floor Tiles	1.5%	500				
	Floor Tile Mastic	3.5%					
	Maroon Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	2' x 2' Ceiling Tile	NAD					
	Gray Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 447	Gray and White 12"x 12" Floor Tiles	1.5%	140				
	Floor Tile Mastic	3.5%					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Gray Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 448	Gray and White 12"x 12" Floor Tiles	1.5%	150				
	Floor Tile Mastic	3.5%					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Sink Undercoating	NAD					
	Gray Cove Base	NAD					
	Cove Base Mastic	NAD					
	2' x 2' Ceiling Tile	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 449	2"x 2" Gray Ceramic Tiles	NAD					
	Grout to 2"x 2" Ceramic Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 450	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Stucco Wall Finish	NAD					
Room 451 through 453	Grout to Marble Floor Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Stucco Wall Finish	NAD					
Room 454 through 456	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Stucco Wall Finish	NAD					
Rooms 457 and 458	2"x 2" Gray Ceramic Tiles	NAD					
	Grout to 2"x 2" Ceramic Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 459	Sheetrock	NAD					
	Joint Compound	NAD					
Room 460	Grout to Marble Floor Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Stucco Wall Finish	NAD					
P-1	Grout to Marble Floor Tile	NAD					
	Stucco Wall Finish	NAD					
	Sheetrock	NAD					
P-2	Joint Compound	NAD					
	Gray Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
P-3	Joint Compound	NAD					
	Sheetrock	NAD					
	Grout to Marble Floor Tile	NAD					
P-4 through P-10	Gray Carpet Mastic	NAD					
	Black Cove Base	NAD					
	Cove Base Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 3
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
P-11	Grout to Marble Floor Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Stucco Wall Finish	NAD					
P-12	Grout to Marble Floor Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
P-13	Grout to Marble Floor Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Stucco Wall Finish	NAD					
Attic Space Above P-13	No Suspect ACMs Observed						

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 4
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Exterior							
Roof Level	Rubber Roof Seam Sealant	2.1%					3.500 lf (all seams on rubber roof system)
	Flashing Caulk	NAD					
	Gray Sealant	NAD					
	Pitch Pocket	NAD					
	Roof Fiberboard	NAD					
Exterior Walls, Windows and Doors	Exterior Window Caulk	4.8%					12 windows - 16 lf per
	Exterior Door Caulk	4.2%					1 door - 24 lf
	Patch on Exterior Wall	NAD					
Interior							
Room 001 (basement)	White Pipe Wrap	5.1%			1		
Room 100	Sheetrock	NAD					
	Joint Compound	NAD					
Room 101	6"x 6" Clay Floor Tile	NAD					
	Grout to 6"x 6" Clay Floor Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
	4" White Ceramic Wall Tile	NAD					
	Grout to 4" White Ceramic Wall Tile	NAD					
	12"x 12" Beige Ceramic Floor Tile	NAD					
Room 102	Grout to 12"x 12" Beige Ceramic Floor Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
	6"x 6" Clay Floor Tile	NAD					
Room 103	Grout to 6"x 6" Clay Floor Tile	NAD					
	12"x 12" Beige Ceramic Floor Tile	NAD					
	Grout to 12"x 12" Beige Ceramic Floor Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
	12"x 12" Beige Floor Tile	NAD					
Room 104	12"x 12" Black Floor Tile	NAD					
	Mastic to 12"x 12" Beige and Black Floor Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 4
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 105	Marble-Patterned Linoleum Floor Tiles	NAD					
	Leveling Compound	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
	Laminant Wall Paneling	NAD					
Room 106	Mastic to Laminant Wall Paneling	NAD					
	1" Black Ceramic Floor Tiles	NAD					
	Grout to 1" Black Ceramic Floor Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 107	1" Black Ceramic Floor Tiles	NAD					
	Grout to 1" Black Ceramic Floor Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 108	Paper Above Wood Ceiling	NAD					
	12"x 12" Black Ceramic Floor Tiles	NAD					
	Grout to 12"x 12" Black Ceramic Floor Tile	NAD					
	Sheetrock	NAD					
Room 109	Joint Compound	NAD					
	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 200	Paper Above Wood Ceiling	NAD					
	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 201	Paper Above Wood Ceiling	NAD					
	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 202	Paper Above Wood Ceiling	NAD					
	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 4
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 203	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 204	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 204	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 205	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 206	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 207	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 208	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 209	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 210	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
	Sink Undercoating	5.3%					1 sink

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 4
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 211	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 212	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 213	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 214	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 215	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 216	Blue Carpet Mastic	NAD					
	Tan Clay Tile	NAD					
	Grout to Tan Clay Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 217	1" Black Ceramic Floor Tiles	NAD					
	Grout to 1" Black Ceramic Floor Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 218	1" Black Ceramic Floor Tiles	NAD					
	Grout to 1" Black Ceramic Floor Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 4
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 300	1" Black Ceramic Floor Tiles	NAD					
	Grout to 1" Black Ceramic Floor Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 301	1" Black Ceramic Floor Tiles	NAD					
	Grout to 1" Black Ceramic Floor Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 302	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 303	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 304	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 305	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 306	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 307	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 308	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 4
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 309	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 310	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 311	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 312	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 313	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 314	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 315	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 316	Purple Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 317	Mastic Remnants	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Paper Above Wood Ceiling	NAD					
Room 400	Beige Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 4
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 401	Dot-Patterned Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 402	Beige Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 403	Carpet Tile Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 404	Carpet Tile Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 405	Carpet Tile Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 406	Beige Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 407	Beige Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 408	Beige Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 409	Beige Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 410	Green Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 411	Box-Style Linoleum Flooring	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Sink Undercoating	5.3%					1 sink

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 6
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Exterior							
Main Roof and Small Roof	Gray Sealant on Exterior Wall	12.7%					125 sf
	Built-Up Roofing Material - Field	15.2%					8,685 sf
	Built-Up Roofing Material - Flashing	9.8%					
	Gray Flashing Sealant	12.7%					1' wide strip along perimeter / 500 sf
	Coping Stone Grout	NAD					
	Exterior Window Glazing Compound	Trace					
Interior							
Room 001	Aircell Pipe Insulation	44.4%			7		
	Wall Damp-Proofing	NAD					
	Sheetrock Remnants on Ceiling	NAD					
Room 002	Aircell Pipe Insulation	44.4%			35		
	Fiberglass Insulation Paper and Mastic	NAD					
	Mudded Fitting Insulation	22.2%		12			
	Pipe Insulation Debris	44.4%					1,300 sf
	Sheetrock Remnants on Ceiling	NAD					
Room 003	Aircell Pipe Insulation	44.4%			20		
	Fiberglass Insulation Paper and Mastic	NAD					
	Mudded Fitting Insulation	22.2%		3			
	Pipe Insulation Debris	44.4%					1,300 sf
Room 004	Boiler Insulation	NAD					
	Aircell Pipe Insulation	44.4%			30		
	Fiberglass Insulation Paper and Mastic	NAD					
	Mudded Fitting Insulation	22.2%		15			
	Wall Damp-Proofing	NAD					
	Boiler Breeching Insulation	Assumed					50 sf
	Pipe Insulation Debris	Assumed					1,000 sf
	Transite Panels (above boiler)	66.7%					144 sf
First Floor							
Room 100	Gray Carpet Mastic	NAD					
	Ceramic Floor Tiles	NAD					
	Grout to Ceramic Floor Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Gray Cove Base	NAD					
	Cove Base Mastic	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 6
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 101	Gray Carpet Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Gray Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 102	Ceramic Floor Tiles	NAD					
	Grout to Ceramic Floor Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 103	Ceramic Floor Tiles	NAD					
	Grout to Ceramic Floor Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Gray Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 104	Ceramic Floor Tiles	NAD					
	Grout to Ceramic Floor Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Gray Cove Base	NAD					
	Cove Base Mastic	NAD					
Room 105	Ceramic Floor Tiles	NAD					
	Grout to Ceramic Floor Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 106	Ceramic Floor Tiles	NAD					
	Grout to Ceramic Floor Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Gray Cove Base	NAD					
	Cove Base Mastic	NAD					
	Aircell Pipe Insulation	44.4%			16		

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 6
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 107	Ceramic Floor Tiles	NAD					
	Grout to Ceramic Floor Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Aircell Pipe Insulation	44.4%			16		
	Beige 12"x 12" Floor Tile	NAD					
Room 108	Floor Tile Mastic	NAD					
	Ceramic Floor Tiles	NAD					
	Grout to Ceramic Floor Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Brown Cove Base	NAD					
Room 109	Cove Base Mastic	NAD					
	Ceramic Floor Tiles	NAD					
	Grout to Ceramic Floor Tiles	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Brown Cove Base	NAD					
Room 110	Cove Base Mastic	NAD					
	Beige 12"x 12" Floor Tile	NAD					
	Floor Tile Mastic	NAD					
	Sheetrock	NAD					
	Ceramic Floor Tiles	NAD					
	Floor Tile Mastic	NAD					
	Brown Cove Base	NAD					
	Cove Base Mastic	NAD					
	Structural Steel Plaster	NAD					
	Aircell Pipe Insulation	44.4%			36		
	Mudded Fitting Insulation	22.2%		7			
	Mag Panel Above Metal Ceiling	66.7%					3,000 sf
Room 111	Wall Panel Glue	3.0%					250 sf
	Beige 12"x 12" Floor Tile	NAD					
	Floor Tile Mastic	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 112	Wall Plaster	NAD					
	Ceiling Plaster	NAD					
	Brown Cove Base	NAD					
	Cove Base Mastic	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
E-COMM Building 6
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Second Floor							
Room 200	1' x 1' Ceiling Tile	NAD					
	Plaster Walls	NAD					
Room 201	Plaster Walls	NAD					
	Plaster Ceiling	NAD					
Room 202	Plaster Walls	NAD					
	Linoleum Flooring	NAD					
	Plaster Ceiling	NAD					
Room 203	Plaster Walls	NAD					
Room 204	Clay Flooring	1.5%	135				
	Plaster Walls	NAD					
Third Floor							
Room 300	Floor Paper	NAD					
	Plaster Walls	NAD					
Room 301	Plaster Walls	NAD					
	Plaster Ceiling	NAD					
Room 302	Clay Flooring	1.5%	180				
	Plaster Walls	NAD					
	Plaster Ceiling	NAD					
Room 303	Clay Flooring	1.5%	135				
	Plaster Walls	NAD					
	Plaster Ceiling	NAD					
Fourth Floor							
Room 400	White 12"x 12" Floor Tile	7.2%	300				
	Green and Gray 9"x 9" Floor Tiles	10.5%					
	Leveling Compound	NAD					
	Plaster Walls	NAD					
	Plaster Ceiling	NAD					
Room 401	Plaster Walls	NAD					
	Plaster Ceiling	NAD					
Room 402	Sheetrock	NAD					
	Fiberglass Paper	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
Former Mission Building
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Exterior							
Roofs	Low Roof - Built-Up Roofing	5.2%					1,350 sf
	High Roof - Built-Up Roofing	8.6%					2,175 sf
	Roof Tar	3.1%					Quantities for these materials are included in the above totals.
	Silvercoat	8.2%					
Exterior Walls and Windows	Stucco Finish on Exterior Walls	NAD					
	Exterior Window Glazing Compound	NAD					
Interior							
Basement	No Suspect ACMs Observed						
Room 100	White 12"x 12" Floor Tile	NAD					
	Mastic to White 12"x 12" Floor Tile	Trace					
	Beige 12"x 12" Floor Tile	NAD					
	Mastic to Beige 12"x 12" Floor Tile	Trace					
	Textured 12"x 12" Floor Tile (no mastic)	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Wall Plaster	NAD					
	Window Sill Linoleum	NAD					
Room 101	Wall Panel Glue	NAD					
	Wall Plaster	NAD					
Room 102	Wall Plaster	NAD					
	Ceiling Plaster	NAD					
	Beige 12"x 12" Floor Tile	NAD					
Room 103	Mastic to Beige 12"x 12" Floor Tile	Trace					
	Clay Floor Tile	NAD					
	Grout to Clay Floor Tile	NAD					
	Wall Plaster	NAD					
	Ceiling Plaster	NAD					
Room 200	Sheetrock	NAD					
	Joint Compound	NAD					
	Wall Plaster	NAD					
Room 201	Linoleum Flooring	NAD					
	Ceramic Floor Tile	NAD					
	Grout to Ceramic Floor Tile	NAD					
	Ceiling Plaster	NAD					
	Sheetrock	NAD					
Room 201	Joint Compound	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
Former Mission Building
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 202	Streaked 12"x 12" Floor Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 203	Gray 12"x 12" Floor Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Wall Plaster	NAD					
Room 204	Swirl Pattern Linoleum	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Textured Ceiling Finish	NAD					
Room 205 (bathroom)	Brown Swirl Pattern Linoleum	10.0%	50				
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 206	Swirl Pattern Linoleum	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Textured Ceiling Finish	NAD					
	Wood Panel Glue (4' up walls)	NAD					
Room 207	Wall Plaster	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
Room 300	Ceiling Plaster	NAD					
	Wall Plaster	NAD					
Room 301	Sheetrock	NAD					
	Joint Compound	NAD					
	Ceiling Plaster	NAD					
	Wall Plaster	NAD					
Room 302	Ceiling Plaster	NAD					
	Wall Plaster	NAD					
Room 303 (bathroom)	6"x 6" Ceramic Tiles	NAD					
	Grout to Ceramic Floor Tile	NAD					
	Ceiling Plaster	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Wall Plaster	NAD					
	Black Ceramic Tile	NAD					
	Grout to Black Ceramic Tile	NAD					

TABLE 3
ROOM BY ROOM INVENTORY
Former Mission Building
Albany, New York

ROOM NAME	SUSPECT MATERIALS	ASBESTOS CONTENT (%)	FLOORING (SF)	PIPE FITTING INSULATION (EA)	PIPE INSULATION (LF)	ASBESTOS CONTAINING DEBRIS (SF)	MISCELLANEOUS MATERIAL (SF/LF)
Room 304	Gray 12"x 12" Floor Tile	NAD					
	White 12"x 12" Floor Tile	NAD					
	Mastic to White 12"x 12" Floor Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Ceiling Plaster	NAD					
	Wall Plaster	NAD					
Room 305	Gray 12"x 12" Floor Tile	NAD					
	White 12"x 12" Floor Tile	NAD					
	Mastic to White 12"x 12" Floor Tile	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Ceiling Plaster	NAD					
	Wall Plaster	NAD					
Room 306	Sheetrock	NAD					
	Joint Compound	NAD					
	Ceiling Plaster	NAD					
	Wall Plaster	NAD					
	Textured Ceiling Finish	NAD					
Room 307	Sheetrock	NAD					
	Joint Compound	NAD					
	Ceiling Plaster	NAD					
	Wall Plaster	NAD					
Room 308	Sheetrock	NAD					
	Joint Compound	NAD					
	Ceiling Plaster	NAD					
	Wall Plaster	NAD					
	Textured Ceiling Finish	NAD					
Room 309 (bathroom)	Gray 12"x 12" Linoleum	NAD					
	Sheetrock	NAD					
	Joint Compound	NAD					
	Ceiling Plaster	NAD					
	Wall Plaster	NAD					
	2'x 2' Ceiling Tile	NAD					

APPENDIX A
Asbestos Bulk Sample Analysis

**AmeriSci Boston**

8 SCHOOL ST.
WEYMOUTH, MA 02189
TEL: (781) 337-9334 • FAX: (781) 337-7642

PLM Bulk Asbestos Report

Clough, Harbour & Associates
Attn: Jim Morey
3 Winners Circle

Albany, NY 12205

Date Received 03/31/10 AmeriSci Job # 510031329
Date Examined 04/05/10 P.O. #
ELAP # 10982 Page 1 of 18
RE: 16433; ACCA; Building 2

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032410JM-01A 1 Location: Roof Level	510031329-01	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: Brown, Homogeneous, Non-Fibrous, Cementitious, Coping Stone Grout Asbestos Types: Other Material: Non-fibrous 100 %			
AS032410JM-01B 1 Location: Roof Level	510031329-02	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: Brown, Homogeneous, Non-Fibrous, Cementitious, Coping Stone Grout Asbestos Types: Other Material: Non-fibrous 100 %			
AS032410JM-02A 2 Location: Roof Level	510031329-03	Yes	3.7 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Silver, Homogeneous, Fibrous, Silver Coat Asbestos Types: Chrysotile 3.7 % Other Material: Wollastonite Trace, Non-fibrous 26.6 %			
AS032410JM-02B 2 Location: Roof Level	510031329-04	Yes	2.3 % (ELAP 198.6; 400pc) by Ivan H Reyes on 04/05/10
Analyst Description: Silver, Homogeneous, Fibrous, Silver Coat Asbestos Types: Chrysotile 2.3 % Other Material: Wollastonite Trace, Non-fibrous 30.6 %			
AS032410JM-03A 3 Location: Roof Level	510031329-05	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Fibrous, Built-up Roofing - Btm Lyr Asbestos Types: Other Material: Non-fibrous 5.2 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 2

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032410JM-03B 3 Location: Roof Level	510031329-06	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Fibrous, Built-up Roofing - 7th Lyr Asbestos Types: Other Material: Non-fibrous 2.8 %			
AS032410JM-03C 3 Location: Roof Level	510031329-07	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Fibrous, Built-up Roofing - 6th Lyr Asbestos Types: Other Material: Fibrous glass Trace, Non-fibrous 5.8 %			
AS032410JM-03D 3 Location: Roof Level	510031329-08	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Fibrous, Built-up Roofing - 5th Lyr Asbestos Types: Other Material: Fibrous glass 2 %, Non-fibrous 17 %			
AS032410JM-03E 3 Location: Roof Level	510031329-09	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Fibrous, Built-up Roofing - 4th Lyr Asbestos Types: Other Material: Fibrous glass 2 %, Non-fibrous 18.2 %			
AS032410JM-03F 3 Location: Roof Level	510031329-10	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Fibrous, Built-up Roofing - 3rd Lyr Asbestos Types: Other Material: Fibrous glass 1 %, Non-fibrous 9.7 %			
AS032410JM-03G 3 Location: Roof Level	510031329-11	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Fibrous, Built-up Roofing - 2nd Lyr Asbestos Types: Other Material: Fibrous glass 1 %, Non-fibrous 12.6 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 2

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032410JM-03H 3 Location: Roof Level	510031329-12	Yes	Trace (<0.25 % pc) (ELAP 198.6; 400pc) by Ivan H Reyes on 04/05/10
Analyst Description: Silver/Black, Heterogeneous, Fibrous, Built-up Roofing - 1st Lyr Asbestos Types: Chrysotile <0.25 % pc Other Material: Fibrous glass 2 %, Wollastonite Trace, Non-fibrous 18.8 %			
AS032410JM-04A 4 Location: Roof Level	510031329-13	Yes	5.3 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Fibrous, Roof Patch Asbestos Types: Chrysotile 5.3 % Other Material: Non-fibrous 18.5 %			
AS032410JM-04B 4 Location: Roof Level	510031329-14	Yes	3.2 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Fibrous, Roof Patch Asbestos Types: Chrysotile 3.2 % Other Material: Non-fibrous 12.6 %			
AS032410JM-05A 5 Location: Roof Level	510031329-15	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Non-Fibrous, Roof Flashing Asbestos Types: Other Material: Non-fibrous 6.4 %			
AS032410JM-05B 5 Location: Roof Level	510031329-16	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Non-Fibrous, Roof Flashing Asbestos Types: Other Material: Non-fibrous 2 %			
AS032410JM-06 Location: Roof Level	510031329-17	Yes	Trace (<0.25 % pc) (ELAP 198.6; 400pc) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Fibrous, Flashing-Bottom Lyr Asbestos Types: Chrysotile <0.25 % pc Other Material: Fibrous glass 3 %, Non-fibrous 33 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 2

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032410JM-07 Location: Roof Level Analyst Description: Silver/Black, Homogeneous, Fibrous, Flashing-Top Lyr Asbestos Types: Chrysotile 2.9 % Other Material: Fibrous glass 2 %, Non-fibrous 18.9 %	510031329-18	Yes	2.9 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
AS032410JM-08A 8 Location: Roof Level Analyst Description: Black, Homogeneous, Fibrous, Flashing Sealant Asbestos Types: Chrysotile 11.0 % Other Material: Non-fibrous 19.3 %	510031329-19	Yes	11 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
AS032410JM-08B 8 Location: Roof Level Analyst Description: Black, Homogeneous, Fibrous, Flashing Sealant Asbestos Types: Chrysotile 11.1 % Other Material: Non-fibrous 16.7 %	510031329-20	Yes	11.1 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
AS032410JM-09A 9 Location: Roof Level Analyst Description: Black, Homogeneous, Fibrous, Pitch Pocket Asbestos Types: Chrysotile <0.25 % pc Other Material: Non-fibrous 14.2 %	510031329-21	Yes	Trace (<0.25 % pc) (ELAP 198.6; 400pc) by Ivan H Reyes on 04/05/10
AS032410JM-09B 9 Location: Roof Level Analyst Description: Black, Homogeneous, Fibrous, Pitch Pocket Asbestos Types: Other Material: Non-fibrous 13.8 %	510031329-22	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
AS032410JM-10A 10 Location: Analyst Description: White, Homogeneous, Non-Fibrous, Ext. Window Glazing Asbestos Types: Other Material: Non-fibrous 12 %	510031329-23	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10

PLM Bulk Asbestos Report

16433; ACCA; Building 2

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032410JM-10B 10 Location:	510031329-24	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: White, Homogeneous, Non-Fibrous, Ext. Window Glazing Asbestos Types: Other Material: Non-fibrous 5.4 %			
AS032410JM-11A 11 Location: 3rd Floor	510031329-25	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: White, Homogeneous, Fibrous, 2'x2' Ceiling Tile Asbestos Types: Other Material: Cellulose 45 %, Fibrous glass 30 %, Non-fibrous 25 %			
AS032410JM-11B 11 Location: 3rd Floor	510031329-26	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: White, Homogeneous, Fibrous, 2'x2' Ceiling Tile Asbestos Types: Other Material: Cellulose 50 %, Fibrous glass 30 %, Non-fibrous 20 %			
AS032410JM-12A 12 Location: 4th Floor	510031329-27	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: White, Homogeneous, Fibrous, 2'x2' Ceiling Tile Asbestos Types: Other Material: Cellulose 45 %, Fibrous glass 30 %, Non-fibrous 25 %			
AS032410JM-12B 12 Location: 4th Floor	510031329-28	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: White, Homogeneous, Fibrous, 2'x2' Ceiling Tile Asbestos Types: Other Material: Cellulose 45 %, Fibrous glass 30 %, Non-fibrous 25 %			
AS032410JM-13A 13 Location: 2nd Floor	510031329-29	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: White, Homogeneous, Fibrous, 2'x4' Ceiling Tile Asbestos Types: Other Material: Cellulose 50 %, Fibrous glass 30 %, Non-fibrous 20 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 2

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032410JM-13B 13 Location: 2nd Floor	510031329-30	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: White, Homogeneous, Fibrous, 2'x4' Ceiling Tile Asbestos Types: Other Material: Cellulose 45 %, Fibrous glass 35 %, Non-fibrous 20 %			
AS032410JM-14A 14 Location: 3rd Floor	510031329-31	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: Off-White/Tan, Homogeneous, Fibrous, Sheetrock Asbestos Types: Other Material: Cellulose 6 %, Fibrous glass 2 %, Non-fibrous 92 %			
AS032410JM-14B 14 Location: 3rd Floor	510031329-32	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: Off-White/Tan, Homogeneous, Fibrous, Sheetrock Asbestos Types: Other Material: Cellulose 12 %, Fibrous glass 2 %, Non-fibrous 86 %			
AS032410JM-15A 15 Location: 4th Floor	510031329-33	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: Off-White/Tan, Homogeneous, Fibrous, Sheetrock Asbestos Types: Other Material: Cellulose 10 %, Non-fibrous 90 %			
AS032410JM-15B 15 Location: 4th Floor	510031329-34	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: Off-White/Tan, Homogeneous, Fibrous, Sheetrock Asbestos Types: Other Material: Cellulose 15 %, Non-fibrous 85 %			
AS032410JM-16A 16 Location: 3rd Floor	510031329-35	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: White, Homogeneous, Non-Fibrous, Joint Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 2

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032410JM-16B 16 Location: 3rd Floor	510031329-36	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: White, Homogeneous, Non-Fibrous, Joint Compound Asbestos Types: Other Material: Cellulose Trace, Fibrous glass Trace, Non-fibrous 100 %			
AS032410JM-17A 17 Location: 4th Floor	510031329-37	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: White, Homogeneous, Non-Fibrous, Joint Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS032410JM-17B 17 Location: 4th Floor	510031329-38	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: White, Homogeneous, Non-Fibrous, Joint Compound Asbestos Types: Other Material: Cellulose Trace, Synthetic fibers Trace, Non-fibrous 100 %			
AS032410JM-18A 18 Location: 4th Floor	510031329-39	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Fibrous, Tar Paper Udr Wood Floor Asbestos Types: Other Material: Non-fibrous 5.6 %			
AS032410JM-18B 18 Location: 4th Floor	510031329-40	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Fibrous, Tar Paper Udr Wood Floor Asbestos Types: Other Material: Non-fibrous 5.2 %			
AS032410JM-19A 19 Location: 4th Floor Kitchen	510031329-41	Yes	5.6 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Purple, Homogeneous, Fibrous, Sink Undercoat Asbestos Types: Chrysotile 5.6 % Other Material: Non-fibrous 50.7 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 2

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032410JM-19B 19 Location: 4th Floor Kitchen	510031329-42	Yes	5.5 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Purple, Homogeneous, Fibrous, Sink Undercoat Asbestos Types: Chrysotile 5.5 % Other Material: Non-fibrous 49.2 %			
AS032410JM-20A 20 Location: Basement	510031329-43	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Pipe Penetration Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS032410JM-20B 20 Location: Basement	510031329-44	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Pipe Penetration Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS032410JM-21A 21 Location: 4th Floor - Elec Closet	510031329-45	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Non-Fibrous, Mastic Pucks Asbestos Types: Other Material: Non-fibrous 45.8 %			
AS032410JM-21B 21 Location: 4th Floor - Elec Closet	510031329-46	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Non-Fibrous, Mastic Pucks Asbestos Types: Other Material: Non-fibrous 46 %			
AS032410JM-22A 22 Location: 4th Floor - Bathroom	510031329-47	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, 1'x1' Ceramic Tile Asbestos Types: Other Material: Non-fibrous 100 %			

Client Name: Clough, Harbour & Associates

PLM Bulk Asbestos Report

16433; ACCA; Building 2

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032410JM-22B 22	510031329-48 Location: 4th Floor - Bathroom	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, 1'x1' Ceramic Tile Asbestos Types: Other Material: Non-fibrous 100 %			
AS032410JM-23	510031329-49 Location: 4th Floor - Bathroom	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, 1'x1' Ceramic Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS032410JM-24A 24	510031329-50 Location: 3rd Floor	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, Cementitious, Leveling Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS032410JM-24B 24	510031329-51 Location: 3rd Floor	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, Cementitious, Leveling Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS032410JM-25A 25	510031329-52 Location: 4th Floor	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, Leveling Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS032410JM-25B 25	510031329-53 Location: 4th Floor	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/05/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, Leveling Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 2

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032410JM-26A 26 Location: 4th Floor	510031329-54	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: White/Grey, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 1.2 %			
AS032410JM-26B 26 Location: 4th Floor	510031329-55	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: White/Grey, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 1 %			
AS032410JM-27A 27 Location: 4th Floor	510031329-56	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 1.6 %			
AS032410JM-27B 27 Location: 4th Floor	510031329-57	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 2 %			
AS032410JM-28A 28 Location: 4th Floor - Stairwell	510031329-58	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 1.7 %			
AS032410JM-28B 28 Location: 4th Floor - Stairwell	510031329-59	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 1.6 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 2

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032410JM-29A 29 Location: 4th Floor - Stairwell	510031329-60	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Mastic Asbestos Types: Other Material: Non-fibrous 35.6 %			
AS032410JM-29B 29 Location: 4th Floor - Stairwell	510031329-61	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Mastic Asbestos Types: Other Material: Non-fibrous 34.7 %			
AS032410JM-30A 30 Location: 3rd Floor	510031329-62	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 4.8 %			
AS032410JM-30B 30 Location: 3rd Floor	510031329-63	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 5 %			
AS032410JM-31A 31 Location: 4th Floor - Kitchen	510031329-64	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Blue/Grey/White, Homogeneous, Fibrous, Linoleum Flooring Asbestos Types: Other Material: Fibrous glass 1 %, Non-fibrous 12.8 %			
AS032410JM-31B 31 Location: 4th Floor - Kitchen	510031329-65	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Blue/Grey/White, Homogeneous, Fibrous, Linoleum Flooring Asbestos Types: Other Material: Fibrous glass 1 %, Non-fibrous 16.2 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 2

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032410JM-32A 32 Location: 4th Floor - Kitchen	510031329-66	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Linoleum Flooring Mastic Asbestos Types: Other Material: Non-fibrous 19 %			
AS032410JM-32B 32 Location: 4th Floor - Kitchen	510031329-67	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Linoleum Flooring Mastic Asbestos Types: Other Material: Non-fibrous 32.6 %			
AS032410JM-33A 33 Location: 3rd Floor	510031329-68	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 42.7 %			
AS032410JM-33B 33 Location: 3rd Floor	510031329-69	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 42.4 %			
AS032410JM-34A 34 Location: 4th Floor	510031329-70	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 41.2 %			
AS032410JM-34B 34 Location: 4th Floor	510031329-71	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 43.2 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 2

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032410JM-35A 35 Location: 3rd Floor	510031329-72	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 32.3 %			
AS032410JM-35B 35 Location: 3rd Floor	510031329-73	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 32.6 %			
AS032410JM-36A 36 Location: 3rd Floor	510031329-74	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 32.2 %			
AS032410JM-36B 36 Location: 3rd Floor	510031329-75	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 33.4 %			
AS032410JM-37A 37 Location: 3rd Floor	510031329-76	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 23.1 %			
AS032410JM-37B 37 Location: 3rd Floor	510031329-77	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 36.9 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 2

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032410JM-38A 38 Location: 3rd Floor	510031329-78	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 42.6 %			
AS032410JM-38B 38 Location: 3rd Floor	510031329-79	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 27.9 %			
AS032410JM-39A 39 Location: 4th Floor	510031329-80	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 55.6 %			
AS032410JM-39B 39 Location: 4th Floor	510031329-81	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 57.2 %			
AS032410JM-40A 40 Location: 4th Floor	510031329-82	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 66.5 %			
AS032410JM-40B 40 Location: 4th Floor	510031329-83	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 65 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 2

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032410JM-41A 41 Location: 3rd Floor	510031329-84	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Blue, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 1 %			
AS032410JM-41B 41 Location: 3rd Floor	510031329-85	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Blue, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 1.1 %			
AS032410JM-42A 42 Location: 3rd Floor	510031329-86	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 58.1 %			
AS032410JM-42B 42 Location: 3rd Floor	510031329-87	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 57.2 %			
AS032410JM-43A 43 Location: 3rd Floor	510031329-88	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Green, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 1.8 %			
AS032410JM-43B 43 Location: 3rd Floor	510031329-89	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Green, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 1.6 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 2

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032410JM-44A 44 Location: 3rd Floor	510031329-90	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 2.8 %			
AS032410JM-44B 44 Location: 3rd Floor	510031329-91	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 3.2 %			
AS032410JM-45A 45 Location: 3rd Floor - Kitchen	510031329-92	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 42.7 %			
AS032410JM-45B 45 Location: 3rd Floor - Kitchen	510031329-93	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 42.6 %			
AS032410JM-46A 46 Location: 3rd Floor - Kitchen	510031329-94	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 59.7 %			
AS032410JM-46B 46 Location: 3rd Floor - Kitchen	510031329-95	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 56.8 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 2

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032410JM-47A 47 Location: 3rd Floor	510031329-96	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 0.8 %			
AS032410JM-47B 47 Location: 3rd Floor	510031329-97	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 1 %			
AS032410JM-48A 48 Location: 3rd Floor	510031329-98	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 1 %			
AS032410JM-48B 48 Location: 3rd Floor	510031329-99	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 7.2 %			
AS032410JM-49A 49 Location: 3rd Floor	510031329-100	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 0.2 %			
AS032410JM-49B 49 Location: 3rd Floor	510031329-101	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 0.7 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 2

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032410JM-50A 50 Location: 3rd Floor	510031329-102	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 15 %			
AS032410JM-50B 50 Location: 3rd Floor	510031329-103	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/05/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 18.8 %			

Reporting Notes:Analyzed by: Ivan H Reyes ; Date Analyzed: 4/5/10

NAD = no asbestos detected; CVES = Calibrated Visual Estimate; NA = not analyzed; NA/PS = not analyzed / positive stop; "Present" or NVA = "No Visible Asbestos" are observations made during a qualitative analysis; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #102079-0) or NY ELAP PLM Analysis Protocol 198.1 for New York friable samples (198.6 for NOB samples) (NY ELAP Lab # 10982); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. NAD or Trace results by PLM are inconclusive, TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). NIST Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested.

Reviewed By: _____

Relinquished By:
 Received By:
 Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 463-3916

Fax: (518) 463-4773

Email: jmorey@cha-llp.com

Cell: (315) 440-1670

Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

All samples preceded by: (AS0324105m-)

Date/Time: 3/30/10
Date/Time:
Date/Time:
Date/Time: 7/21/10

Date/Time:

Project:

ACCA

SciLab #:

510031329

Project #: 16423

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

Field ID

Location

Sample Description
(for dusts - size of surface area sampled)

Homogenous Air
(HA #)

01A Cogging Stone Goot

01D Silvercoat

02A

02B

03A Built-up Roofing - Field - Bottom Layer

03B

03C

03D

03E

03F

03G

03H

04A Black Roof Patch - top layer

04B

05A

05B

Roof Flashing - Top - IMC

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle



[Signature]

Date/Time:
Date/Time:
Date/Time:

7/31/10
1015



AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.ORG

Project:

SciLab #:

510031329

Project #:

City: Albany

State: NY

Zip: 12206

Project Address:

Project Manager:

Phone: (518) 463-3916

Fax: (518) 463-4773

E-Mail: jmorey@cha-llp.com

Cell: (315) 440-1670

Analysis: ☐ PLM Only ☐ TEM Only ☐ NY ELAP PLM/TEM with NOB Prep.

☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe) ☐ Other (describe in comments)

Turnaround Time:

Material Type: ☐ Bulk ☐ Dust ☐

Secondary Fax #:

E-Mail Results: Yes

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID

Location

Sample Description
(for dust size of surface area sampled)

Homogenous Air
(HA #)

17 06
8 07
14 084
20 0815
21 094
22 096

Flashing - Bottom Layer
Top Layer
Gray Flashing Sealant
Pitch Pocket

Roof Level

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773


Email: jmorey@cha-llp.com

Cell: (518) 440-1670

Telephone/Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:



Date/Time:
Date/Time:
Date/Time:

3/21/01015

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (888) 724-5221
WWW.AMERISCI.COM

Project:

Scalps #:

510031329

Project Address:

Project #:

Project Manager:

Analysis: ☐ PLM Only ☐ TEM Only ☐ NY ELAP PLM/TEM with NOB Prep.

☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe)) Other (describe in comments)

E-Mail Results: Yes

Turnaround Time:

Material Type: ☐ Bulk ☐ Dust ☐

Sampled By:

Date Sampled:

Field ID

Location

Sample Description
(for dusts size of surface area sampled)

Homogenous Air
(HA #)

23 104

Exterior Window Gleazing Compound

24 1013

2x2 Ceiling Tile

3rd Fl.

25 11A

2x2 Ceiling Tile

4th Floor

26 11B

2x2 Ceiling Tile

4th Floor

27 12A

2x2 Ceiling Tile

2nd Floor

28 12B

2x4 Ceiling Tile

2nd Floor

29 13A

Sheetrock

3rd Fl.

30 13B

Sheetrock

3rd Fl.

31 14A

Sheetrock

4th Fl.

32 14B

Sheetrock

4th Fl.

33 15A

Joint Compound

4th Fl.

34 15B

Joint Compound

3rd Fl.

35 16A

Joint Compound

3rd Fl.

36 16B

Joint Compound

4th Fl.

37 17A

Joint Compound

4th Fl.

38 17B

Joint Compound

4th Fl.

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany

Phone: (518) 453-3915
Mail: jmorey@cha-llp.com

Telephone/Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205
Special Instructions or Comments:

Date/Time:

Date/Time:

Date/Time:

Date/Time:

Project:

SciLab #:

AMERISCI
BOSTON

AmeriSci Boston

8 School Street

Weymouth, MA 02189

Phone: (781) 337-9334

Fax: (781) 337-7642

TOLL FREE: (800) 724-5221

WWW.AMERISCI.COM

510031329

Project #:

State: NY

Zip: 12205

Fax: (518) 453-4773
Cell: (518) 440-1670

E-Mail Results: Yes

Turnaround Time:

Date Sampled:

Field ID

Location

Sample Description
(for dust- size of surface area sampled)

Homogenous Air
(HA #)

39- 18A
46- 18B
41- 19A
42- 19B
43- 20A
44- 20B
45- 21A
46- 21B
47- 22A
48- 22B
49- 23
50- 24A
51- 24B
52- 25A
53- 25B

TAPE Paper: Beneath Wood Floor

4th Floor

Sink Undercoating

4th Fl. Kitchen

Pipe Penetration GROUT

Basement

Mortar Rocks

4th Floor - Elec. Closet

1"x1" Gray Ceramic Tile

" " - Bath Room

GROUT to 1"x1" Gray Ceramic Tile

3rd Floor

Leveling Compound

4th Fl.

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773

Email: jmorey@cha-llp.com

Cell: (315) 440-1670

Telephone/Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

Date/Time:
Date/Time:
Date/Time:

Date/Time:

Project:

SciLab #:

510031329

Project Address:

Project #:

Project Manager:

Analysis: ☐ PLM Only ☐ TEM Only

☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe)

Turnaround Time:

Material Type:

☐ Bulk ☐ Dust

E-Mail Results: Yes

Sampled By:

Date Sampled:



AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

Field ID	Location	Sample Description (for dust - size of surface area sampled)	Homogenous Air (HA #)
24 26A	Light Gray 12X12 Floor Tile	4 th Fl.	
55 26B	"		
56 27A	Dark Gray 12X12 Floor Tile	↓	
57 27D	"		
58 28A	Gray 12X12 Floor Tile	4 th Fl. - Spinnell	
59 28D	"		
60 29A	Maskic to Gray 12X12 FT.	"	
61 29B	"		
62 30A	Beige 12X12 Floor Tile	3 rd Floor	
63 30B	"		
64 31A	Blue Unknown Flooring	4 th Fl. Kitchen	
65 31B	"		
66 32A	Master's bathroom Linoleum	"	
67 32B	"		
68 33A	Blue Carpet/Maskic	3 rd Fl.	
69 33B	"		

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773

Email: jmorey@cha-llp.com

Cell: (315) 440-1670

Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:



Date/Time:
Date/Time:
Date/Time:

Date/Time:

7/31/10
1015

Project:

Scal: #:

510031325



AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

- 76 34A
- 71 34B
- 22 35A
- 73 35B
- 74 36A
- 75 36B
- 76 37A
- 77 37B
- 78 38A
- 79 38B
- 80 39A
- 81 39B
- 82 40A
- 83 40B
- 84 41A
- 85 41B

Field ID

Location

Sample Description
(for dust - size of surface area sampled)

Homogenous Air
(HA #)

Gray Coagulated Plastic

4" Fl.

Brown Coagulated Plastic

3" Fl.

Light Blue Coagulated Plastic

"

Green Coagulated Plastic

3" Fl.

Blue Coagulated Plastic

"

TAN 4" Core Beams

4" Fl.

Mastic to TAN 4" Core

"

4" Blue Core Beams

3" Fl.

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany

Phone: (518) 453-3915

Email: jmorey@elcha-ill.com

Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

Date/Time:

Date/Time:

Date/Time:

Date/Time:

Project:

SciLab #:

510031329

Project Address:

Project #:

Project Manager:

Analysis: ☐ PLM Only

☐ TEM Only

☐ NY ELAP PLM/TEM with NOB Prep.

☐ ASTM Dust (microvac)

☐ ASTM Dust (Wipe)) Other (describe in comment)

E-Mail Results: Yes

Turnaround Time:

Material Type:

☐ Bulk ☐ Dust

Sampled By:

Date Sampled:

Location

Sample Description
(for dusts size of surface area sampled)

Homogenous Air
(HA #)

Field ID

86	424	Mastic to 4" Core Base	3rd FL	
87	420	"	"	
88	434	Green 4" Core Base	"	
89	436	"	"	
90	444	Mastic to 4" Core Base	"	
91	446	"	"	
92	454	TAN 4" Core Base	3rd FL - Kitchen	
93	458	"	"	
94	464	Mastic to 4" Core Base	"	
95	468	"	3rd FL	
96	474	4" Brown Core Base	"	
97	478	"	"	
98	484	Mastic to 4" Brown Core Base	"	
99	488	"	"	
100	494	4" Black Core Base	"	
101	496	"	"	

AMERI Sci
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
www.AmeriSci.com

Relinquished By:
Received By:
Relinquished By:

Date/Time:
Date/Time:
Date/Time:

3/31/10
Date/Time:

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (888) 724-5221
WWW.AMERISCI.COM

Received By:

CHIA

CITIA CHIA HARBOR & ASSOCIATES LLP

Company:

Project:

Scilab #:

510031329

Street Address: 3 Winners Circle

Project #:

City: Albany

State: NY

Zip: 12205

Project Manager:

Phone: (518) 453-3916

Fax: (518) 453-4773

Analysis: ☐ PLM Only ☐ TEM Only ☐ NY ELAP PLM/TEM with NOB Prep.

Email: jmorey@cha-llp.com

Cell: (315) 440-1670

☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe)) Other (describe in comments)

E-Mail Results: Yes

Turnaround Time:

Material Type: ☐ Bulk ☐ Dust ☐

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID

Location

Sample Description
(for dust- size of surface area sampled)

Homogenous Air
(HA #)

102 50A
109 50A

Mashed to 4" Black Core Bur

3" Fl.

Table I
Summary of Bulk Asbestos Analysis Results

16433; ACCA; Building 2

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
01	AS032410JM-01A	1	---	---	---	---	NAD	NA
Location: Roof Level								
02	AS032410JM-01B	1	---	---	---	---	NAD	NA
Location: Roof Level								
03	AS032410JM-02A	2	0.120	66.9	2.8	26.6	Chrysotile 3.7	NA
Location: Roof Level								
04	AS032410JM-02B	2	0.114	62.3	4.7	30.6	Chrysotile 2.3	NA
Location: Roof Level								
05	AS032410JM-03A	3	0.170	93.7	1.1	5.2	NAD	NAD
Location: Roof Level								
06	AS032410JM-03B	3	0.147	97.1	0.1	2.8	NAD	NAD
Location: Roof Level								
07	AS032410JM-03C	3	0.447	93.8	0.3	5.8	NAD	NAD
Location: Roof Level								
08	AS032410JM-03D	3	0.368	80.4	0.6	19.0	NAD	NAD
Location: Roof Level								
09	AS032410JM-03E	3	0.248	78.6	1.3	20.2	NAD	NAD
Location: Roof Level								
10	AS032410JM-03F	3	0.323	88.2	1.1	10.7	NAD	NAD
Location: Roof Level								
11	AS032410JM-03G	3	0.342	86.4	0.0	13.6	NAD	NAD
Location: Roof Level								
12	AS032410JM-03H	3	0.432	78.6	0.6	20.7	Chrysotile <0.25	Chrysotile Trace
Location: Roof Level								
13	AS032410JM-04A	4	0.247	65.2	11.0	18.5	Chrysotile 5.3	NA
Location: Roof Level								
14	AS032410JM-04B	4	0.344	74.7	9.6	12.6	Chrysotile 3.2	NA
Location: Roof Level								
15	AS032410JM-05A	5	0.102	93.6	0.0	6.4	NAD	NAD
Location: Roof Level								
16	AS032410JM-05B	5	0.177	97.4	0.6	2.0	NAD	NAD
Location: Roof Level								

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 2

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
17	AS032410JM-06		0.155	62.9	1.1	27.0	Chrysotile <0.25	Chrysotile 9.0
Location: Roof Level								
18	AS032410JM-07		0.363	73.7	2.6	20.9	Chrysotile 2.9	NA
Location: Roof Level								
19	AS032410JM-08A	8	0.434	62.7	7.0	19.3	Chrysotile 11.0	NA
Location: Roof Level								
20	AS032410JM-08B	8	0.267	66.8	5.5	16.7	Chrysotile 11.1	NA
Location: Roof Level								
21	AS032410JM-09A	9	0.279	74.0	11.8	14.1	Chrysotile <0.25	Chrysotile Trace
Location: Roof Level								
22	AS032410JM-09B	9	0.294	75.1	11.0	13.7	NAD	Chrysotile Trace
Location: Roof Level								
23	AS032410JM-10A	10	0.603	12.7	75.3	12.0	NAD	NAD
Location:								
24	AS032410JM-10B	10	0.485	12.6	81.9	5.3	NAD	Chrysotile Trace
Location:								
25	AS032410JM-11A	11	----	----	----	----	NAD	NA
Location: 3rd Floor								
26	AS032410JM-11B	11	----	----	----	----	NAD	NA
Location: 3rd Floor								
27	AS032410JM-12A	12	----	----	----	----	NAD	NA
Location: 4th Floor								
28	AS032410JM-12B	12	----	----	----	----	NAD	NA
Location: 4th Floor								
29	AS032410JM-13A	13	----	----	----	----	NAD	NA
Location: 2nd Floor								
30	AS032410JM-13B	13	----	----	----	----	NAD	NA
Location: 2nd Floor								
31	AS032410JM-14A	14	----	----	----	----	NAD	NA
Location: 3rd Floor								
32	AS032410JM-14B	14	----	----	----	----	NAD	NA
Location: 3rd Floor								

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 2

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
33	AS032410JM-15A	15	---	---	---	---	NAD	NA
Location: 4th Floor								
34	AS032410JM-15B	15	---	---	---	---	NAD	NA
Location: 4th Floor								
35	AS032410JM-16A	16	---	---	---	---	NAD	NA
Location: 3rd Floor								
36	AS032410JM-16B	16	---	---	---	---	NAD	NA
Location: 3rd Floor								
37	AS032410JM-17A	17	---	---	---	---	NAD	NA
Location: 4th Floor								
38	AS032410JM-17B	17	---	---	---	---	NAD	NA
Location: 4th Floor								
39	AS032410JM-18A	18	0.108	90.8	3.6	5.6	NAD	NAD
Location: 4th Floor								
40	AS032410JM-18B	18	0.088	92.6	2.2	5.2	NAD	NAD
Location: 4th Floor								
41	AS032410JM-19A	19	0.034	28.3	15.5	50.7	Chrysotile 5.6	NA
Location: 4th Floor Kitchen								
42	AS032410JM-19B	19	0.054	28.1	17.2	49.2	Chrysotile 5.5	NA
Location: 4th Floor Kitchen								
43	AS032410JM-20A	20	---	---	---	---	NAD	NA
Location: Basement								
44	AS032410JM-20B	20	---	---	---	---	NAD	NA
Location: Basement								
45	AS032410JM-21A	21	0.174	42.0	12.2	45.8	NAD	NAD
Location: 4th Floor - Elec Closet								
46	AS032410JM-21B	21	0.154	44.1	9.8	46.0	NAD	NAD
Location: 4th Floor - Elec Closet								
47	AS032410JM-22A	22	---	---	---	---	NAD	NA
Location: 4th Floor - Bathroom								
48	AS032410JM-22B	22	---	---	---	---	NAD	NA
Location: 4th Floor - Bathroom								

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 2

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
49	AS032410JM-23		---	----	----	----	NAD	NA
Location: 4th Floor - Bathroom								
50	AS032410JM-24A	24	----	----	----	----	NAD	NA
Location: 3rd Floor								
51	AS032410JM-24B	24	----	----	----	----	NAD	NA
Location: 3rd Floor								
52	AS032410JM-25A	25	----	----	----	----	NAD	NA
Location: 4th Floor								
53	AS032410JM-25B	25	----	----	----	----	NAD	NA
Location: 4th Floor								
54	AS032410JM-26A	26	0.330	15.1	83.7	1.2	NAD	NAD
Location: 4th Floor								
55	AS032410JM-26B	26	0.354	15.2	83.8	1.0	NAD	NAD
Location: 4th Floor								
56	AS032410JM-27A	27	0.326	17.5	80.9	1.6	NAD	NAD
Location: 4th Floor								
57	AS032410JM-27B	27	0.235	17.5	80.6	2.0	NAD	NAD
Location: 4th Floor								
58	AS032410JM-28A	28	0.287	18.2	80.1	1.7	NAD	NAD
Location: 4th Floor - Stairwell								
59	AS032410JM-28B	28	0.379	18.5	80.0	1.6	NAD	NAD
Location: 4th Floor - Stairwell								
60	AS032410JM-29A	29	0.150	40.0	24.5	35.6	NAD	NAD
Location: 4th Floor - Stairwell								
61	AS032410JM-29B	29	0.114	41.4	23.9	34.7	NAD	NAD
Location: 4th Floor - Stairwell								
62	AS032410JM-30A	30	0.362	15.5	79.7	4.8	NAD	NAD
Location: 3rd Floor								
63	AS032410JM-30B	30	0.340	16.0	79.0	5.0	NAD	NAD
Location: 3rd Floor								
64	AS032410JM-31A	31	0.233	45.6	40.6	13.8	NAD	NAD
Location: 4th Floor - Kitchen								

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 2

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
65 Location: 4th Floor - Kitchen	AS032410JM-31B	31	0.241	42.9	39.9	17.2	NAD	NAD
66 Location: 4th Floor - Kitchen	AS032410JM-32A	32	0.076	34.6	46.4	19.0	NAD	NAD
67 Location: 4th Floor - Kitchen	AS032410JM-32B	32	0.196	29.5	37.9	32.6	NAD	NAD
68 Location: 3rd Floor	AS032410JM-33A	33	0.151	55.1	2.1	42.7	NAD	NAD
69 Location: 3rd Floor	AS032410JM-33B	33	0.175	54.6	3.0	42.4	NAD	NAD
70 Location: 4th Floor	AS032410JM-34A	34	0.286	53.0	5.8	41.2	NAD	NAD
71 Location: 4th Floor	AS032410JM-34B	34	0.290	55.3	1.5	43.2	NAD	NAD
72 Location: 3rd Floor	AS032410JM-35A	35	0.301	37.2	30.5	32.3	NAD	NAD
73 Location: 3rd Floor	AS032410JM-35B	35	0.222	37.9	29.5	32.6	NAD	NAD
74 Location: 3rd Floor	AS032410JM-36A	36	0.241	34.5	33.2	32.2	NAD	NAD
75 Location: 3rd Floor	AS032410JM-36B	36	0.306	37.0	29.6	33.4	NAD	NAD
76 Location: 3rd Floor	AS032410JM-37A	37	0.302	40.6	36.3	23.1	NAD	NAD
77 Location: 3rd Floor	AS032410JM-37B	37	0.233	35.4	27.7	36.9	NAD	NAD
78 Location: 3rd Floor	AS032410JM-38A	38	0.185	31.6	25.8	42.6	NAD	NAD
79 Location: 3rd Floor	AS032410JM-38B	38	0.167	31.8	40.4	27.9	NAD	NAD
80 Location: 4th Floor	AS032410JM-39A	39	0.425	39.2	5.1	55.6	NAD	NAD

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 2

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
81 Location: 4th Floor	AS032410JM-39B	39	0.261	41.1	1.7	57.2	NAD	NAD
82 Location: 4th Floor	AS032410JM-40A	40	0.193	30.4	3.1	66.5	NAD	NAD
83 Location: 4th Floor	AS032410JM-40B	40	0.151	31.2	3.7	65.0	NAD	NAD
84 Location: 3rd Floor	AS032410JM-41A	41	0.216	53.4	45.7	1.0	NAD	NAD
85 Location: 3rd Floor	AS032410JM-41B	41	0.194	52.6	46.3	1.1	NAD	NAD
86 Location: 3rd Floor	AS032410JM-42A	42	0.097	34.0	7.9	58.1	NAD	NAD
87 Location: 3rd Floor	AS032410JM-42B	42	0.214	33.4	9.4	57.2	NAD	NAD
88 Location: 3rd Floor	AS032410JM-43A	43	0.195	48.8	49.4	1.8	NAD	NAD
89 Location: 3rd Floor	AS032410JM-43B	43	0.183	49.9	48.5	1.6	NAD	NAD
90 Location: 3rd Floor	AS032410JM-44A	44	0.146	43.3	53.9	2.8	NAD	NAD
91 Location: 3rd Floor	AS032410JM-44B	44	0.214	41.9	54.9	3.2	NAD	NAD
92 Location: 3rd Floor - Kitchen	AS032410JM-45A	45	0.134	54.3	3.0	42.7	NAD	NAD
93 Location: 3rd Floor - Kitchen	AS032410JM-45B	45	0.190	55.3	2.1	42.6	NAD	NAD
94 Location: 3rd Floor - Kitchen	AS032410JM-46A	46	0.195	37.6	2.7	59.7	NAD	NAD
95 Location: 3rd Floor - Kitchen	AS032410JM-46B	46	0.192	38.8	4.4	56.8	NAD	NAD
96 Location: 3rd Floor	AS032410JM-47A	47	0.271	48.2	51.0	0.8	NAD	NAD

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 2

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
97 Location: 3rd Floor	AS032410JM-47B	47	0.218	48.8	50.2	1.0	NAD	NAD
98 Location: 3rd Floor	AS032410JM-48A	48	0.153	53.0	46.0	1.0	NAD	NAD
99 Location: 3rd Floor	AS032410JM-48B	48	0.162	51.5	41.2	7.2	NAD	NAD
100 Location: 3rd Floor	AS032410JM-49A	49	0.867	14.9	85.0	0.2	NAD	NAD
101 Location: 3rd Floor	AS032410JM-49B	49	0.283	46.7	52.5	0.7	NAD	NAD
102 Location: 3rd Floor	AS032410JM-50A	50	0.145	45.7	39.3	15.0	NAD	NAD
103 Location: 3rd Floor	AS032410JM-50B	50	0.154	47.9	33.3	18.8	NAD	NAD

Reviewed by:

Date Reviewed:

Analyzed By: Sandhya Gunasekara

Date Analyzed: 4/8/2010

Semi-Quantitative Analysis: NAD = no asbestos detected; NA = not analyzed; NA/PS = not analyzed due to positive stop; Trace = <1%; PLM analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #102079-0) or NY ELAP 198.6 for New York NOB samples (NY ELAP Lab # 10982); TEM analysis by EPA 600/R-93/116 (not covered by NVLAP Bulk accreditation) or NY ELAP 198.4 for New York NOB samples (NY ELAP Lab # 10982);

** Warning Notes: Consider PLM fiber diameter limitation, only TEM will resolve fibers <0.25 micrometers in diameter. TEM bulk analysis is representative of the fine grained matrix material and may not be representative of non-uniformly dispersed debris, soils or other heterogeneous materials for which a combination PLM/TEM evaluation is recommended; Quantitation for beginning weights of <0.1 grams should be considered as qualitative only.

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12208

Phone: (518) 463-3915

Fax: (518) 453-4773

Cell: (315) 440-1670

E-Mail: jmorey@cha-llp.com

Site/Secondary Fax #:

Results to: Jim Morey

E-Mail Results: Yes

3 Winners Circle Albany, NY 12208

Special Instructions or Comments:

All Samples preceded by: (A5032405m-)

Date/Time: 3/30/10
Date/Time:
Date/Time:
Date/Time: 3/30/10



AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
www.AmeriSci.com

SciLab #:

Project:

ACCA

510031329

Project #:

16433

Project Address: Bldg. 2

Project Manager: Seth Fowler

Analysis: PLM Only

TEM Only

NY ELAP PLM/TEM with NOB Prep.

ASTM Dust (microvac)

ASTM Dust (Wipe)

Other (describe in comment)

Material Type: Bulk

Dust

Turnaround Time: 5-DAY

Material

Date Sampled:

3/24/10

Sampled By:

J. Morey

Homogenous Ar
(HA #)

Sample Description
(for dust= size of surface area sampled)

Location

Field ID

1 01A

2 01B

3 02A

4 02B

5 03A

6 03B

7 03C

8 03D

9 03E

10 03F

11 03G

12 03H

13 04A

14 04A

15 05A

16 05B

Coping Stone Groat

Silvercoat

Built-up Roofing - Field - Bottom Layer

7th

6th

5th

4th

3rd

2nd Layer

top layer

Black Roof Patch

Root Flashing - Top - TAR

Bottom

Relinquished By:

Received By:

Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jmorey@cha-llp.com

Cell: (315) 440-1670

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Results to: Jim Morey

3 Winners Circle Albany, NY 12205

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID

Location

Sample Description
(for dust= size of surface area sampled)

Homogenous Air
(HA #)

17 06

18 07

19 08A

20 08B

21 09A

22 09B

Flashing - Bottom Layer

- Top Layer

Gray Flashing Sealant

Pitch Pocket

Foot Level

"

"

"

"

"

Date/Time:

Date/Time:

Date/Time:

Date/Time:

Project:

SCILAS #:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jmorey@cha-llp.com

Cell: (315) 440-1670

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Results to: Jim Morey

3 Winners Circle Albany, NY 12205

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID

Location

Sample Description
(for dust= size of surface area sampled)

Homogenous Air
(HA #)

17 06

18 07

19 08A

20 08B

21 09A

22 09B

Flashing - Bottom Layer

- Top Layer

Gray Flashing Sealant

Pitch Pocket

Foot Level

"

"

"

"

"

Date/Time:

Date/Time:

Date/Time:

Date/Time:

Project:

SCILAS #:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jmorey@cha-llp.com

Cell: (315) 440-1670

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Results to: Jim Morey

3 Winners Circle Albany, NY 12205

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID

Location

Sample Description
(for dust= size of surface area sampled)

Homogenous Air
(HA #)

17 06

18 07

19 08A

20 08B

21 09A

22 09B

Flashing - Bottom Layer

- Top Layer

Gray Flashing Sealant

Pitch Pocket

Foot Level

"

"

"

"

"

Date/Time:

Date/Time:

Date/Time:

Date/Time:

Project:

SCILAS #:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jmorey@cha-llp.com

Cell: (315) 440-1670

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Results to: Jim Morey

3 Winners Circle Albany, NY 12205

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID

Location

Sample Description
(for dust= size of surface area sampled)

Homogenous Air
(HA #)

17 06

18 07

19 08A

20 08B

21 09A

22 09B

Flashing - Bottom Layer

- Top Layer

Gray Flashing Sealant

Pitch Pocket

Foot Level

"

"

"

"

"

Date/Time:

Date/Time:

Date/Time:

Date/Time:

Project:

SCILAS #:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jmorey@cha-llp.com

Cell: (315) 440-1670

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Results to: Jim Morey

3 Winners Circle Albany, NY 12205

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID

Location

Sample Description
(for dust= size of surface area sampled)

Homogenous Air
(HA #)

17 06

18 07

19 08A

20 08B

21 09A

22 09B

Flashing - Bottom Layer

- Top Layer

Gray Flashing Sealant

Pitch Pocket

Foot Level

"

"

"

"

"

Date/Time:

Date/Time:

Date/Time:

Date/Time:

Project:

SCILAS #:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jmorey@cha-llp.com

Cell: (315) 440-1670

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Results to: Jim Morey

3 Winners Circle Albany, NY 12205

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID

Location

Sample Description
(for dust= size of surface area sampled)

Homogenous Air
(HA #)

17 06

18 07

19 08A

20 08B

21 09A

22 09B

Flashing - Bottom Layer

- Top Layer

Gray Flashing Sealant

Pitch Pocket

Foot Level

"

"

"

"

"

Date/Time:

Date/Time:

Date/Time:

Date/Time:

Project:

SCILAS #:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jmorey@cha-llp.com

Cell: (315) 440-1670

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Results to: Jim Morey

3 Winners Circle Albany, NY 12205

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID

Location

Sample Description
(for dust= size of surface area sampled)

Homogenous Air
(HA #)

17 06

18 07

19 08A

20 08B

21 09A

22 09B

Flashing - Bottom Layer

- Top Layer

Gray Flashing Sealant

Pitch Pocket

Foot Level

"

"

"

"

"

Date/Time:

Date/Time:

Date/Time:

Date/Time:

Project:

SCILAS #:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jmorey@cha-llp.com

Cell: (315) 440-1670

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Results to: Jim Morey

3 Winners Circle Albany, NY 12205

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID

Location

<

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12205
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670

Site/Secondary Fax #: E-Mail Results: Yes
Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

Field ID

Location

Sample Description
(for dust= size of surface area sampled)

Homogenous Air
(HA #)

23 10A
24 10B
25 11A
26 11B
27 12A
28 12B
29 13A
30 13B
31 14A
32 14B
33 15A
34 15B
35 16A
36 16B
37 17A
38 17B

Exterior Window Glazing Compound

2x2 ceiling Tile

2x2 ceiling Tile

2x4 ceiling Tile

Sheetrock

Joint Compound

3rd Fl.

4th Floor

2nd Floor

3rd Fl.

3rd Fl.

4th Fl.

4th Fl.

3rd Fl.

3rd Fl.

4th Fl.

4th Fl.

Date/Time:
Date/Time:
Date/Time:
Date/Time:

Project:

SciLab #:

Project #:

Project Address:

Project Manager:

Analysis: PLM Only TEM Only NY ELAP PLM/TEM with NOB Prep.
ASTM Dust (microvac) ASTM Dust (Wipe) Other (describe in comment:
Material Type: Bulk Dust

Turnaround Time:

Sampled By: Date Sampled:

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (888) 724-5221
WWW.AMERISCI.COM

CHA
CHACH NARBON & ASSOCIATES LLP

510031329

PAGE

3

OF

8

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12205
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670

Site/Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

Date/Time:
Date/Time:
Date/Time:
Date/Time:

Project:

Project Address:

Project Manager:

Analysis: PLM Only TEM Only NY ELAP PLM/TEM with NOB Prep.

ASTM Dust (microvac) ASTM Dust (Wipe) Other (describe in comment)

Turnaround Time:

Sampled By:

Date Sampled:

Material Type: Bulk Dust



AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

SCILAB #:

510031329

Project #:

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Ar (HA #)
44-18A	TAR Paper Beneath Wood Floor	4th Floor	
46-18B	"	"	
41-19A	Sink Undercoating	4th Fl. Kitchen	
42-19B	"	"	
43-20A	Pipe Penetration GROUT	Basement	
44-20B	"	"	
45-21A	Mastic Pockets	4th Floor - Elec. Closet	
46-21B	"	"	
47-22A	1"x1" Gray Ceramic Tile	" - Bathroom	
48-22B	"	"	
49-23	GROUT to 1"x1" Gray Ceramic Tile	"	
50-24A	Leveling Compound	3rd Floor	
51-24B	"	"	
52-25A	"	4th Fl.	
53-25B	"	"	

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12205
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670

Site/Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

Date/Time:
Date/Time:
Date/Time:
Date/Time:

Project:

Project Address:

SciLab #:



CHALCH HARBOR & ASSOCIATES LLP

Project Manager:

Project #:

Analysis: ☐ PLM Only ☐ TEM Only ☐ NY ELAP PLM/TEM with NOB Prep.
☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe) ☐ Other (describe in comments)

Turnaround Time:

Material Type: ☐ Bulk ☐ Dust

Date Sampled:

Sampled By:

Field ID

Location

Sample Description
(for dust= size of surface area sampled)

Homogenous Air
(HA #)

54 26A
55 26B
56 27A
57 27D
58 28A
59 28D
60 29A
61 29B
62 30A
63 30B
64 31A
65 31B
66 32A
67 32B
68 33A
69 33B

Light Gray 12X12 Floor Tile
" "
Dark Gray 12X12 Floor Tile
" "
Gray 12X12 Floor Tile
" "
Mastic to Gray 12X12 PT.
" "
Beige 12X12 Floor Tile
" "
Blue linoleum Flooring
" "
Mastic beneath linoleum
" "
Blue Carpet Mastic
" "

4th Fl.
↓
4th Fl. - Stairwell
" "
" "
3rd Floor
" "
4th Fl. Kitchen
" "
" "
" "
3rd Fl.
" "

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12205
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: imorey@cha-llp.com Cell: (315) 440-1670

Site/Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

Date/Time:
Date/Time:
Date/Time:
Date/Time:

Project:

Project Address:

Project Manager:

Analysis: PLM Only TEM Only NY ELAP PLM/TEM with NOB Prep.

ASTM Dust (microvac) ASTM Dust (Wipe) Other (describe in comments)

Turnaround Time:

Sampled By:

Date Sampled:

Field ID

Location

Sample Description

(for dust= size of surface area sampled)

Homogenous Air (HA #)

76 34A
71 34B
72 35A
73 35B
74 36A
75 36B
76 37A
77 37B
78 38A
79 38D
80 39A
81 39B
82 40A
83 40B
84 41A
85 41D

Gray Carpet Mastic

Brown Carpet Mastic

Light Blue Carpet Mastic

Green Carpet Mastic

Blue Carpet Mastic

TAN 4" Cove Base

Mastic to TAN 4" Cove

4" Blue Cove Base

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

AMERISCI
BOSTON

SCILAS #:

510031329

Project #:

PAGE

OF

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12205
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670

Site/Secondary Fax #: E-Mail Results: Yes
Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:



AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

SciLab #:

Project:



510031329

Project Address:

Project #:

Project Manager:

Analysis: PLM Only TEM Only NY ELAP PLM/TEM with NOB Prep.
ASTM Dust (microvac) ASTM Dust (Wipe) Other (describe in comment)

Turnaround Time:

Material Type: Bulk Dust

Sampled By: Date Sampled:

Field ID	Location	Sample Description (for dusts size of surface area sampled)	Homogenous Ar (HA #)
86 42A	Mastic to 4" Blue Cove Base	3rd Fl.	
87 42D	"	"	
88 43A	Green 4" Cove Base	"	
89 43B	"	"	
90 44A	Mastic to 4" Cove Base	"	
91 44B	"	"	
92 45A	TAN 4" Cove Base	3rd Fl. - Kitchen	
93 45B	"	"	
94 46A	Mastic to 4" Cove Base	"	
95 46B	"	"	
96 47A	4" Brown Cove Base	3rd Fl.	
97 47B	"	"	
98 48A	Mastic to 4" Brown Cove Base	"	
99 48B	"	"	
100 49A	4" Black Cove Base	"	
101 49B	"	"	

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Treat Address: 3 Winners Circle

City: Albany State: NY Zip: 12205
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@ccha-llp.com Cell: (315) 440-1670

Site/Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

Field ID

Location

Sample Description

(for dust= size of surface area sampled)

Homogenous Air
(HA #)

102 50A
109 50A

Mastic to 4" Black Cove Bush

3rd Fl.

Date/Time:
Date/Time:
Date/Time:
Date/Time:

Project:

Project Address:

Project Manager:

Analysis: PLM Only TEM Only NY ELAP PLM/TEM with NOB Prep.

ASTM Dust (microvac) ASTM Dust (Wipe) Other (describe in comment)

Material Type: Bulk Dust

Turnaround Time:

Sampled By:

Date Sampled:



AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

Project: 510031329



CITACON HARBOR & ASSOCIATES LLP

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 3

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
01	01A	1	---	---	---	---	NAD	NA
Location: Penthouse								
02	01B	1	---	---	---	---	NAD	NA
Location: Penthouse								
03	01C	1	---	---	---	---	NAD	NA
Location: 1st Floor - Behind PM Office								
04	01D	1	---	---	---	---	NAD	NA
Location: 1st Floor - Behind PM Office								
05	01E	1	---	---	---	---	NAD	NA
Location: 2nd Floor - Mech Room								
06	01F	1	---	---	---	---	NAD	NA
Location: 2nd Floor - Mech Room								
07	02A	2	---	---	---	---	NAD	NA
Location: Penthouse								
08	02B	2	---	---	---	---	NAD	NA
Location: Penthouse								
09	02C	2	---	---	---	---	NAD	NA
Location: 1st Floor - Behind PM Office								
10	02D	2	---	---	---	---	NAD	NA
Location: 1st Floor - Behind PM Office								
11	02E	2	---	---	---	---	NAD	NA
Location: 2nd Floor - Mech Room								
12	02F	2	---	---	---	---	NAD	NA
Location: 2nd Floor - Mech Room								
13	03A	3	---	---	---	---	NAD	NA
Location: 2nd Floor - Mech Room								
14	03B	3	---	---	---	---	NAD	NA
Location: 1st Floor - Behind PM Room								
15	04A	4	0.041	38.5	25.7	35.8	NAD	NAD
Location: 4th Floor - Kitchen								
16	04B	4	0.059	37.7	27.3	35.0	NAD	NAD
Location: 4th Floor - Kitchen								

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 3

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
17	05A	5	-----	-----	-----	-----	NAD	NA
Location: Penthouse								
18	05B	5	-----	-----	-----	-----	NAD	NA
Location: Penthouse								
19	06A	6	-----	-----	-----	-----	NAD	NA
Location: 3rd Floor (Mercer)								
20	06B	6	-----	-----	-----	-----	NAD	NA
Location: 3rd Floor (Mercer)								
21	07A	7	0.186	19.7	47.0	33.3	NAD	NAD
Location: Penthouse								
22	07B	7	0.158	24.2	40.1	35.7	NAD	NAD
Location: Penthouse								
23	07C	7	0.176	26.8	35.7	37.5	NAD	NAD
Location: Penthouse								
24	07D	7	0.174	26.5	33.7	39.7	NAD	NAD
Location: Penthouse								
25	07E	7	0.200	27.1	33.1	39.8	NAD	NAD
Location: Penthouse								
26	08		-----	-----	-----	-----	NAD	NA
Location: Vestibule								
27	09		-----	-----	-----	-----	NAD	NA
Location: Vestibule								
28	10A	10	0.178	74.1	12.6	13.3	NAD	NAD
Location: Elect Room - 1st Floor								
29	10B	10	0.221	75.0	12.0	13.0	NAD	NAD
Location: Elect Room - 1st Floor								
30	11A	11	-----	-----	-----	-----	NAD	NA
Location: Bathroom								
31	11B	11	-----	-----	-----	-----	NAD	NA
Location: Bathroom								
32	12A	12	-----	-----	-----	-----	NAD	NA
Location: Bathroom								

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 3

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
33	12B	12	---	---	---	---	NAD	NA
Location: Bathroom								
34	13A	13	---	---	---	---	NAD	NA
Location: Penthouse								
35	13B	13	---	---	---	---	NAD	NA
Location: Penthouse								
36	14A	14	---	---	---	---	NAD	NA
Location: 3rd Floor Storage Room								
37	14B	14	---	---	---	---	NAD	NA
Location: 3rd Floor Storage Room								
38	15A	15	0.202	62.5	36.5	1.0	NAD	NAD
Location: 1st Floor Bathroom								
39	15B	15	0.227	60.0	34.3	5.7	NAD	NAD
Location: 3rd Floor Storage Room								
40	16A	16	0.097	83.4	12.4	4.1	NAD	NAD
Location: 3rd Floor - Group								
41	16B	16	0.149	82.7	12.1	5.2	NAD	NAD
Location: 3rd Floor - Group								
42	17A	17	0.137	76.2	11.9	11.9	NAD	NAD
Location: 1st Floor - Wellcare								
43	17B	17	0.094	48.3	9.3	42.4	NAD	NAD
Location: 1st Floor - Wellcare								
44	18A	18	0.084	68.0	4.4	27.6	NAD	NAD
Location: 4th Floor								
45	18B	18	0.089	67.7	6.4	25.9	NAD	NAD
Location: 4th Floor								
46	19A	19	0.290	53.9	5.5	40.7	NAD	NAD
Location: Penthouse								
47	19B	19	0.177	51.7	14.4	33.9	NAD	NAD
Location: Penthouse								
48	20A	20	0.321	35.7	58.3	5.9	NAD	NAD
Location: 3rd Floor								

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 3

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
49	20B	20	0.287	34.1	60.2	5.7	NAD	NAD
Location: 3rd Floor								
50	21A	21	0.292	18.7	51.1	30.2	NAD	NAD
Location: 3rd Floor								
51	21B	21	0.196	32.4	36.5	31.1	NAD	NAD
Location: 3rd Floor								
52	22A	22	0.470	16.6	41.5	41.9	NAD	NAD
Location: 3rd Floor								
53	22B	22	0.454	17.2	55.7	27.1	NAD	NAD
Location: 3rd Floor								
54	23A	23	0.198	52.6	20.7	26.8	NAD	NAD
Location: 1st Floor								
55	23B	23	0.276	56.2	8.5	35.4	NAD	NAD
Location: 1st Floor								
56	24A	24	0.134	43.3	9.5	47.2	NAD	NAD
Location: 1st Floor								
57	24B	24	0.118	59.5	8.1	32.3	NAD	NAD
Location: 1st Floor								
58	25A	25	0.117	58.3	8.1	33.6	NAD	NAD
Location: 1st Floor								
59	25B	25	0.193	58.2	7.6	34.2	NAD	NAD
Location: 1st Floor								
60	26A	26	0.311	19.2	76.5	4.3	NAD	NAD
Location: 4th Floor								
61	26B	26	0.246	19.0	76.8	4.2	NAD	NAD
Location: 4th Floor								
62	27A	27	0.340	27.4	60.2	10.9	Chrysotile 1.5	NA
Location: 4th Floor								
63	27B	27	0.198	28.4	60.8	10.9	NA/PS	NA
Location: 4th Floor								
64	28A	28	0.078	55.7	21.5	19.3	Chrysotile 3.5	NA
Location: 4th Floor								

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 3

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
65	28B	28	0.169	48.5	16.7	34.8	NA/PS	NA
Location: 4th Floor								
66	29A	29	0.205	15.8	81.1	3.1	NAD	NAD
Location: 1st Floor								
67	29B	29	0.262	15.9	80.9	3.2	NAD	NAD
Location: 1st Floor								
68	30A	30	0.205	21.9	44.7	33.4	NAD	NAD
Location: 3rd Floor								
69	30B	30	0.319	21.6	43.3	35.1	NAD	NAD
Location: 3rd Floor								
70	31A	31	0.325	20.0	72.4	7.6	NAD	NAD
Location: 3rd Floor								
71	31B	31	0.286	20.3	73.3	6.4	NAD	NAD
Location: 3rd Floor								
72	32		0.151	42.7	18.3	39.0	NAD	NAD
Location: 3rd Floor								
73	33A	33	0.259	14.2	85.7	0.1	NAD	NAD
Location: 3rd Floor								
74	33B	33	0.236	14.9	85.0	0.1	NAD	NAD
Location: 3rd Floor								
75	34A	34	0.192	15.2	84.3	0.4	NAD	NAD
Location: 1st Floor								
76	34B	34	0.262	14.6	85.2	0.2	NAD	NAD
Location: 1st Floor								
77	35		0.057	51.2	9.5	39.3	NAD	NAD
Location: 1st Floor								
78	36A	36	0.243	45.3	48.9	5.8	NAD	NAD
Location: 1st Floor								
79	36B	36	0.453	46.5	48.3	5.2	NAD	NAD
Location: 1st Floor								
80	37A	37	0.229	62.3	30.7	7.0	NAD	NAD
Location: 1st Floor								

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 3

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
81 Location: 1st Floor	37B	37	0.173	60.1	39.5	0.3	NAD	NAD
82 Location: 1st Floor	38		0.074	49.3	17.0	33.7	NAD	NAD
83 Location: Penthouse	39A	39	0.183	36.5	63.4	0.1	NAD	NAD
84 Location: Penthouse	39B	39	0.189	44.9	55.0	0.1	NAD	NAD
85 Location: Penthouse	40A	40	0.268	42.4	30.2	27.4	NAD	NAD
86 Location: Penthouse	40B	40	0.167	43.8	38.4	17.8	NAD	NAD
87 Location: 4th Floor	41A	41	0.216	53.0	46.9	0.1	NAD	NAD
88 Location: 4th Floor	41B	41	0.213	51.5	48.4	0.1	NAD	NAD
89 Location: 4th Floor	42A	42	0.091	45.4	50.4	4.2	NAD	NAD
90 Location: 4th Floor	42B	42	0.396	37.9	62.0	0.1	NAD	NAD
91 Location: 3rd Floor	43A	43	0.241	44.5	53.2	2.3	NAD	NAD
92 Location: 3rd Floor	43B	43	0.172	41.9	57.5	0.6	NAD	NAD
93 Location: 3rd Floor	44A	44	0.274	50.2	8.3	41.5	NAD	NAD
94 Location: 3rd Floor	44B	44	0.205	48.2	10.4	41.4	NAD	NAD
95 Location: 1st Floor Corridor	45A	45	0.269	51.4	47.8	0.8	NAD	NAD
96 Location: 1st Floor Corridor	45B	45	0.215	51.5	47.7	0.8	NAD	NAD

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 3

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
97	46A	46	0.160	45.5	54.4	0.1	NAD	NAD
Location: 1st Floor Corridor								
98	46B	46	0.143	45.4	53.9	0.8	NAD	NAD
Location: 1st Floor Corridor								
99	47A	47	0.157	56.2	43.8	0.1	NAD	NAD
Location: 1st Floor								
100	47B	47	0.172	56.8	43.1	0.1	NAD	NAD
Location: 1st Floor								
101	48A	48	0.124	46.3	46.9	6.8	NAD	NAD
Location: 1st Floor								
102	48B	48	0.094	46.2	49.2	4.6	NAD	NAD
Location: 1st Floor								
103	49A	49	0.171	29.6	70.2	0.1	NAD	NAD
Location: AHU Room - 1st Floor								
104	49B	49	0.157	30.5	69.4	0.1	NAD	NAD
Location: AHU Room - 1st Floor								
105	50		0.251	95.4	4.5	0.1	NAD	NAD
Location: AHU Room - 1st Floor								
106	51A	51	0.178	45.9	53.5	0.7	NAD	NAD
Location: 2nd Floor Kitchen								
107	51B	51	0.206	46.4	52.9	0.6	NAD	NAD
Location: 2nd Floor Kitchen								
108	52A	52	0.175	34.4	58.7	6.9	NAD	NAD
Location: 2nd Floor Kitchen								
109	52B	52	0.121	41.4	54.2	4.5	NAD	NAD
Location: 2nd Floor Kitchen								
110	53A	53	0.359	19.3	77.3	3.4	NAD	NAD
Location: 2nd Floor Kitchen								
111	53B	53	0.267	19.2	77.2	3.6	NAD	NAD
Location: 2nd Floor Kitchen								
112	54A	54	0.470	35.0	17.8	42.6	Chrysotile 4.7 Anthophyllite <1	NA
Location: Exterior - Roof								

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 3

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
113	54B	54	0.658	38.1	15.1	41.0	Chrysotile 5.7	NA
Location: Exterior - Roof							Anthrophyllite <1	
114	55A	55	0.275	55.9	31.4	12.7	NAD	NAD
Location: Low Roof								
115	55B	55	0.309	59.5	30.1	10.4	NAD	NAD
Location: Low Roof								
116	56A	56	0.178	59.4	20.8	16.8	Chrysotile 3.0	NA
Location: Low Roof								
117	56B	56	0.184	62.1	25.3	12.6	NA/PS	NA
Location: Low Roof								
118	57A	57	0.335	55.8	3.6	40.5	Chrysotile <0.25	Chrysotile Trace
Location: Roof #1								
119	57B	57	0.213	98.0	1.8	0.2	NAD	NAD
Location: Roof #1								
120	57C	57	0.149	76.3	2.8	20.8	NAD	NAD
Location: Roof #1								
121	57D	57	0.282	85.0	2.2	12.2	NAD	Chrysotile 0.64
Location: Roof #1								
122	58A	58	0.366	88.5	2.0	9.4	NAD	Chrysotile Trace
Location: Roof #2								
123	58B	58	0.160	88.0	2.2	9.8	NAD	NAD
Location: Roof #2								
124	58C	58	0.087	65.9	4.3	29.8	NAD	NAD
Location: Roof #2								
125	59A	59	0.512	89.6	1.6	8.7	NAD	Chrysotile Trace
Location: Roof #2								
126	59B	59	0.595	91.9	0.7	7.3	NAD	Chrysotile Trace
Location: Roof #2								
127	60A	60	0.469	83.6	2.0	14.3	Chrysotile <0.25	NA
Location: Penthouse Roof								
128	60B	60	0.397	75.9	5.7	11.0	Chrysotile 7.4	NA
Location: Penthouse Roof								

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 3

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
129	61A	61	0.107	91.0	8.8	0.2	NA	NA
Location:	Penthouse Roof							
130	61B	61	0.485	78.3	9.7	12.0	NA	NA
Location:	Penthouse Roof							
131	61C	61	0.650	76.8	9.3	13.9	NA	NA
Location:	Penthouse Roof							
132	62		0.564	83.1	1.7	12.2	Chrysotile <0.25	Chrysotile 3.04
Location:	Small Roof -Penthouse Roof							
133	63		0.958	87.5	4.5	7.6	NAD	Chrysotile 0.4
Location:	Small Roof -Penthouse Roof							
134	64		0.748	69.0	22.6	6.6	Chrysotile 1.9	NA
Location:	Small Roof -Penthouse Roof							

Reviewed by: _____ Date Reviewed: _____ Analyzed By: Bryan H. Clark *Bryan Clark* Date Analyzed: 4/14/10

Semi-Quantitative Analysis: NAD = no asbestos detected; NA = not analyzed; NAY/PS = not analyzed due to positive stop; Trace/± <1%;
 PLM analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #102079-0) or NY ELAP 198.6 for New York NOB samples (NY ELAP Lab # 10982);
 TEM analysis by EPA 600/R-93/116 (not covered by NVLAP Bulk accreditation) or NY ELAP 198.4 for New York NOB samples (NY ELAP Lab # 10982);

** Warning Notes: Consider PLM fiber diameter limitation, only TEM will resolve fibers <0.25 micrometers in diameter. TEM bulk analysis is representative of the fine grained matrix material and may not be representative of non-uniformly dispersed debris, soils or other heterogeneous materials for which a combination PLM/TEM evaluation is recommended; Quantitation for beginning weights of <0.1 grams should be considered as qualitative only.

Relinquished By:
Received By:
Relinquished By:
Received By:

Date/Time: 03/31/00
Date/Time:
Date/Time:
Date/Time:

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (888) 724-5221
WWW.AMERISCI.COM

CHA
CHALLENGE HARDWARE & ASSOCIATES, LLC

Scalac #:

Project: ACCA

510041083

Company:

Street Address: 3 Winners Circle

Project #: 16433

City: Albany State: NY Zip: 12205

Phone: (518) 453-3915 Fax: (518) 453-4773

E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670

Project Address: Bldg. 3
Project Manager: S.M. Fowler

Analysis: PLM Only TEM Only NY ELAP PLM/TEM with NOB Prep.

ASTM Dust (microvac) ASTM Dust (Wipe) Other (describe in comments)

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time: 5-DAY

Material Type: Bulk Dust

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Sampled By: J. Morey

Date Sampled: 03/26/00

Special Instructions or Comments:

Field ID	Location	Sample Description (for dusts size of surface area sampled)	Homogenous Air (HA #)
1 - 01A	Sheetrock	Penthouse	
2 - 01B	Sheetrock	"	
3 - 01C	Sheetrock	1 st Fl. - Behind P.M.'s office	
4 - 01D	Sheetrock	2 nd Floor - Mech. Rm.	
5 - 01E	Sheetrock	"	
6 - 01F	Paint Compartment	Penthouse	
7 - 02A	"	"	
8 - 02B	"	1 st Fl. - Behind PM's office	
9 - 02C	"	"	
10 - 02D	"	2 nd Floor - Mech. Rm.	
11 - 02E	"	"	
12 - 02F	"	"	
13 - 03A	Sheetrock Tape	2 nd Floor - Mech. Rm.	
14 - 03B	"	1 st Fl. - Behind PM's Rm.	
15 - 04A	Sink Undercoating	4 th Floor - Kitchen	
16 - 04B	"	"	

Postives stop
↓

Relinquished By:

Received By:

Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jmorey@clach-nb.com

Cell: (315) 440-1670

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Material Type: Bulk Dust

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID

Location

Sample Description
(for dust size of surface area sampled)

Homogenous Air
(HA #)

17 05A

Fiberboard

Penthouse

18 05B

2x2 ceiling Tile

3rd Floor (Mercer)

19 06A

Textured Wall Paint

~~Penthouse~~ Penthouse

20 06B

"

"

21 07A

"

"

22 07B

"

"

23 07C

"

"

24 07D

"

"

25 07E

1X1' Ceramic Floor Tile

Vestibule

26 08

GROUT to 1X1' Ceramic Floor Tile

"

27 09

GROUT @ Penetrations

Elect. Run - 1st Fl.

28 10A

"

"

29 10B

2"x2" Gray Ceramic Floor Tile

Bathroom

30 11A

"

"

31 40011B

Date/Time:

Date/Time:

Date/Time:

Date/Time:

Project:

SCLAS #:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jmorey@clach-nb.com

Cell: (315) 440-1670

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Material Type: Bulk Dust

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID

Location

Sample Description
(for dust size of surface area sampled)

Homogenous Air
(HA #)

17 05A

Fiberboard

Penthouse

18 05B

2x2 ceiling Tile

3rd Floor (Mercer)

19 06A

Textured Wall Paint

~~Penthouse~~ Penthouse

20 06B

"

"

21 07A

"

"

22 07B

"

"

23 07C

"

"

24 07D

"

"

25 07E

1X1' Ceramic Floor Tile

Vestibule

26 08

GROUT to 1X1' Ceramic Floor Tile

"

27 09

GROUT @ Penetrations

Elect. Run - 1st Fl.

28 10A

"

"

29 10B

2"x2" Gray Ceramic Floor Tile

Bathroom

30 11A

"

"

31 40011B

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (888) 724-5221
WWW.AMERISCI.COM

SCLAS #:

510041083

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jmorey@clach-nb.com

Cell: (315) 440-1670

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Material Type: Bulk Dust

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID

Location

Sample Description
(for dust size of surface area sampled)

Homogenous Air
(HA #)

17 05A

Fiberboard

Penthouse

18 05B

2x2 ceiling Tile

3rd Floor (Mercer)

19 06A

Textured Wall Paint

~~Penthouse~~ Penthouse

20 06B

"

"

21 07A

"

"

22 07B

"

"

23 07C

"

"

24 07D

"

"

25 07E

1X1' Ceramic Floor Tile

Vestibule

26 08

GROUT to 1X1' Ceramic Floor Tile

"

27 09

GROUT @ Penetrations

Elect. Run - 1st Fl.

28 10A

"

"

29 10B

2"x2" Gray Ceramic Floor Tile

Bathroom

30 11A

"

"


31 40011B

Relinquished By:

Received By:

Relinquished By:

Received By:



CHA
CLIA-CH HARBOR & ASSOCIATES LLP

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12205

Phone: (518) 453-3915 Fax: (518) 453-4773

E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670

Site/Secondary Fax #:

E-Mail Results: Yes

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

Date/Time:

Date/Time:

Date/Time:

Date/Time:

Project:

Scilas #:

510041083

Project Address:

Project Manager:

Analysis: ☐ PLM Only ☐ TEM Only ☐ NY ELAP PLM/TEM with NOB Prep.

☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe) ☐ Other (describe in comments)

Turnaround Time:

Material Type: ☐ Bulk ☐ Dust

Sampled By:

Date Sampled:

Field ID

Location

Sample Description
(for dust= size of surface area sampled)

Homogenous Air
(HA #)

42-12A

GROUT to 2"x2" Ceramic Tiles

Bathroom

43-12B

"

44-13A

Marble Floor Grout

Penthouse

45-13B

"

46-14A

Leveling Compound

3rd Fl. Storage Rm.

47-14B

"

48-15A

White Linoleum

11th Fl. Bathroom

Positive Stop

49-15B

"

Positive Stop

40-16A

TAN Linoleum

14th Fl. - Group

Positive Stop

41-16B

"

Positive Stop

42-17A

Light TAN Linoleum

15th Fl. - Wellcare

Positive Stop

43-17B

"

Positive Stop

44-18A

Red Carpet Mastic

14th Fl.

Positive Stop

45-18B

"

Positive Stop

46-19A

Blue Carpet Mastic

Penthouse

Positive Stop

47-19B

"

Positive Stop

Relinquished By:
Received By:
Relinquished By:

Received By:

Date/Time:
Date/Time:
Date/Time:
Date/Time:



CHA
CHAMBERLAIN & ASSOCIATES LLP

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12206
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670

Site/Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12206

Special Instructions or Comments:

E-Mail Results: Yes Turnaround Time:

Sampled By:

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

Project:

510041083

Project Address:

Project #:

Project Manager:

Analysis: ☐ PLM Only ☐ TEM Only ☐ NY ELAP PLM/TEM with NOB Prep.
☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe) ☐ Other (describe in comments)

Material Type: ☐ Bulk ☐ Dust

Date Sampled:

Field ID

Location

Sample Description
(for dust= size of surface area sampled)

Homogenous Air
(HA #)

40 20A
41 20B
50 21A
51 21B
52 22A
53 22B
54 22A
55 23D
56 24A
57 24D
58 25A
59 25B
60 26A
61 26B
62 27A
63 27B

Maroon Carpet
" "
Gray Carpet Mastic
" "
Black Carpet Mastic
" "
Green Carpet Mastic
" "
Brown Box patterned Carpet Mastic
" "
Tan Carpet Mastic
" "
12x12 White Floor Tile
" "
Gray 12x12 Floor Tile
" "

300 Ft.
"
"
"
"
15 Ft.
"
"
4th Fl.
"
"
"

Pos. Stop
Pos. Stop
Pos. Stop
Positive Stop
Pos. Stop
Pos. Stop
Pos. Stop
Pos. Stop
Pos. Stop
Pos. Stop
Pos. Stop
Pos. Stop

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12206
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670

Site/Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12206

Special Instructions or Comments:

Date/Time:
Date/Time:
Date/Time:
Date/Time:

Project:

Project Address:

Project Manager:

Analysis: ☐ PLM Only ☐ TEM Only ☐ NY ELAP PLM/TEM with NOB Prep.
☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe) ☐ Other (describe in comments)

Turnaround Time:

Sampled By:

Material Type: ☐ Bulk ☐ Dust

Date Sampled:

Scalab #:

510041083

Project #:

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
Toll Free: (800) 724-5221
www.amerisciboston.com

CHA
CHAMBERLAIN & ASSOCIATES LLP

Field ID

Location

Sample Description
(for dust= size of surface area sampled)

Homogenous Air
(HA #)

90 37A
91 37B
92 38
93 39A
94 39B
95 40A
96 40B
97 41A
98 41B
99 42A
90 42D
91 43A
92 43B
93 44A
94 44B

Mastic to 4" Brown Cove Base
" "
Barged Mastic
4" Black Cove Base
" "
Mastic to 4" Black Cove Base
" "
4" Blue Cove Base
" "
Mastic to 4" Blue Cove Base
" "
3" White Cove Base
" "
Mastic to 3" White Cove Base
" "

1st Fl.
Penhouse
" "
" "
4th Fl.
" "
" "
3rd Fl.
" "
" "
Pos. Stop
Pos. Stop
Pos. Stop
Pos. Stop
Pos. Stop
Pos. Stop

PAGE

6 OF 9

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12205
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@ciba-llp.com Cell: (315) 440-1670

Site/Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

Date/Time:
Date/Time:
Date/Time:
Date/Time:

Project:

Project Address:

Project Manager:

Analysis: ☐ PLM Only ☐ TEM Only ☐ NY ELAP PLM/TEM with NOB Prep.
☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe) ☐ Other (describe in comments)

Turnaround Time:

Sampled By:

Material Type: ☐ Bulk ☐ Dust

Date Sampled:

Field ID

Location

Sample Description
(for dust= size of surface area sampled)

Homogenous Air
(HA #)

95 45A
96 45B
97 46A
98 46B
99 47A
100 47B
101 48A
102 48B
103 49A
104 49B
105 50
106 51A
107 51B
108 52A
109 52B

4" Green Cove Base
Mastic to 4" Green Cove Base
Dark Blue 4" Cove Base
Mastic to Dark Blue 4" Cove Base
4" TAN Cove Base
Mastic to 4" Cove Base
4" TAN Cove Base
Mastic to 4" Cove Base

1st Fl. Corridor
"
"
First Fl.
"
"
A.H.U. Room - 1st Fl.
"
"
2nd Fl. Kitchen
"
"
"
"

Positive Stop
Pos. Stop
Pos. Stop
Pos. Stop
Pos. Stop
Pos. Stop
Pos. Stop
Pos. Stop

Relinquished By:
Received By:
Relinquished By:
Received By:

Company:

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12205
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@cha-llp.com Cell: (518) 440-1670

Site/Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

Date/Time:
Date/Time:
Date/Time:

Date/Time: 4/6/02

Project:

SCILAS #:

Project Address:

Project Manager:

Analysis: PLM Only

ASTM Dust (microvac)

TEM Only

NY ELAP PLM/TEM with NOB Prep.

ASTM Dust (Wipe)) Other (describe in comments)

Turnaround Time:

Material Type: Bulk

Date Sampled:

Field ID

Location

Sample Description
(for dust= size of surface area sampled)

Homogenous Air
(HA #)

110 53A
111 53B
112 54A
113 54B
114 55A
115 55D
116 56A
117 56B
118 57A
119 57B
120 57C
121 57D
122 58A
123 58D
124 58C

Exterior Window Glazing Compound
Penthouse WALL Cavity
Seam Sealant
Fitch Pocket
Built-up Roofing - Bottom
- 3rd Layer
- 2nd Layer
- Top
- Bottom
- Middle
- Top

Positive Stop
Positive Stop
Positive Stop
Positive Stop

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12205
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@cha-llp.com Cell: (518) 440-1670

Site/Secondary Fax #: E-Mail Results: Yes Turnaround Time:
Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:



AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

Project: Project #:



510041083

Project Address:

Project Manager:

Analysis: PLM Only TEM Only NY ELAP PLM/TEM with NOB Prep.
ASTM Dust (microvac) ASTM Dust (Wipe) Other (describe in comments)
Material Type: Bulk Dust

Date Sampled:

Sampled By:

Field ID

Location

Sample Description
(for dust= size of surface area sampled)

Homogenous Air
(HA #)

125 S9A
126 S9B
127 60A
128 60B
129 61A
130 61B
131 61C
132 62
133 63
134 64

Built-up Roof - Flashing - Bottom
Penthouse Roof - Field - Bottom
" - Top
" - Flashing - Bottom
" - Flashing - Middle
" - Flashing - Top
Small Roof - D.I.T. v Roofing
Root Patch Material
Flashing Sealant

Positive Spel
Positive Spel
Positive Spel

PLM Bulk Asbestos Report

Clough, Harbour & Associates

Attn: James Morey

3 Winners Circle

Albany, NY 12205

Date Received 04/06/10

Date Examined 04/12/10

ELAP # 10982

RE: 16433; ACCA; Building 3

AmeriSci Job # 510041083

P.O. #
Page 1 **of** 23

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
01A 1 Location: Penthouse	510041083-01	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Fibrous, Sheetrock Asbestos Types: Other Material: Cellulose 3 %, Fibrous glass 2 %, Non-fibrous 95 %			
01B 1 Location: Penthouse	510041083-02	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White/Tan, Homogeneous, Fibrous, Sheetrock Asbestos Types: Other Material: Cellulose 10 %, Fibrous glass 2 %, Non-fibrous 88 %			
01C 1 Location: 1st Floor - Behind PM Office	510041083-03	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White/Tan, Homogeneous, Fibrous, Sheetrock Asbestos Types: Other Material: Cellulose 5 %, Fibrous glass 2 %, Non-fibrous 93 %			
01D 1 Location: 1st Floor - Behind PM Office	510041083-04	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Fibrous, Sheetrock Asbestos Types: Other Material: Cellulose 4 %, Fibrous glass 2 %, Non-fibrous 94 %			
01E 1 Location: 2nd Floor - Mech Room	510041083-05	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Fibrous, Sheetrock Asbestos Types: Other Material: Cellulose 3 %, Fibrous glass 2 %, Non-fibrous 95 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
01F 1 Location: 2nd Floor - Mech Room	510041083-06	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Fibrous, Sheetrock Asbestos Types: Other Material: Cellulose 3 %, Fibrous glass 2 %, Non-fibrous 95 %			
02A 2 Location: Penthouse	510041083-07	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, Joint Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
02B 2 Location: Penthouse	510041083-08	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, Joint Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
02C 2 Location: 1st Floor - Behind PM Office	510041083-09	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, Joint Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
02D 2 Location: 1st Floor - Behind PM Office	510041083-10	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, Joint Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
02E 2 Location: 2nd Floor - Mech Room	510041083-11	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, Joint Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
02F 2	510041083-12 Location: 2nd Floor - Mech Room	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, Joint Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
03A 3	510041083-13 Location: 2nd Floor - Mech Room	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Fibrous, Sheetrock Tape Asbestos Types: Other Material: Cellulose 95 %, Non-fibrous 5 %			
03B 3	510041083-14 Location: 1st Floor - Behind PM Room	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Fibrous, Sheetrock Tape Asbestos Types: Other Material: Cellulose 95 %, Non-fibrous 5 %			
04A 4	510041083-15 Location: 4th Floor - Kitchen	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Fibrous, Sink Undercoating Asbestos Types: Other Material: Non-fibrous 35.8 %			
04B 4	510041083-16 Location: 4th Floor - Kitchen	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Fibrous, Sink Undercoating Asbestos Types: Other Material: Non-fibrous 35 %			
05A 5	510041083-17 Location: Penthouse	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: Grey, Homogeneous, Fibrous, Fiberboard Asbestos Types: Other Material: Cellulose 95 %, Non-fibrous 5 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
05B 5 Location: Penthouse	510041083-18	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: Grey, Homogeneous, Fibrous, Fiberboard Asbestos Types: Other Material: Cellulose 95 %, Non-fibrous 5 %			
06A 6 Location: 3rd Floor (Mercer)	510041083-19	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Fibrous, 2'x2' Ceiling Tile Asbestos Types: Other Material: Cellulose 20 %, Fibrous glass 50 %, Non-fibrous 30 %			
06B 6 Location: 3rd Floor (Mercer)	510041083-20	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Fibrous, 2'x2' Ceiling Tile Asbestos Types: Other Material: Cellulose 25 %, Fibrous glass 50 %, Non-fibrous 25 %			
07A 7 Location: Penthouse	510041083-21	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, Textured Wall Paint Asbestos Types: Other Material: Non-fibrous 33.3 %			
07B 7 Location: Penthouse	510041083-22	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, Textured Wall Paint Asbestos Types: Other Material: Non-fibrous 35.7 %			
07C 7 Location: Penthouse	510041083-23	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, Textured Wall Paint Asbestos Types: Other Material: Non-fibrous 37.5 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
07D 7 Location: Penthouse	510041083-24	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, Textured Wall Paint Asbestos Types: Other Material: Non-fibrous 39.7 %			
07E 7 Location: Penthouse	510041083-25	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, Textured Wall Paint Asbestos Types: Other Material: Non-fibrous 39.8 %			
08 Location: Vestibule	510041083-26	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 1'x1' Ceramic Floor Tile Asbestos Types: Other Material: Non-fibrous 100 %			
09 Location: Vestibule	510041083-27	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, 1'x1' Ceramic Floor Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
10A 10 Location: Elect Room - 1st Floor	510041083-28	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Brown, Homogeneous, Non-Fibrous, Grout At Penetration Asbestos Types: Other Material: Non-fibrous 13.3 %			
10B 10 Location: Elect Room - 1st Floor	510041083-29	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Brown, Homogeneous, Non-Fibrous, Grout At Penetration Asbestos Types: Other Material: Non-fibrous 13 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
11A 11 Location: Bathroom	510041083-30	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, 2'x2' Ceramic Floor Tile Asbestos Types: Other Material: Non-fibrous 100 %			
11B 11 Location: Bathroom	510041083-31	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, 2'x2' Ceramic Floor Tile Asbestos Types: Other Material: Non-fibrous 100 %			
12A 12 Location: Bathroom	510041083-32	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Homogeneous, Non-Fibrous, Cementitious, 2'x2' Ceramic Floor Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
12B 12 Location: Bathroom	510041083-33	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Homogeneous, Non-Fibrous, Cementitious, 2'x2' Ceramic Floor Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
13A 13 Location: Penthouse	510041083-34	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, Cementitious, Marble Floor Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
13B 13 Location: Penthouse	510041083-35	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, Cementitious, Marble Floor Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			

Client Name: Clough, Harbour & Associates

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
14A 14	510041083-36 Location: 3rd Floor Storage Room	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, Cementitious, Leveling Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
14B 14	510041083-37 Location: 3rd Floor Storage Room	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, Cementitious, Leveling Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
15A 15	510041083-38 Location: 1st Floor Bathroom	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Fibrous, Linoleum Asbestos Types: Other Material: Fibrous glass Trace, Non-fibrous 1 %			
15B 15	510041083-39 Location: 3rd Floor Storage Room	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Fibrous, Linoleum Asbestos Types: Other Material: Fibrous glass Trace, Non-fibrous 5.7 %			
16A 16	510041083-40 Location: 3rd Floor - Group	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Fibrous, Linoleum Asbestos Types: Other Material: Fibrous glass Trace, Non-fibrous 4.1 %			
16B 16	510041083-41 Location: 3rd Floor - Group	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Fibrous, Linoleum Asbestos Types: Other Material: Fibrous glass Trace, Non-fibrous 5.2 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
17A 17 Location: 1st Floor - Wellcare	510041083-42	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Fibrous, Linoleum Asbestos Types: Other Material: Fibrous glass Trace, Non-fibrous 11.9 %			
17B 17 Location: 1st Floor - Wellcare	510041083-43	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Fibrous, Linoleum Asbestos Types: Other Material: Fibrous glass 1 %, Non-fibrous 41.4 %			
18A 18 Location: 4th Floor	510041083-44	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 27.6 %			
18B 18 Location: 4th Floor	510041083-45	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 25.9 %			
19A 19 Location: Penthouse	510041083-46	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 40.7 %			
19B 19 Location: Penthouse	510041083-47	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 33.9 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
20A 20 Location: 3rd Floor	510041083-48	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Asbestos Types: Other Material: Non-fibrous 5.9 %			
20B 20 Location: 3rd Floor	510041083-49	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Asbestos Types: Other Material: Non-fibrous 5.7 %			
21A 21 Location: 3rd Floor	510041083-50	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 30.2 %			
21B 21 Location: 3rd Floor	510041083-51	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 31.1 %			
22A 22 Location: 3rd Floor	510041083-52	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 41.9 %			
22B 22 Location: 3rd Floor	510041083-53	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 27.1 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
23A 23 Location: 1st Floor	510041083-54	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 26.8 %			
23B 23 Location: 1st Floor	510041083-55	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 35.4 %			
24A 24 Location: 1st Floor	510041083-56	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 47.2 %			
24B 24 Location: 1st Floor	510041083-57	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 32.3 %			
25A 25 Location: 1st Floor	510041083-58	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 33.6 %			
25B 25 Location: 1st Floor	510041083-59	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 34.2 %			

Client Name: Clough, Harbour & Associates

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
26A 26 Location: 4th Floor	510041083-60	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 4.3 %			
26B 26 Location: 4th Floor	510041083-61	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 4.2 %			
27A 27 Location: 4th Floor	510041083-62	Yes	1.5 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Chrysotile 1.5 % Other Material: Non-fibrous 10.9 %			
27B 27 Location: 4th Floor	510041083-63		NA/PS
Analyst Description: 12"x12" Floor Tile Asbestos Types: Other Material:			
28A 28 Location: 4th Floor	510041083-64	Yes	3.5 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Mastic Asbestos Types: Chrysotile 3.5 % Other Material: Non-fibrous 19.3 %			
28B 28 Location: 4th Floor	510041083-65		NA/PS
Analyst Description: 12"x12" Floor Tile Mastic Asbestos Types: Other Material:			

Client Name: Clough, Harbour & Associates

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
29A 29 Location: 1st Floor	510041083-66	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Beige, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 3.1 %			
29B 29 Location: 1st Floor	510041083-67	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Beige, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 3.2 %			
30A 30 Location: 3rd Floor	510041083-68	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Blue, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 33.4 %			
30B 30 Location: 3rd Floor	510041083-69	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Blue, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 35.1 %			
31A 31 Location: 3rd Floor	510041083-70	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 7.6 %			
31B 31 Location: 3rd Floor	510041083-71	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 6.4 %			

Client Name: Clough, Harbour & Associates

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
32 Location: 3rd Floor	510041083-72	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Mastic Asbestos Types: Other Material: Non-fibrous 39 %			
33A 33 Location: 3rd Floor	510041083-73	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Light Blue, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 0.1 %			
33B 33 Location: 3rd Floor	510041083-74	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Light Blue, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 0.1 %			
34A 34 Location: 1st Floor	510041083-75	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 0.4 %			
34B 34 Location: 1st Floor	510041083-76	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 0.2 %			
35 Location: 1st Floor	510041083-77	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Mastic Asbestos Types: Other Material: Non-fibrous 39.3 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
36A 36 Location: 1st Floor	510041083-78	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 5.8 %			
36B 36 Location: 1st Floor	510041083-79	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 5.2 %			
37A 37 Location: 1st Floor	510041083-80	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 7 %			
37B 37 Location: 1st Floor	510041083-81	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 0.3 %			
38 Location: 1st Floor	510041083-82	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 33.7 %			
39A 39 Location: Penthouse	510041083-83	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 0.1 %			

Client Name: Clough, Harbour & Associates

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
39B 39 Location: Penthouse	510041083-84	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 0.1 %			
40A 40 Location: Penthouse	510041083-85	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Cream, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 27.4 %			
40B 40 Location: Penthouse	510041083-86	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Cream, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 17.8 %			
41A 41 Location: 4th Floor	510041083-87	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Blue, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 0.1 %			
41B 41 Location: 4th Floor	510041083-88	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Blue, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 0.1 %			
42A 42 Location: 4th Floor	510041083-89	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 4.2 %			

Client Name: Clough, Harbour & Associates

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
42B 42 Location: 4th Floor	510041083-90	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 0.1 %			
43A 43 Location: 3rd Floor	510041083-91	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, 3" Covebase Asbestos Types: Other Material: Non-fibrous 2.3 %			
43B 43 Location: 3rd Floor	510041083-92	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, 3" Covebase Asbestos Types: Other Material: Non-fibrous 0.6 %			
44A 44 Location: 3rd Floor	510041083-93	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Brown, Homogeneous, Non-Fibrous, 3" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 41.5 %			
44B 44 Location: 3rd Floor	510041083-94	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Brown, Homogeneous, Non-Fibrous, 3" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 41.4 %			
45A 45 Location: 1st Floor Corridor	510041083-95	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Green, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 0.8 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
45B 45	510041083-96 Location: 1st Floor Corridor	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Green, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 0.8 %			
46A 46	510041083-97 Location: 1st Floor Corridor	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 0.1 %			
46B 46	510041083-98 Location: 1st Floor Corridor	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 0.8 %			
47A 47	510041083-99 Location: 1st Floor	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Blue, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 0.1 %			
47B 47	510041083-100 Location: 1st Floor	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Blue, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 0.1 %			
48A 48	510041083-101 Location: 1st Floor	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 6.8 %			

Client Name: Clough, Harbour & Associates

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
48B 48 Location: 1st Floor	510041083-102	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 4.6 %			
49A 49 Location: AHU Room - 1st Floor	510041083-103	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 0.1 %			
49B 49 Location: AHU Room - 1st Floor	510041083-104	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 0.1 %			
50 Location: AHU Room - 1st Floor	510041083-105	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 0.1 %			
51A 51 Location: 2nd Floor Kitchen	510041083-106	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 0.7 %			
51B 51 Location: 2nd Floor Kitchen	510041083-107	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 0.6 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
52A 52 Location: 2nd Floor Kitchen	510041083-108	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 6.9 %			
52B 52 Location: 2nd Floor Kitchen	510041083-109	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 4.5 %			
53A 53 Location: 2nd Floor Kitchen	510041083-110	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, Ext. Window Glazing Compound Asbestos Types: Other Material: Non-fibrous 3.4 %			
53B 53 Location: 2nd Floor Kitchen	510041083-111	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: White, Homogeneous, Non-Fibrous, Ext. Window Glazing Compound Asbestos Types: Other Material: Non-fibrous 3.6 %			
54A 54 Location: Exterior - Roof	510041083-112	Yes	4.7 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Grey, Homogeneous, Fibrous, Penthouse Wall Caulk Asbestos Types: Chrysotile 4.7 %, Anthophyllite <1 % pc Other Material: Fibrous Talc 1 %, Non-fibrous 41.6 %			
54B 54 Location: Exterior - Roof	510041083-113	Yes	5.7 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Grey, Homogeneous, Fibrous, Penthouse Wall Caulk Asbestos Types: Chrysotile 5.7 %, Anthophyllite <1 % pc Other Material: Fibrous Talc 1 %, Non-fibrous 40 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
55A 55 Location: Low Roof	510041083-114	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Homogeneous, Non-Fibrous, Seam Sealant Asbestos Types: Other Material: Non-fibrous 12.7 %			
55B 55 Location: Low Roof	510041083-115	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Homogeneous, Non-Fibrous, Seam Sealant Asbestos Types: Other Material: Non-fibrous 10.4 %			
56A 56 Location: Low Roof	510041083-116	Yes	3 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Homogeneous, Fibrous, Pitch Pocket Asbestos Types: Chrysotile 3.0 % Other Material: Non-fibrous 16.8 %			
56B 56 Location: Low Roof	510041083-117		NA/PS
Analyst Description: Pitch Pocket Asbestos Types: Other Material:			
57A 57 Location: Roof #1	510041083-118	Yes	Trace (<0.25 % pc) (ELAP 198.6; 400pc) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Heterogeneous, Fibrous, Built-up Roofing-Bottom Asbestos Types: Chrysotile <0.25 % pc Other Material: Non-fibrous 40.6 %			
57B 57 Location: Roof #1	510041083-119	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Heterogeneous, Fibrous, Built-up Roofing-3rd Lyr Asbestos Types: Other Material: Non-fibrous 0.2 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
57C 57 Location: Roof #1	510041083-120	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Homogeneous, Fibrous, Built-up Roofing-2nd Lyr Asbestos Types: Other Material: Fibrous glass 2 %, Non-fibrous 18.8 %			
57D 57 Location: Roof #1	510041083-121	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Silver/Black, Homogeneous, Fibrous, Built-up Roofing-Top Asbestos Types: Other Material: Fibrous glass 1 %, Wollastonite Trace, Non-fibrous 11.8 %			
58A 58 Location: Roof #2	510041083-122	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Heterogeneous, Fibrous, Built-up Roofing-Bottom Asbestos Types: Other Material: Non-fibrous 9.5 %			
58B 58 Location: Roof #2	510041083-123	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Homogeneous, Fibrous, Built-up Roofing-Middle Asbestos Types: Other Material: Fibrous glass 1 %, Non-fibrous 8.8 %			
58C 58 Location: Roof #2	510041083-124	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Homogeneous, Fibrous, Built-up Roofing-Top Asbestos Types: Other Material: Fibrous glass 2 %, Non-fibrous 27.8 %			
59A 59 Location: Roof #2	510041083-125	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Heterogeneous, Fibrous, Built-up Roofing-Flashing Btm Asbestos Types: Other Material: Fibrous glass Trace, Non-fibrous 8.8 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
59B 59	510041083-126	No	NAD
Location: Roof #2			(by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Homogeneous, Fibrous, Built-up Roofing-Flashing Top Asbestos Types: Other Material: Fibrous glass 1 %, Non-fibrous 6.4 %			
60A 60	510041083-127	Yes	Trace (<0.25 % pc)
Location: Penthouse Roof			(ELAP 198.6; 400pc) by Ivan H Reyes on 04/12/10
Analyst Description: Silver/Black, Heterogeneous, Fibrous, Roof Field-Bottom Asbestos Types: Chrysotile <0.25 % pc Other Material: Fibrous glass Trace, Non-fibrous 14.3 %			
60B 60	510041083-128	Yes	7.4 %
Location: Penthouse Roof			(by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Analyst Description: Black, Homogeneous, Fibrous, Roof Field-Top Asbestos Types: Chrysotile 7.4 % Other Material: Non-fibrous 11 %			
61A 61	510041083-129		NA
Location: Penthouse Roof			
Analyst Description: Roof Field-Flashing Btm Asbestos Types: Other Material:			
61B 61	510041083-130		NA
Location: Penthouse Roof			
Analyst Description: Roof Field-Flashing Midle Asbestos Types: Other Material:			
61C 61	510041083-131		NA
Location: Penthouse Roof			
Analyst Description: Roof Field-Flashing Top Asbestos Types: Other Material:			

PLM Bulk Asbestos Report

16433; ACCA; Building 3

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
62	510041083-132	Yes	Trace (<0.25 % pc) (ELAP 198.6; 400pc) by Ivan H Reyes on 04/12/10
Location: Small Roof -Penthouse Roof			
Analyst Description: Silver/Black, Heterogeneous, Fibrous, Built Up Roofing			
Asbestos Types: Chrysotile <0.25 % pc			
Other Material: Fibrous glass 1 %, Non-fibrous 14.2 %			
63	510041083-133	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Location: Small Roof -Penthouse Roof			
Analyst Description: Black, Homogeneous, Fibrous, Roof Patch Material			
Asbestos Types:			
Other Material: Fibrous glass 1 %, Non-fibrous 7 %			
64	510041083-134	Yes	1.9 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/12/10
Location: Small Roof -Penthouse Roof			
Analyst Description: Black, Heterogeneous, Fibrous, Flashing Sealant			
Asbestos Types: Chrysotile 1.9 %			
Other Material: Fibrous glass Trace, Non-fibrous 6.6 %			

Reporting Notes:Analyzed by: Ivan H Reyes ; Date Analyzed: 4/12/10

NAD = no asbestos detected; CVES = Calibrated Visual Estimate; NA = not analyzed; NA/PS = not analyzed / positive stop; "Present" or NVA = "No Visible Asbestos" are observations made during a qualitative analysis; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #102079-0) or NY ELAP PLM Analysis Protocol 198.1 for New York friable samples (198.6 for NOB samples) (NY ELAP Lab # 10982); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. NAD or Trace results by PLM are inconclusive, TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). NIST Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested.

Reviewed By: _____

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12206

Home: (518) 463-3916

Fax: (518) 463-4773

E-Mail: jmorey@cha-llp.com

Cell: (518) 440-1670

Alt/Secondary Fax #:

E-Mail Results: Yes

Results to: Jim Morey 3 Winners Circle Albany, NY 12206

Special Instructions or Comments:

Date/Time: 03/31/00

Date/Time:

Date/Time:

Date/Time:

4/6/10 12:15

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

Project:

ACCA

Scale #:

510041083

Project #: 16433

Project Address: Bldg. 3

Project Manager: S.M. Fadden

Analysis: PLM Only

TEM Only

NY ELAP PLM/TEM with NOB Prep.

ASTM Dust (microvac)

ASTM Dust (Wipe)

Other (describe in comments)

Turnaround Time: 5-7 Day

Material Type: Bulk

Dust

Sampled By: J. Morey

Date Sampled: 03/26/10

Field ID

Location

Sample Description
(for dusts size of surface area sampled)

Homogenous Air
(HA #)

1 01A

Sheetrock

Penthouse

2 01D

Sheetrock

"

3 01C

Sheetrock

1st Fl. - Behind PM's Office

4 01D

Sheetrock

2nd Floor - Mech Rm

5 01E

Sheetrock

"

6 01F

Sheetrock

Penthouse

7 02A

Sheetrock

"

8 02D

Sheetrock

1st Fl. - Behind PM's Office

9 02C

Sheetrock

"

10 02D

Sheetrock

2nd Floor - Mech Rm

11 02E

Sheetrock

"

12 02F

Sheetrock

"

13 03A

Sheetrock

2nd Floor - Mech Rm

14 03B

Sheetrock

1st Fl. - Behind PM's Office

15 04A

Sheetrock

4th Floor - Kitchen

16 04B

Sheetrock

"

PAGE

1 OF 9

Relinquished By:
Received By:
Relinquished By:

Received By:

Date/Time:
Date/Time:
Date/Time:

4/6/10
12:15

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (888) 724-5221
WWW.AMERISCI.COM

Company:

CHA

510041083

Street Address: 3 Winners Circle

Project Address:

Project #:

City: Albany

State: NY

Zip: 12205

Project Manager:

Phone: (518) 463-3915

Fax: (518) 463-4773

E-Mail: jmorey@cha-llp.com

Cell: (315) 440-1670

Analysis: ☐ PLM Only ☐ TEM Only ☐ NY ELAP PLM/TEM with NOB Prep.

☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe)) Other (describe in comments)

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Material Type: ☐ Bulk ☐ Dust

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID	Location	Sample Description (For dusts size of surface area sampled)	Homogenous Air (HA #)
17	05A	Fiberboard	
18	05B		
19	06A	2x2 ceiling Tile	
20	06B	3rd Floor (MERCURY)	
21	07A	Textured Wall Paint	
22	07B		
23	07C		
24	07D		
25	07E		
26	08	1X1' Ceramic Floor Tile	
27	09	Grout to 1X1' Ceramic Floor Tile	
28	10A	Grout @ Penetration	
29	10B		
30	11A	2" x 2" Gray Ceramic Floor Tile	
31	11B		

Relinquished By:
Received By:
Relinquished By:

Received By:

Date/Time:
Date/Time:
Date/Time:

4/6/0 12:15

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.USA.COM

Company:

CHIA

510041083

Street Address: 3 Winners Circle

Project Address:

Project #:

City: Albany

State: NY

Zip: 12206

Home: (518) 463-3915

Fax: (518) 463-4773

E-Mail: morey@cha-llp.com

Cell: (315) 440-1670

File/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Material Type:

Bulk Dust

Results to: Jim Morey 3 Winners Circle Albany, NY 12206

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID

Location

Sample Description
(for dust size of surface area sampled)

Homogenous Air
(HA #)

32 124	Goat to 2" x 2" Cement Tile	Bathroom	
33 123	"	"	
34 134	Marble Floor Goat	Penthouse	
35 133	"	"	
36 144	Leveling Compound	3rd Fl. Storage Rm	
37 143	"	"	
38 154	White Linoleum	1st Fl. Bathroom	Positive Stop
39 155	"	"	Positive Stop
40 164	Tan Linoleum	1st Fl. - Garage	Positive Stop
41 165	"	"	Positive Stop
42 174	Light Tan Linoleum	1st Fl. - Bellcare	Positive Stop
43 175	"	"	Positive Stop
44 184	Red Carpet Mastic	4th Fl.	Positive Stop
45 193	"	"	Positive Stop
46 194	Blue Carpet Mastic	Penthouse	Positive Stop
47 195	"	"	Positive Stop

Relinquished By:
Received By:
Relinquished By:

Received By:

Date/Time:
Date/Time:
Date/Time:

4/6/10
12/15

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
www.AmeriSci.com

Company:

CMA

510041083

Street Address: 3 Winners Circle

Project Address:

Project #:

City: Albany

State: NY

Zip: 12205

Project Manager:

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jmorey@cma-llp.com

Call: (315) 440-1670

Analysis: ☐ PLM Only ☐ TEM Only ☐ NY ELAP PLM/TEM with NOB Prep.

☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe)) Other (describe in comments:

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Material Type: ☐ Bulk ☐ Dust

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID

Location

Sample Description
(for dusts size of surface area sampled)

Homogenous Air
(HA #)

48 20A

Maroon Carpet

3rd Fl.

Pos. Stop

49 26B

Gray Carpet Mastic

"

Pos. Stop

50 21A

"

"

Pos. Stop

51 21B

Black Carpet Mastic

"

Pos. Stop

52 22A

"

"

Pos. Stop

53 22B

Green Carpet Mastic

1st Fl.

Pos. Stop

54 23A

Brown Box Patterned Carpet Mastic

"

Pos. Stop

55 23D

Tan Carpet Mastic

"

Pos. Stop

56 24A

"

"

Pos. Stop

57 24D

"

"

Pos. Stop

58 25A

"

"

Pos. Stop

59 25B

"

"

Pos. Stop

60 26A

"

"

Pos. Stop

61 26B

"

"

Pos. Stop

62 27A

"

"

Pos. Stop

63 27B

"

"

Pos. Stop

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Home: (518) 463-3915

Fax: (518) 463-4773

E-Mail: jmorey@ciba-ill.com

Cell: (315) 440-1670

Site/Secondary Fax #:

E-Mail Results: Yes

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

Date/Time:

Date/Time:

Date/Time:

Date/Time:

4/6/10

12/15

Project:

Project:

Project:

Project:

Project:

Project:

Project:

Project:

Project:

Project:

Project:



AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
Toll Free: (800) 724-5221
www.AmeriSci.com

510041083

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Air (HA #)
64 28A	Mashc to Gray+White 12X12 Tile	4th Fl.	Pos. Stop
65 28B	"	4th Fl.	Pos. Stop
66 29A	Beige 12X12 Floor Tile - Domestic	1st Fl.	Pos. Stop
67 29B	"	1st Fl.	Pos. Stop
68 30A	Blue 12X12 Floor Tile	3rd Fl.	Pos. Stop
69 30B	"	"	Pos. Stop
70 31A	White 12X12 Floor Tile	"	Pos. Stop
71 31B	"	"	Pos. Stop
72 32	Mashc to Blue+White 12X12 FT.	"	Pos. Stop
73 33A	Light Blue 12X12 Floor Tile	"	Pos. Stop
74 33B	"	"	Pos. Stop
75 34A	Off-White 12X12 Floor Tile	1st Fl.	Positive Stop
76 34B	"	"	Positive Stop
77 35	Mashc to off-white Floor Tile	1st Fl.	Pos. Stop
78 36A	4" Brown Core Base	1st Fl.	Pos. Stop
79 36B	"	1st Fl.	Pos. Stop

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jmorey@cha-llp.com

Cell: (315) 440-1670

Site/Secondary Fax #:

E-Mail Results: Yes

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

Date/Time:

Date/Time:

Date/Time:

Date/Time:

Project:

Scalix #:

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

510041083

Project #:

Project Manager:

Analysis: ☐ PLM Only ☐ TEM Only ☐ NY ELAP PLM/TEM with NOB Prep.

☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe)) Other (describe in comment:

Turnaround Time:

Material Type: ☐ Bulk ☐ Dust

Sampled By:

Date Sampled:

Field ID

Location

Sample Description
(for dust - size of surface area sampled)

Homogenous Air
(HA #)

90 374

Mastic to 4" Brown Core Base

1st Fl.

Pos. Stop

81 376

Target Mastic

1st Fl.

Pos. Stop

82 38

4" Black Core Base

Penetration

Pos. Stop

83 394

Mastic to 4" Black Core Base

"

Pos. Stop

84 404

4" Blue Core Base

"

Pos. Stop

85 406

Mastic to 4" Blue Core Base

"

Pos. Stop

86 414

4" Blue Core Base

4th Fl.

Pos. Stop

87 414

Mastic to 4" Blue Core Base

"

Pos. Stop

88 416

3" White Core Base

3rd Fl.

Pos. Stop

89 424

Mastic to 3" White Core Base

"

Pos. Stop

90 424

Mastic to 3" White Core Base

"

Pos. Stop

91 434

Mastic to 3" White Core Base

"

Pos. Stop

92 436

Mastic to 3" White Core Base

"

Pos. Stop

93 444

Mastic to 3" White Core Base

"

Pos. Stop

94 445

Mastic to 3" White Core Base

"

Pos. Stop

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 463-3915

Fax: (518) 463-4773

E-Mail: jmorey@cpha-llp.com

Cell: (315) 440-1670

File/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Sampled By:

Date Sampled:

Special Instructions or Comments:

Date/Time:
Date/Time:
Date/Time:

4/6/10
12:15

Project:

Scans #:

510041083

Project Address:

Project #:

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

Field ID	Location	Sample Description (for dusts size of surface area sampled)	Homogenous Air (HA #)
95 45A	4" Green Core Base	1st Fl. Corridor	Positive Stop ↓
96 45B	4" Green Core Base	"	Pos. Stop ↓
97 46A	"	"	Pos. Stop ↓
98 46B	"	"	Pos. Stop ↓
99 47A	Dark Blue 4" Core Base	1st Fl.	Pos. Stop ↓
100 47B	"	"	Pos. Stop ↓
101 48A	Master to Dark Blue 4" Core Base	"	Pos. Stop ↓
102 48B	"	"	Pos. Stop ↓
103 49A	4" TAN Core Base	AHU Room - 1st Fl.	Pos. Stop ↓
104 49B	"	"	Pos. Stop ↓
105 50	Master to 4" Core Base	"	Pos. Stop ↓
106 51A	4" TAN Core Base	2nd Fl. Ventilation	Pos. Stop ↓
107 51B	"	"	Pos. Stop ↓
108 52A	Master to 4" Core Base	"	Pos. Stop ↓
109 52B	"	"	Pos. Stop ↓

Relinquished By:
Received By:
Relinquished By:

Date/Time:
Date/Time:
Date/Time:

Received By:

Date/Time:

Project:

Scalac #:

Company:

CHA

510041083

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

Street Address: 3 Winners Circle

Project Address:

Project #:

City: Albany

State: NY

Zip: 12206

Project Manager:

Home: (518) 463-3915

Fax: (518) 463-4773

E-Mail: jmorey@cha-llp.com

Cell: (315) 440-1670

Analysis: ☐ PLM Only ☐ TEM Only ☐ NY ELAP PLM/TEM with NOB Prep.

☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe) ☐ Other (describe in comments)

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Material Type: ☐ Bulk ☐ Dust ☐

Results to: Jim Morey 3 Winners Circle Albany, NY 12206

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID

Location

Sample Description
(for dusts size of surface area sampled)

Homogenous Air
(HA #)

110 53A

Exterior Window Gleazing Compound

Exterior Roof

Positive Sbp

111 53B

Penthouse Wall Caulk

Exterior Roof

Positive Sbp

112 54A

Seam Sealant

Exterior Roof

Positive Sbp

113 54B

Seam Sealant

Exterior Roof

Positive Sbp

114 55A

Seam Sealant

Exterior Roof

Positive Sbp

115 55D

Seam Sealant

Exterior Roof

Positive Sbp

116 56A

Seam Sealant

Exterior Roof

Positive Sbp

117 56B

Seam Sealant

Exterior Roof

Positive Sbp

118 57A

Seam Sealant

Exterior Roof

Positive Sbp

119 57B

Seam Sealant

Exterior Roof

Positive Sbp

120 57C

Seam Sealant

Exterior Roof

Positive Sbp

121 57D

Seam Sealant

Exterior Roof

Positive Sbp

122 58A

Seam Sealant

Exterior Roof

Positive Sbp

123 58D

Seam Sealant

Exterior Roof

Positive Sbp

124 58C

Seam Sealant

Exterior Roof

Positive Sbp

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jimora@cha-llp.com

Cell: (315) 440-1670

Site/Secondary Fax #:

E-Mail Results: Yes

Results to: Jim Mora 3 Winners Circle Albany, NY 12205

Sampled By:

Date Sampled:

Special Instructions or Comments:

Date/Time:
Date/Time:
Date/Time:

4/6/10 12:15

Project:

Scalas #:

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9394
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

510041083

Project #:

Field ID

Location

Sample Description
(for dusts size of surface area sampled)

Homogenous Air
(HA #)

105 599A
126 598B
127 604
128 605
129 614
130 615
131 61C
132 62
133 63
134 64

Built-up Roof - Flashing - Bottom
Penthouse Roof Field - Bottom
" " - Top
" " - Flashing - Bottom
" " - Flashing - Middle
" " - Flashing - Top
Small Roof - Built-up Roofing
Roof Patch Material
Flashing Sealant

Positive Spill
Positive Spill
Penthouse Roof

PLM Bulk Asbestos Report

Clough, Harbour & Associates

Attn: Jim Morey

3 Winners Circle

Albany, NY 12205

Date Received 03/31/10

Date Examined 04/06/10

ELAP # 10982

RE: 16433; ACCA; Building 300

AmeriSci Job # 510031330

P.O. #
Page 1 **of** 15

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-01A 1 Location: Exterior Of Building	510031330-01	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Patch On Ext. Wall Asbestos Types: Other Material: Non-fibrous 100 %			
AS031810JM-01B 1 Location: Exterior Of Building	510031330-02	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Patch On Ext. Wall Asbestos Types: Other Material: Non-fibrous 100 %			
AS031810JM-01C 1 Location: Exterior Of Building	510031330-03	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Patch On Ext. Wall Asbestos Types: Other Material: Non-fibrous 100 %			
AS031810JM-02A 2 Location: Exterior Of Building	510031330-04	Yes	3.8 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Black, Homogeneous, Fibrous, Ext. Window Caulking Asbestos Types: Chrysotile 3.8 % Other Material: Non-fibrous 34.5 %			
AS031810JM-02B 2 Location: Exterior Of Building	510031330-05	Yes	4.8 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Black, Homogeneous, Fibrous, Ext. Window Caulking Asbestos Types: Chrysotile 4.8 % Other Material: Non-fibrous 35.1 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 300

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-03A 3 Location: Exterior Of Building	510031330-06	Yes	4.2 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Grey, Homogeneous, Fibrous, Ext. Door Caulking Asbestos Types: Chrysotile 4.2 % Other Material: Non-fibrous 37.3 %			
AS031810JM-03B 3 Location: Exterior Of Building	510031330-07	Yes	4.2 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Grey, Homogeneous, Fibrous, Ext. Door Caulking Asbestos Types: Chrysotile 4.2 % Other Material: Non-fibrous 38.2 %			
AS031810JM-04A 4 Location: Kitchen	510031330-08	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Off-White, Homogeneous, Fibrous, Sheetrock Asbestos Types: Other Material: Cellulose 5 %, Non-fibrous 95 %			
AS031810JM-04B 4 Location: Kitchen	510031330-09	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Off-White, Homogeneous, Fibrous, Sheetrock Asbestos Types: Other Material: Cellulose 6 %, Non-fibrous 94 %			
AS031810JM-05A 5 Location: Kitchen	510031330-10	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: White, Homogeneous, Non-Fibrous, Joint Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-05B 5 Location: Kitchen	510031330-11	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: White, Homogeneous, Non-Fibrous, Joint Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 300

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-06A 6 Location: Elect Closet	510031330-12	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: White, Homogeneous, Fibrous, Laminant Wall Panel Asbestos Types: Other Material: Fibrous glass 1 %, Non-fibrous 8.3 %			
AS031810JM-06B 6 Location: Elect Closet	510031330-13	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: White, Homogeneous, Fibrous, Laminant Wall Panel Asbestos Types: Other Material: Fibrous glass 1 %, Non-fibrous 10.1 %			
AS031810JM-07A 7 Location: Elect Closet	510031330-14	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, Laminant Wall Panel Mastic Asbestos Types: Other Material: Non-fibrous 48.3 %			
AS031810JM-07B 7 Location: Elect Closet	510031330-15	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, Laminant Wall Panel Mastic Asbestos Types: Other Material: Non-fibrous 40.5 %			
AS031810JM-08A 8 Location: From Basement	510031330-16	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Red/Tan/Black, Heterogeneous, Fibrous, Fiberglass Paper Asbestos Types: Other Material: Cellulose 80 %, Non-fibrous 20 %			
AS031810JM-08B 8 Location: From Basement	510031330-17	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Red/Tan/Black, Heterogeneous, Fibrous, Fiberglass Paper Asbestos Types: Other Material: Cellulose 80 %, Non-fibrous 20 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 300

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-09A 9 Location: Basement	510031330-18	Yes	4.4 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Off-White, Homogeneous, Fibrous, Pipe Wrap Asbestos Types: Chrysotile 4.4 % Other Material: Non-fibrous 13.3 %			
AS031810JM-09B 9 Location: Basement	510031330-19	Yes	4.9 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Off-White, Homogeneous, Fibrous, Pipe Wrap Asbestos Types: Chrysotile 4.9 % Other Material: Non-fibrous 12.4 %			
AS031810JM-09C 9 Location: Basement	510031330-20	Yes	5.1 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Off-White, Homogeneous, Fibrous, Pipe Wrap Asbestos Types: Chrysotile 5.1 % Other Material: Non-fibrous 12.9 %			
AS031810JM-10A 10 Location: 3rd Floor	510031330-21	Yes	5.3 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Purple, Homogeneous, Fibrous, Sink Undercoating Asbestos Types: Chrysotile 5.3 % Other Material: Non-fibrous 38.3 %			
AS031810JM-10B 10 Location: 3rd Floor	510031330-22	Yes	4.8 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Purple, Homogeneous, Fibrous, Sink Undercoating Asbestos Types: Chrysotile 4.8 % Other Material: Non-fibrous 44.1 %			
AS031810JM-11A 11 Location: From Kitchen	510031330-23	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Brown, Homogeneous, Fibrous, Paper Above Wood Ceiling Asbestos Types: Other Material: Cellulose 95 %, Non-fibrous 5 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 300

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-11B 11 Location: From Kitchen	510031330-24	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Brown, Homogeneous, Fibrous, Paper Above Wood Ceiling Asbestos Types: Other Material: Cellulose 95 %, Non-fibrous 5 %			
AS031810JM-12A 12 Location: 1st Floor	510031330-25	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 12"x12" Linoleum Asbestos Types: Other Material: Non-fibrous 1.5 %			
AS031810JM-12B 12 Location: 1st Floor	510031330-26	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 12"x12" Linoleum Asbestos Types: Other Material: Non-fibrous 1.7 %			
AS031810JM-13A 13 Location: Dining Room	510031330-27	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 3.9 %			
AS031810JM-13B 13 Location: Dining Room	510031330-28	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 3.7 %			
AS031810JM-14A 14 Location: Dining Room	510031330-29	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Beige, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 3.1 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 300

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-14B 14 Location: Dining Room	510031330-30	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Beige, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 3.1 %			
AS031810JM-15A 15 Location: Dining Room	510031330-31	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Mastic Asbestos Types: Other Material: Non-fibrous 8.4 %			
AS031810JM-15B 15 Location: Dining Room	510031330-32	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Mastic Asbestos Types: Other Material: Non-fibrous 10.8 %			
AS031810JM-16A 16 Location: Kitchen - 4th Floor	510031330-33	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: White/Beige, Homogeneous, Non-Fibrous, Linoleum Flooring Asbestos Types: Other Material: Non-fibrous 0.4 %			
AS031810JM-16B 16 Location: Kitchen - 4th Floor	510031330-34	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: White/Beige, Homogeneous, Non-Fibrous, Linoleum Flooring Asbestos Types: Other Material: Non-fibrous 0.8 %			
AS031810JM-17A 17 Location: 1st Floor	510031330-35	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, Cementitious, Floor Leveling Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 300

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-17B 17 Location: 1st Floor	510031330-36	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, Cementitious, Floor Leveling Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-18A 18 Location: 2nd Floor	510031330-37	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 30.4 %			
AS031810JM-18B 18 Location: 2nd Floor	510031330-38	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 36 %			
AS031810JM-19A 19 Location: 4th Floor	510031330-39	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Tile carpet Mastic Asbestos Types: Other Material: Non-fibrous 40.3 %			
AS031810JM-19B 19 Location: 4th Floor	510031330-40	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Tile carpet Mastic Asbestos Types: Other Material: Non-fibrous 39.5 %			
AS031810JM-20A 20 Location: 4th Floor	510031330-41	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 39.2 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 300

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-20B 20 Location: 4th Floor	510031330-42	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 41.1 %			
AS031810JM-21A 21 Location: 4th Floor	510031330-43	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 44.1 %			
AS031810JM-21B 21 Location: 4th Floor	510031330-44	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 40.5 %			
AS031810JM-22A 22 Location: 2nd Floor	510031330-45	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 20.4 %			
AS031810JM-22B 22 Location: 2nd Floor	510031330-46	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 13.8 %			
AS031810JM-23A 23 Location: 3rd Floor	510031330-47	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 36.7 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 300

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-23B 23 Location: 3rd Floor	510031330-48	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Carpet Mastic Asbestos Types: Other Material: Non-fibrous 37.3 %			
AS031810JM-24A 24 Location: 1st Floor	510031330-49	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Beige, Homogeneous, Non-Fibrous, 12"x12" Ceramic Tile Asbestos Types: Other Material: Non-fibrous 100 %			
AS031810JM-24B 24 Location: 1st Floor	510031330-50	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Beige, Homogeneous, Non-Fibrous, 12"x12" Ceramic Tile Asbestos Types: Other Material: Non-fibrous 100 %			
AS031810JM-25A 25 Location: 1st Floor	510031330-51	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, 12"x12" Ceramic Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-25B 25 Location: 1st Floor	510031330-52	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, 12"x12" Ceramic Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-26A 26 Location: Kitchen	510031330-53	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Brown, Homogeneous, Non-Fibrous, Floor Tile Asbestos Types: Other Material: Non-fibrous 100 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 300

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-26B 26 Location: Kitchen	510031330-54	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Brown, Homogeneous, Non-Fibrous, Floor Tile Asbestos Types: Other Material: Non-fibrous 100 %			
AS031810JM-27A 27 Location: Kitchen	510031330-55	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Floor Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-27B 27 Location: Kitchen	510031330-56	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Floor Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-28A 28 Location: Kitchen	510031330-57	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: White, Homogeneous, Non-Fibrous, 4" Ceramic Wall Tile Asbestos Types: Other Material: Non-fibrous 100 %			
AS031810JM-28B 28 Location: Kitchen	510031330-58	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: White, Homogeneous, Non-Fibrous, 4" Ceramic Wall Tile Asbestos Types: Other Material: Non-fibrous 100 %			
AS031810JM-29A 29 Location: Kitchen	510031330-59	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 4" Ceramic Wall Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			

Client Name: Clough, Harbour & Associates

PLM Bulk Asbestos Report

16433; ACCA; Building 300

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-29B 29 Location: Kitchen	510031330-60	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 4" Ceramic Wall Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-30A 30 Location: Kitchen	510031330-61	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, 4" Ceramic Wall Tile Mastic Asbestos Types: Other Material: Non-fibrous 3.7 %			
AS031810JM-30B 30 Location: Kitchen	510031330-62	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, 4" Ceramic Wall Tile Mastic Asbestos Types: Other Material: Non-fibrous 3.9 %			
AS031810JM-31A 31 Location: 1st Floor	510031330-63	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 1'x1' Ceramic Tile Asbestos Types: Other Material: Non-fibrous 100 %			
AS031810JM-31B 31 Location: 1st Floor	510031330-64	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 1'x1' Ceramic Tile Asbestos Types: Other Material: Non-fibrous 100 %			
AS031810JM-32A 32 Location: 1st Floor	510031330-65	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Dark Grey, Homogeneous, Non-Fibrous, Cementitious, 1'x1' Ceramic Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 300

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-32B 32 Location: 1st Floor	510031330-66	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Dark Grey, Homogeneous, Non-Fibrous, Cementitious, 1'x1' Ceramic Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-33A 33 Location: 1st Floor Bath	510031330-67	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 1'x1' Ceramic Tile Asbestos Types: Other Material: Non-fibrous 100 %			
AS031810JM-33B 33 Location: 1st Floor Bath	510031330-68	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 1'x1' Ceramic Tile Asbestos Types: Other Material: Non-fibrous 100 %			
AS031810JM-34A 34 Location: 1st Floor Bath	510031330-69	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, 1'x1' Ceramic Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-34B 34 Location: 1st Floor Bath	510031330-70	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, 1'x1' Ceramic Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-35A 35 Location: 4th Floor	510031330-71	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Red/Brown, Homogeneous, Non-Fibrous, Glazed Clay Tile Asbestos Types: Other Material: Non-fibrous 100 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 300

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-35B 35 Location: 4th Floor	510031330-72	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Red/Brown, Homogeneous, Non-Fibrous, Glazed Clay Tile Asbestos Types: Other Material: Non-fibrous 100 %			
AS031810JM-36A 36 Location: 4th Floor	510031330-73	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Dark Brown, Homogeneous, Non-Fibrous, Cementitious, Glazed Clay Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-36B 36 Location: 4th Floor	510031330-74	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Dark Brown, Homogeneous, Non-Fibrous, Cementitious, Glazed Clay Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-37A 37 Location: 4th Floor	510031330-75	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Off-White/Grey, Heterogeneous, Non-Fibrous, Cementitious, Mortar To Clay Tile Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-37B 37 Location: 4th Floor	510031330-76	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Off-White/Grey, Heterogeneous, Non-Fibrous, Cementitious, Mortar To Clay Tile Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-38A 38 Location: 1st Floor Wall Cavity	510031330-77	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Black/Yellow, Homogeneous, Fibrous, Fiberglass Insulation Paper Asbestos Types: Other Material: Fibrous glass 1 %, Non-fibrous 12.5 %			

PLM Bulk Asbestos Report


16433; ACCA; Building 300

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-38B 38	510031330-78 Location: 1st Floor Wall Cavity	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Black/Yellow, Homogeneous, Fibrous, Fiberglass Insulation Paper Asbestos Types: Other Material: Fibrous glass 1 %, Non-fibrous 4.7 %			
AS031810JM-39 39	510031330-79 Location: Roof Level	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/06/10
Analyst Description: Tan, Homogeneous, Fibrous, Roof Field Fiberboard Asbestos Types: Other Material: Cellulose 90 %, Non-fibrous 10 %			
AS031810JM-40A 40	510031330-80 Location: Roof Level	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Black, Homogeneous, Non-Fibrous, Pitch Pocket Asbestos Types: Other Material: Non-fibrous 2.3 %			
AS031810JM-40B 40	510031330-81 Location: Roof Level	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Black, Homogeneous, Non-Fibrous, Pitch Pocket Asbestos Types: Other Material: Non-fibrous 2.4 %			
AS031810JM-41A 41	510031330-82 Location: Perimeter Flashing	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, Flashing Caulk Asbestos Types: Other Material: Non-fibrous 8.4 %			
AS031810JM-41B 41	510031330-83 Location: Perimeter Flashing	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, Flashing Caulk Asbestos Types: Other Material: Non-fibrous 10.8 %			

PLM Bulk Asbestos Report

16433; ACCA; Building 300

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-42A 42 Location: On Flashing	510031330-84	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Black, Homogeneous, Fibrous, Sealant Asbestos Types: Other Material: Non-fibrous 14.4 %			
AS031810JM-42B 42 Location: On Flashing	510031330-85	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/06/10
Analyst Description: Black, Homogeneous, Fibrous, Sealant Asbestos Types: Other Material: Non-fibrous 12 %			

Reporting Notes:Analyzed by: Ivan H Reyes  Date Analyzed: 4/6/10

NAD = no asbestos detected; CVES = Calibrated Visual Estimate; NA = not analyzed; NA/PS = not analyzed / positive stop; "Present" or NVA = "No Visible Asbestos" are observations made during a qualitative analysis; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #102079-0) or NY ELAP PLM Analysis Protocol 198.1 for New York friable samples (198.6 for NOB samples) (NY ELAP Lab # 10982); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. NAD or Trace results by PLM are inconclusive, TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). NIST Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested.

Reviewed By: _____

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

CHIA

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 463-3915

Fax: (518) 463-4773

Cell: (315) 440-1670

E-Mail: jmorey@chia-llp.com

E-Mail Results: Yes

Secondary Fax #:

3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

All samples received by:

Sampled By: S. Morey

Date Sampled: 03/18/10

Date/Time:
Date/Time:
Date/Time:

Date/Time:

Project:

ACCA

SciLab #:

510031330

Project #: 16433

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

Field ID

Location

Sample Description
(for dusts size of surface area sampled)

Homogenous Air
(HA #)

1 Patch on EXTERIOR WALL

"

2 EXTERIOR WINDOW CAULK

"

3 EXTERIOR DOOR CAULK

Kitchen

4 SHEETROCK

"

5 JOINT COMPOUND

"

ELECT. CLOSET

6 LAMINATE WALL PANEL

"

7 MASSIVE TO LAMINATE WALL PANEL



"

8 075

PAGE

OF

5

Relinquished By: 
Received By: 
Relinquished By:

Received By:

Company:

CHIA

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jmorey@chia-lhp.com

Cell: (315) 440-1670

ite/Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

Date/Time: 3/23/10
Date/Time:
Date/Time: 3/21/10

AMERI Sci
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

Project:

ACCA

Scilas #:

510031330

Project Address:

Project #: 16432

Project Manager:

Analysis: ☐ PLM Only ☐ TEM Only

☐ ASTM Dust (microvac)

☐ ASTM Dust (Wipe)

☒ NY ELAP PLM/TEM with NOB Prep.

Turnaround Time: 5-7 Day

Material Type: ☒ Bulk ☐ Dust

Sampled By: J. Morey

Date Sampled: 3/18/10

Field ID

Location

Sample Description
(for dust= size of surface area sampled)

Homogenous Air
(HA #)

16 08A

17 08A

18 09A

19 09A

20 09A

21 10A

22 10A

23 11A

24 11B

25 12A

26 12B

27 13A

28 13B

29 14A

30 14B

Fiberglass Paper

Pipe Wrap

Sink Undercoating

Paper Above Wood Ceiling

12x12 Marble-Style Linoleum

12x12 Black Floor Tile

12x12 Beige Floor Tile

from Basement

Basement

3rd Floor

from Kitchen

1st Floor

Dining Rm

Relinquished By:
Received By:
Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany

Home: (518) 463-3915

Mail: jmorey@cha-llp.com

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Field ID

Date/Time: 3/24/10
Date/Time:
Date/Time:

Date/Time:

Project:

ACCA

Scallos #:

510031330

Project Address:

Project #: 16433

Project Manager:

Analysis: PLM Only

ASTM Dust (microvac)

Turnaround Time:

Sampled By:

Date Sampled:

AMERI Sci
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
www.AmeriSci.com

71 15A
72 15B
73 16A
74 16B
75 17A
76 17B
77 18A
78 18B
79 19A
80 19B
81 20A
82 20B
83 21A
84 21B
85 22A
86 22B

Location	Sample Description (for dusts size of surface area sampled)	Homogenous Air (HA #)
MASTIC to Beige + Black Floor Tile	Dining Rm	
Linoleum Flooring	Kitchen - 4th Floor	
Floor Leveling Compound	1st Floor	
Gray Carpet MASTIC	2nd Floor	
Green Tile Carpet MASTIC	4th Floor	
Green/Beige Carpet MASTIC	"	
Green Carpet MASTIC	"	
Blue Carpet MASTIC	2nd Fl.	

Delinquent By:
Received By:
Delinquent By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jmorey@cha-llp.com

Cell: (315) 440-1670

Site/Secondary Fax #:

Results to: Jim Morey

3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

Date/Time: 3/24/00
Date/Time:
Date/Time:

3/24/00 10:10 AM

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

Project:

ACCA

Scale #:

510031330

Project #: 16933

Project Address:

Project Manager:

Analysis: ☐ PLM Only ☐ TEM Only ☒ NY ELAP PLM/TEM with NOB Prep.

☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe)) Other (describe in comment:

Turnaround Time: 5-10 days

Material Type: ☒ Bulk ☐ Dust

Sampled By: J. Morey

Date Sampled: 03/18/00

Field ID

Location

Sample Description
(for dust - size of surface area sampled)

Homogenous Air
(HA #)

47 23A	Purple Carpet MASTIC	2 nd Floor	
48 23B	"	"	
49 24A	12x12 Ceramic Tile - Beige	1 st Fl.	
50 24B	"	"	
51 25A	Grout to 12x12 Ceramic Tile	"	
52 25B	"	"	
53 26A	Clay Floor Tile	Kitchen	
54 26B	"	"	
55 27A	Grout to Clay Floor Tile	"	
56 27B	"	"	
57 28A	4" White Ceramic Wall Tile	"	
58 28B	"	"	
59 29A	Grout to White Ceramic Tile	"	
60 29B	"	"	
61 30A	MASTIC to White Ceramic Tile	"	
62 30B	"	"	

Relinquished By:

Received By:

Relinquished By:

Received By:

Company:

Street Address: 3 Winners Circle

City: Albany

State: NY

Zip: 12205

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: lmoney@cha-llp.com

Cell: (518) 440-1670

Site/Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

Date/Time: 2/24/10

Date/Time:

Date/Time:

Date/Time:

Project:

Scale #:

AMERI Sci
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189

Phone: (781) 337-9334

Fax: (781) 337-7642

Toll Free: (888) 724-5221

www.AmeriSci.com

510031330

Project #: 16433

Project Address:

Project Manager:

Analysis: ☐ PLM Only ☐ TEM Only ☒ NY ELAP PLM/TEM with NOB Prep.

☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe)) Other (describe in comment:

Turnaround Time: 5-7 DAY

Sampled By: J. Morey

Date Sampled: 03/12/10

Field ID

Location

Sample Description
(for dusts - size of surface area sampled)

Homogenous Air
(HA #)

03 31A
04 31B
05 32A
06 32B
07 33A
08 33B
09 34A
10 34D
11 35A
12 35B
13 36A
14 36B
15 37A
16 37B

1'x1' Black Ceramic Tile

First Fl.

Goat to 1'x1' Black Ceramic Tile

"

1'x1' Black Ceramic Tile

1st Fl. Bath

Goat to 1'x1' Black Ceramic Tile

"

Tan-Glazed Clay Tile

4th Fl.

Goat to Clay Tile

"

Monter to Clay Tile

"

Relinquished By: *[Signature]*
Received By: *[Signature]*
Relinquished By:

Date/Time: 3/30/10
Date/Time:
Date/Time: 7/31/10

AMERI Sci
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

Company: **CHA**
Street Address: 3 Winners Circle
City: Albany State: NY Zip: 12205

Project: **ACCA**
Project Address: Building 4
Project #: 16453
510031330

Phone: (518) 453-3916 Fax: (518) 453-4773
Cell: (315) 440-1670
E-Mail Results: Yes
Turnaround Time: 5-DAY
Material Type: Bulk Dust

Secondary Fax #: *[Blank]*
Results to: Jim Morey 3 Winners Circle Albany, NY 12205
Special Instructions or Comments: All samples preceded by (AS03251000M-)

Field ID	Location	Sample Description (for dust- size of surface area sampled)	Homogenous Air (HA #)
17.38A	Fiberglass Insulation Paper	1st Floor Wall Cavity	
78.38B			
79.39	Roof Field Fiberglass	Roof Level	
80.40A	Pitch Pocket	"	
81.40B			
82.41A	Flashing Caulk	Perimeter Flashing	
83.41B	"		
84.42A	Gray Sealant	on Flashing	
85.42B			

PLM Bulk Asbestos Report

Clough, Harbour & Associates

Attn: James Morey

3 Winners Circle

Albany, NY 12205

Date Received 04/05/10

Date Examined 04/09/10

RE: 16433; ACCA; Building 4

AmeriSci Job # 510041064

P.O. #

Page 1 of 1

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-43A 43	510041064-01 Location: Rubber Roof Seam Sealant	Yes	2.1 % (by NYS ELAP 198.6) by John A. Burns on 04/09/10
Analyst Description: Black, Homogeneous, Non-Fibrous, Roof Level Asbestos Types: Chrysotile 2.1 % Other Material: Non-fibrous 21.1 %			
AS031810JM-43B 43	510041064-02 Location: Rubber Roof Seam Sealant	Yes	1.7 % (by NYS ELAP 198.6) by John A. Burns on 04/09/10
Analyst Description: Black, Heterogeneous, Non-Fibrous, Roof Level Asbestos Types: Chrysotile 1.7 % Other Material: Non-fibrous 19.5 %			

Reporting Notes:

Analyzed by: John A. Burns ; Date Analyzed: 4/9/10

NAD = no asbestos detected; CVES = Calibrated Visual Estimate; NA = not analyzed; NA/PS = not analyzed / positive stop; "Present" or NVA = "No Visible Asbestos" are observations made during a qualitative analysis; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #102079-0) or NY ELAP PLM Analysis Protocol 198.1 for New York friable samples (198.6 for NOB samples) (NY ELAP Lab # 10982); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. NAD or Trace results by PLM are inconclusive, TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). NIST Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested.

Reviewed By: _____

Relinquished By: [Signature]

Received By: [Signature]

Relinquished By: [Signature]

Received By: [Signature]

Company: CHA

Project Address: 3 Winners Circle

City: Albany

Phone: (518) 453-3915

Fax: (518) 453-4773

Cell: (518) 440-1670

E-Mail Results: Yes

Turnaround Time: 5-DAY

Date Sampled: 2/18/10

Material Type: Bulk

Dust

Special Instructions or Comments:

Field ID

Location

Sample Description

Homogenous Air

Sample Size of surface area sampled

HA #

Page 1 of 1

Date/Time: 2/31/10

Date/Time:

Date/Time:

Date/Time: 4/5/10

Project:

ACCA

Scalac #:

510041064

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

Project Address: 81994

Project Manager: Seth Fuchs

Analysis: PLM Only TEM Only NY ELAP PLM/TEM with NOB Prep.

ASTM Dust (microvac) ASTM Dust (Wipe) Other (describe in comment:

Sampled By: J. Morey

Samplets needed by: (AS0318103m-)

Location

Rubber Roof Seam Seakent

43A

4375

Sample Description

Roof Sealed

Sample Size of surface area sampled

HA #

Homogenous Air

Sample Size of surface area sampled

HA #

Page 1 of 1

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 300

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
01	AS031810JM-01A	1	----	----	----	----	NAD	NA
Location:	Exterior Of Building							
02	AS031810JM-01B	1	----	----	----	----	NAD	NA
Location:	Exterior Of Building							
03	AS031810JM-01C	1	----	----	----	----	NAD	NA
Location:	Exterior Of Building							
04	AS031810JM-02A	2	0.369	51.7	9.9	34.5	Chrysotile 3.8	NA
Location:	Exterior Of Building							
05	AS031810JM-02B	2	0.194	49.2	10.9	35.1	Chrysotile 4.8	NA
Location:	Exterior Of Building							
06	AS031810JM-03A	3	0.161	51.1	7.4	37.4	Chrysotile 4.2	NA
Location:	Exterior Of Building							
07	AS031810JM-03B	3	0.145	47.7	9.8	38.2	Chrysotile 4.2	NA
Location:	Exterior Of Building							
08	AS031810JM-04A	4	----	----	----	----	NAD	NA
Location:	Kitchen							
09	AS031810JM-04B	4	----	----	----	----	NAD	NA
Location:	Kitchen							
10	AS031810JM-05A	5	----	----	----	----	NAD	NA
Location:	Kitchen							
11	AS031810JM-05B	5	----	----	----	----	NAD	NA
Location:	Kitchen							
12	AS031810JM-06A	6	0.294	42.8	47.9	9.2	NAD	Chrysotile Trace
Location:	Elect Closet							
13	AS031810JM-06B	6	0.289	42.2	46.7	11.1	NAD	NAD
Location:	Elect Closet							
14	AS031810JM-07A	7	0.178	14.9	36.8	48.3	NAD	NAD
Location:	Elect Closet							
15	AS031810JM-07B	7	0.131	33.3	26.3	40.5	NAD	NAD
Location:	Elect Closet							
16	AS031810JM-08A	8	----	----	----	----	NAD	NA
Location:	From Basement							

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 300

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
17	AS031810JM-08B	8	---	---	---	---	NAD	NA
Location:	From Basement							
18	AS031810JM-09A	9	0.187	77.6	4.7	13.3	Chrysotile 4.4	NA
Location:	Basement							
19	AS031810JM-09B	9	0.138	78.2	4.6	12.4	Chrysotile 4.9	NA
Location:	Basement							
20	AS031810JM-09C	9	0.144	77.1	4.9	12.9	Chrysotile 5.1	NA
Location:	Basement							
21	AS031810JM-10A	10	0.067	31.6	24.9	38.3	Chrysotile 5.3	NA
Location:	3rd Floor							
22	AS031810JM-10B	10	0.061	31.3	19.9	44.1	Chrysotile 4.8	NA
Location:	3rd Floor							
23	AS031810JM-11A	11	---	---	---	---	NAD	NA
Location:	From Kitchen							
24	AS031810JM-11B	11	---	---	---	---	NAD	NA
Location:	From Kitchen							
25	AS031810JM-12A	12	0.431	22.5	76.0	1.5	NAD	NAD
Location:	1st Floor							
26	AS031810JM-12B	12	0.384	22.7	75.6	1.7	NAD	NAD
Location:	1st Floor							
27	AS031810JM-13A	13	0.422	19.1	77.0	3.9	NAD	NAD
Location:	Dining Room							
28	AS031810JM-13B	13	0.439	19.3	77.1	3.7	NAD	NAD
Location:	Dining Room							
29	AS031810JM-14A	14	0.451	12.0	84.9	3.1	NAD	NAD
Location:	Dining Room							
30	AS031810JM-14B	14	0.354	12.0	84.9	3.1	NAD	NAD
Location:	Dining Room							
31	AS031810JM-15A	15	0.196	23.6	68.0	8.4	NAD	NAD
Location:	Dining Room							
32	AS031810JM-15B	15	0.165	22.2	67.0	10.8	NAD	NAD
Location:	Dining Room							

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 300

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
33 Location: Kitchen - 4th Floor	AS031810JM-16A	16	0.270	51.3	48.3	0.4	NAD	NAD
34 Location: Kitchen - 4th Floor	AS031810JM-16B	16	0.242	12.7	86.5	0.8	NAD	NAD
35 Location: 1st Floor	AS031810JM-17A	17	----	----	----	----	NAD	NA
36 Location: 1st Floor	AS031810JM-17B	17	----	----	----	----	NAD	NA
37 Location: 2nd Floor	AS031810JM-18A	18	0.163	33.5	36.0	30.4	NAD	NAD
38 Location: 2nd Floor	AS031810JM-18B	18	0.230	31.2	32.9	36.0	NAD	NAD
39 Location: 4th Floor	AS031810JM-19A	19	0.106	44.0	15.8	40.3	NAD	NAD
40 Location: 4th Floor	AS031810JM-19B	19	0.186	44.5	16.1	39.5	NAD	NAD
41 Location: 4th Floor	AS031810JM-20A	20	0.177	51.1	9.6	39.2	NAD	NAD
42 Location: 4th Floor	AS031810JM-20B	20	0.156	52.3	6.6	41.1	NAD	NAD
43 Location: 4th Floor	AS031810JM-21A	21	0.351	35.4	20.5	44.1	NAD	NAD
44 Location: 4th Floor	AS031810JM-21B	21	0.254	33.7	25.8	40.5	NAD	NAD
45 Location: 2nd Floor	AS031810JM-22A	22	0.589	39.3	40.3	20.4	NAD	NAD
46 Location: 2nd Floor	AS031810JM-22B	22	0.229	30.3	55.9	13.8	NAD	NAD
47 Location: 3rd Floor	AS031810JM-23A	23	0.189	38.7	24.6	36.7	NAD	NAD
48 Location: 3rd Floor	AS031810JM-23B	23	0.206	44.1	18.6	37.3	NAD	NAD

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 300

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
49 Location: 1st Floor	AS031810JM-24A	24	----	----	----	----	NAD	NA
50 Location: 1st Floor	AS031810JM-24B	24	----	----	----	----	NAD	NA
51 Location: 1st Floor	AS031810JM-25A	25	----	----	----	----	NAD	NA
52 Location: 1st Floor	AS031810JM-25B	25	----	----	----	----	NAD	NA
53 Location: Kitchen	AS031810JM-26A	26	----	----	----	----	NAD	NA
54 Location: Kitchen	AS031810JM-26B	26	----	----	----	----	NAD	NA
55 Location: Kitchen	AS031810JM-27A	27	----	----	----	----	NAD	NA
56 Location: Kitchen	AS031810JM-27B	27	----	----	----	----	NAD	NA
57 Location: Kitchen	AS031810JM-28A	28	----	----	----	----	NAD	NA
58 Location: Kitchen	AS031810JM-28B	28	----	----	----	----	NAD	NA
59 Location: Kitchen	AS031810JM-29A	29	----	----	----	----	NAD	NA
60 Location: Kitchen	AS031810JM-29B	29	----	----	----	----	NAD	NA
61 Location: Kitchen	AS031810JM-30A	30	0.097	32.9	63.4	3.7	NAD	NAD
62 Location: Kitchen	AS031810JM-30B	30	0.130	32.3	63.8	3.9	NAD	NAD
63 Location: 1st Floor	AS031810JM-31A	31	----	----	----	----	NAD	NA
64 Location: 1st Floor	AS031810JM-31B	31	----	----	----	----	NAD	NA

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 300


AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
65	AS031810JM-32A	32	---	---	---	---	NAD	NA
Location: 1st Floor								
66	AS031810JM-32B	32	---	---	---	---	NAD	NA
Location: 1st Floor								
67	AS031810JM-33A	33	---	---	---	---	NAD	NA
Location: 1st Floor Bath								
68	AS031810JM-33B	33	---	---	---	---	NAD	NA
Location: 1st Floor Bath								
69	AS031810JM-34A	34	---	---	---	---	NAD	NA
Location: 1st Floor Bath								
70	AS031810JM-34B	34	---	---	---	---	NAD	NA
Location: 1st Floor Bath								
71	AS031810JM-35A	35	---	---	---	---	NAD	NA
Location: 4th Floor								
72	AS031810JM-35B	35	---	---	---	---	NAD	NA
Location: 4th Floor								
73	AS031810JM-36A	36	---	---	---	---	NAD	NA
Location: 4th Floor								
74	AS031810JM-36B	36	---	---	---	---	NAD	NA
Location: 4th Floor								
75	AS031810JM-37A	37	---	---	---	---	NAD	NA
Location: 4th Floor								
76	AS031810JM-37B	37	---	---	---	---	NAD	NA
Location: 4th Floor								
77	AS031810JM-38A	38	0.185	75.5	11.1	13.5	NAD	NAD
Location: 1st Floor Wall Cavity								
78	AS031810JM-38B	38	0.250	89.7	4.6	5.7	NAD	NAD
Location: 1st Floor Wall Cavity								
79	AS031810JM-39		---	---	---	---	NAD	NA
Location: Roof Level								
80	AS031810JM-40A	40	0.405	64.7	33.0	2.3	NAD	NAD
Location: Roof Level								

See Reporting notes on last page

Client Name: Clough, Harbour & Associates

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Building 300

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
81 Location: Roof Level	AS031810JM-40B	40	0.405	64.9	32.8	2.4	NAD	NAD
82 Location: Perimeter Flashing	AS031810JM-41A	41	0.409	32.1	59.5	8.4	NAD	NAD
83 Location: Perimeter Flashing	AS031810JM-41B	41	0.527	32.8	56.5	10.8	NAD	NAD
84 Location: On Flashing	AS031810JM-42A	42	0.254	80.4	5.1	14.4	NAD	NAD
85 Location: On Flashing	AS031810JM-42B	42	0.246	83.0	5.0	12.0	NAD	NAD

Reviewed by: _____ Date Reviewed: _____ Analyzed By: Sandhya Gunasekara  Date Analyzed: 4/7/2010

Semi-Quantitative Analysis: NAD = no asbestos detected; NA = not analyzed; NA/PS = not analyzed due to positive stop; Trace = <1%;
 PLM analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #102079-0) or NY ELAP 198.6 for New York NOB samples (NY ELAP Lab # 10982);
 TEM analysis by EPA 600/R-93/116 (not covered by NVLAP Bulk accreditation) or NY ELAP 198.4 for New York NOB samples (NY ELAP Lab # 10982);

** Warning Notes: Consider PLM fiber diameter limitation, only TEM will resolve fibers <0.25 micrometers in diameter. TEM bulk analysis is representative of the fine grained matrix material and may not be representative of non-uniformly dispersed debris, soils or other heterogeneous materials for which a combination PLM/TEM evaluation is recommended; Quantitation for beginning weights of <0.1 grams should be considered as qualitative only.

Relinquished By: 
 Received By: 
 Relinquished By: 

Date/Time: 3/23/10
 Date/Time:
 Date/Time:
 Date/Time: 3/31/10



AmeriSci Boston
 8 School Street
 Weymouth, MA 02189
 Phone: (781) 337-9334
 Fax: (781) 337-7642
 TOLL FREE: (800) 724-5221
 WWW.AMERISCI.COM

Received By:
 Company: CHA
 CHA HARBOR & ASSOCIATES LLP

Project: ACHA
 Project Address:
 Project Manager:

Project #: 16433
 SCILAS #: 510031330

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12206
 Phone: (518) 453-3915 Fax: (518) 453-4773
 E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670

Analysis: PLM Only TEM Only XNY ELAP PLM/TEM with NOB Prep.
 ASTM Dust (microvac) ASTM Dust (Wipe) Other (describe in comment):
 Turnaround Time: 5-DAY Material Type: Bulk Dust

Date Sampled: 3/18/10
 Sampled By: J. Morey

Site/Secondary Fax #: Jim Morey 3 Winners Circle Albany, NY 12206
 Special Instructions or Comments:

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Air (HA #)
16 08A	Fiberglass Paper	from Basement	
17 08A	Pipe Wrap	Basement	
18 09A	"	"	
19 09B	"	"	
20 09C	Sink Undercoating	3rd Floor	
21 10A	"	"	
22 10B	Paper Above Wood Ceiling	from Kitchen	
23 11A	"	"	
24 11B	12x12 Marble Style Linoleum	First Floor	
25 12A	12x12 Black Floor Tile	Dining Room	
26 12B	12x12 Beige Floor Tile	↓	
27 13A			
28 13B			
29 14A			
30 14B			

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

AMERISCI
BOSTON

Project #: 16433

SCILAB #:

Project: *ACCA*

Company:

CHA
CLEAN HARBOR ASSOCIATES, LLP

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12208

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jmorey@cha-llp.com

Cell: (315) 440-1670

Site/Secondary Fax #:

E-Mail Results: Yes

Results to: Jim Morey 3 Winners Circle Albany, NY 12208

Turnaround Time: 5-DAY




Material Type: ☒ Bulk ☐ Dust

Sampled By: J. Morey

Date Sampled: 02/18/10

Special Instructions or Comments:

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Air (HA #)
91 15A	MASTIC to Beige + Placed Floor Tile	Dining R	
92 15B	Linoleum Flooring	Kitchen - 4th Floor	
93 16A		1st Floor	
94 16B	Floor Leveling Compound	2nd Floor	
95 17A	Gray Carpet MASTIC	4th Floor	
96 17B	Green Tile Carpet MASTIC	4th Floor	
97 18A	Green/Beige Carpet MASTIC	4th Floor	
98 18B	Green Carpet MASTIC	"	
99 19A	Green Carpet MASTIC	"	
40 19B	Blue Carpet MASTIC	2nd Fl.	
41 20A		"	
42 20B		"	
43 21A		"	
44 21B		"	
45 22A		"	
46 22B		"	

Relinquished By: 
 Received By: 
 Relinquished By: 

Date/Time: 3/24/10
 Date/Time:
 Date/Time:
 Date/Time: 3/31/10 10:10 PM

AMERISCI
 BOSTON
 AmeriSci Boston
 8 School Street
 Weymouth, MA 02189
 Phone: (781) 337-9334
 Fax: (781) 337-7642
 TOLL FREE: (800) 724-5221
 WWW.AMERISCI.COM



Project: ACCA
 SciLab #:

510031330
 Project #: 16433

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12205
 Phone: (518) 453-3915 Fax: (518) 453-4773
 E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670

Project Manager:
 Analysis: PLM Only TEM Only NY ELAP PLM/TEM with NOB Prep.
ASTM Dust (microvac) ASTM Dust (Wipe) Other (describe in comment)
 Material Type: 5-DAY Bulk Dust


E-Mail Results: Yes
 Turnaround Time: 5-DAY
 Sampled By: J. Morey
 Date Sampled: 03/18/10

Special Instructions or Comments:

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Ar (HA #)
47 23A	Purple Ca-grout MASTIC	2 nd Floor	
48 23B	"	"	
49 24A	12x12 Ceramic Tile - Beige	1 st Fl.	
50 24B	"	"	
51 25A	Grout to 12x12 Ceramic Tile	"	
52 25B	"	"	
53 26A	Clay Floor Tile	Kitchen	
54 26B	"	"	
55 27A	Grout to Clay Floor Tile	"	
56 27B	"	"	
57 28A	4" White Ceramic WALL Tile	"	
58 28B	"	"	
59 29A	Grout to White Ceramic Tile	"	
60 29B	"	"	
61 30A	MASTIC to White Ceramic Tile	"	
62 30B	"	"	

Relinquished By:  Date/Time: 2/24/10
 Received By:  Date/Time:
 Relinquished By:  Date/Time: 2/24/10

AMERISCI BOSTON
 AmeriSci Boston
 8 School Street
 Weymouth, MA 02189
 Phone: (781) 337-9334
 Fax: (781) 337-7642
 TOLL FREE: (800) 724-5221
 WWW.AMERISCI.COM

Received By: 
 Company: **CHA**
 CHA HARBOR ASSOCIATES LLP
 Street Address: 3 Winners Circle
 City: Albany State: NY Zip: 12205
 Phone: (518) 453-3915 Fax: (518) 453-4773
 E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670

Project: **ALCA** Project #: **16433**
 Project Address:
 Project Manager:
 Analysis: ☒ PLM Only ☐ TEM Only ☒ NY ELAP PLM/TEM with NOB Prep.
☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe) ☐ Other (describe in comment):
 Material Type: ☒ Bulk ☐ Dust

Turnaround Time: 5-DAY
 Date Sampled: 03/10/10
 Sampled By: J. Morey
 E-Mail Results: Yes
 Results to: Jim Morey 3 Winners Circle Albany, NY 12205
 Special Instructions or Comments:

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Ar (HA #)
63 31A	1'x1' Black Ceramic Tile	First Fl.	
64 31B	"	"	
65 32A	Gout to 1'x1' Black Ceramic Tile	"	
66 32B	"	"	
67 33A	1'x1' Black Ceramic Tile	1st Fl. Bath	
68 33B	"	"	
69 34A	Gout to 1'x1' Black Ceramic Tile	"	
70 34B	"	"	
71 35A	TAN-Glazed Clay Tile	4th Fl.	
72 35B	"	"	
73 36A	Gout to Clay Tile	"	
74 36B	"	"	
75 37A	Mortar to Clay Tile	"	
76 37B	"	"	

Relinquished By: *[Signature]*
Received By: *[Signature]*
Relinquished By: *[Signature]*

Date/Time: 3/30/10
Date/Time:
Date/Time:
Date/Time: 3/30/10
Date/Time: 10:15

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (888) 724-5221
WWW.AMERISCI.COM

AMERISCI
BOSTON

Received By:

CHA
CLACHMAN GROUP'S ASSOCIATES LLP

Project:

SCILAS #:

ACCA

510031330

Company:

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12205
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670

Project Address: Building 4

Project #:

16453

Project Manager:

Analysis: PLM Only ☒ NY ELAP PLM/TEM with NOB Prep.
ASTM Dust (microvac) ☐ ASTM Dust (Wipe) ☐ Other (describe in comment)

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time: 5-DAY

Material Type: ☒ Bulk ☐ Dust

Results to: Jim Morey

3 Winners Circle Albany, NY 12205

Sampled By: Morey

Date Sampled: 3/25/10

Special Instructions or Comments:

All samples provided by: ASD325070M-

Field ID	Location	Sample Description (for dusts= size of surface area sampled)	Homogenous Air (HA #)
77-38A	Fiberglass Insulation Paper	1st Floor Wall Cavity	
78-38B	"		
79-39	Roof Field Fiberboard	Roof Level	
80-40A	Pitch Pocket	"	
81-40B	Flashing Caulk	Perimeter Flashing	
82-41A	"	"	
83-41B	Gray Sealant	on Flashing	
84-42A			
85-42B			



AmeriSci Boston

8 SCHOOL ST.

WEYMOUTH, MA 02189

TEL: (781) 337-9334 • FAX: (781) 337-7642

PLM Bulk Asbestos Report

Clough, Harbour & Associates

Attn: Jim Morey

3 Winners Circle

Albany, NY 12205

Date Received 04/06/10

Date Examined 04/10/10

ELAP # 10982

RE: 16433; ACCA; Broadway, Albany, NY

AmeriSci Job # 510041070

P.O. #

Page 1 of 18

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-01A 1 Location: 1st Floor	510041070-01	Yes	44.4 % (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Grey/White, Homogeneous, Non-Fibrous, Aircell Pipe Insulation Asbestos Types: Chrysotile 44.4 % Other Material: Cellulose 40 %, Non-fibrous 15.6 %			
AS031810JM-01B 1 Location: 1st Floor	510041070-02		NA/PS
Analyst Description: Aircell Pipe Insulation Asbestos Types: Other Material:			
AS031810JM-01C 1 Location: 1st Floor	510041070-03		NA/PS
Analyst Description: Aircell Pipe Insulation Asbestos Types: Other Material:			
AS031810JM-02A 2 Location: 1st Floor	510041070-04	Yes	18.2 % (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: White, Homogeneous, Fibrous, Mudded Fitting Insulation Asbestos Types: Chrysotile 18.2 % Other Material: Cellulose Trace, Non-fibrous 81.8 %			
AS031810JM-02B 2 Location: 1st Floor	510041070-05	Yes	22.2 % (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: White, Homogeneous, Fibrous, Mudded Fitting Insulation Asbestos Types: Chrysotile 22.2 % Other Material: Non-fibrous 77.8 %			

See Reporting notes on last page

PLM Bulk Asbestos Report

16433; ACCA; Broadway, Albany, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-02C 2 Location: 1st Floor	510041070-06	Yes	20 % (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: White, Homogeneous, Fibrous, Mudded Fitting Insulation Asbestos Types: Chrysotile 20.0 % Other Material: Non-fibrous 80 %			
AS031810JM-03A 3 Location: 1st Floor	510041070-07	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Tan/Black/Silver, Heterogeneous, Fibrous, Fiberglass Insulation Paper Asbestos Types: Other Material: Fibrous glass Trace, Non-fibrous 16.6 %			
AS031810JM-03B 3 Location: 1st Floor	510041070-08	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Tan/Black/Silver, Heterogeneous, Fibrous, Fiberglass Insulation Paper Asbestos Types: Other Material: Non-fibrous 3.7 %			
AS031810JM-04A 4 Location: Exterior Of Building	510041070-09	Yes	Trace (<0.25 % pc) (ELAP 198.6; 400pc) by Ivan H Reyes on 04/10/10
Analyst Description: Beige, Homogeneous, Non-Fibrous, Ext. Window Glazing Compound Asbestos Types: Chrysotile <0.25 % pc Other Material: Non-fibrous 7.6 %			
AS031810JM-04B 4 Location: Exterior Of Building	510041070-10	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Beige, Homogeneous, Non-Fibrous, Ext. Window Glazing Compound Asbestos Types: Other Material: Non-fibrous 9.2 %			
AS031810JM-05A 5 Location: 4th Floor	510041070-11	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Floor Leveling Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			

PLM Bulk Asbestos Report

16433; ACCA; Broadway, Albany, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-05B 5 Location: 4th Floor	510041070-12	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Floor Leveling Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-06A 6 Location: Stair Landing	510041070-13	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Green, Homogeneous, Fibrous, Linoleum Flooring Asbestos Types: Other Material: Non-fibrous 3 %			
AS031810JM-06B 6 Location: Stair Landing	510041070-14	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Green, Homogeneous, Fibrous, Linoleum Flooring Asbestos Types: Other Material: Non-fibrous 2.9 %			
AS031810JM-07A 7 Location: 4th Floor	510041070-15	Yes	4.9 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: White, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Chrysotile 4.9 % Other Material: Non-fibrous 35.6 %			
AS031810JM-07B 7 Location: 4th Floor	510041070-16	Yes	7.2 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: White, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Chrysotile 7.1 % Other Material: Non-fibrous 39.3 %			
AS031810JM-08A 8 Location: 4th Floor	510041070-17	Yes	5.9 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Beige, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Chrysotile 5.9 % Other Material: Non-fibrous 26.4 %			

PLM Bulk Asbestos Report

16433; ACCA; Broadway, Albany, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-08B 8 Location: 4th Floor	510041070-18	Yes	4.7 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Beige, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Chrysotile 4.7 % Other Material: Non-fibrous 19 %			
AS031810JM-09A 9 Location: 4th Floor	510041070-19	Yes	3.8 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Black/Tan, Heterogeneous, Fibrous, Material Under Floor Tile Asbestos Types: Chrysotile 3.8 % Other Material: Non-fibrous 34.6 %			
AS031810JM-09B 9 Location: 4th Floor	510041070-20	Yes	2.9 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Black/Tan, Heterogeneous, Fibrous, Material Under Floor Tile Asbestos Types: Chrysotile 2.9 % Other Material: Non-fibrous 26.3 %			
AS031810JM-10A 10 Location: 3rd Floor	510041070-21	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Brown, Homogeneous, Non-Fibrous, Floor Paper Asbestos Types: Other Material: Non-fibrous 6 %			
AS031810JM-10B 10 Location: 3rd Floor	510041070-22	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Brown, Homogeneous, Non-Fibrous, Floor Paper Asbestos Types: Other Material: Non-fibrous 4 %			
AS031810JM-11A 11 Location: 4th Floor	510041070-23	Yes	7.8 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Chrysotile 7.8 % Other Material: Non-fibrous 46.8 %			

PLM Bulk Asbestos Report

16433; ACCA; Broadway, Albany, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-11B 11 Location: 4th Floor	510041070-24	Yes	5.4 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Chrysotile 5.4 % Other Material: Non-fibrous 38.8 %			
AS031810JM-12A 12 Location: 1st Floor	510041070-25	Yes	10.5 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Green, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Chrysotile 10.5 % Other Material: Non-fibrous 41.9 %			
AS031810JM-12B 12 Location: 1st Floor	510041070-26	Yes	11.4 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Green, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Chrysotile 11.4 % Other Material: Non-fibrous 40.1 %			
AS031810JM-13A 13 Location: 1st Floor	510041070-27	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 1.2 %			
AS031810JM-13B 13 Location: 1st Floor	510041070-28	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 1 %			
AS031810JM-14A 14 Location: 1st Floor	510041070-29	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Brown, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 43.2 %			

PLM Bulk Asbestos Report

16433; ACCA; Broadway, Albany, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-14B 14 Location: 1st Floor	510041070-30	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Brown, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 32.1 %			
AS031810JM-15A 15 Location: 1st Floor	510041070-31	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Brown, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 3.9 %			
AS031810JM-15B 15 Location: 1st Floor	510041070-32	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Brown, Homogeneous, Non-Fibrous, 4" Covebase Asbestos Types: Other Material: Non-fibrous 2.9 %			
AS031810JM-16A 16 Location: 1st Floor	510041070-33	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 31 %			
AS031810JM-16B 16 Location: 1st Floor	510041070-34	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, 4" Covebase Mastic Asbestos Types: Other Material: Non-fibrous 26.7 %			
AS031810JM-17A 17 Location: 1st Floor	510041070-35	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Beige, Homogeneous, Non-Fibrous, Clay Tile Asbestos Types: Other Material: Non-fibrous 100 %			

PLM Bulk Asbestos Report

16433; ACCA; Broadway, Albany, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-17B 17 Location: 1st Floor	510041070-36	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Brown, Homogeneous, Non-Fibrous, Clay Tile Asbestos Types: Other Material: Non-fibrous 100 %			
AS031810JM-18A 18 Location: 1st Floor	510041070-37	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Clay Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-18B 18 Location: 1st Floor	510041070-38	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Clay Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-19A 19 Location: 2nd Floor	510041070-39	Yes	1.3 % (ELAP 198.1; 400pc) by Ivan H Reyes on 04/10/10
Analyst Description: Red, Homogeneous, Fibrous, Cementitious, Clay Floor Asbestos Types: Chrysotile 1.3 % Other Material: Cellulose 3 %, Non-fibrous 95.7 %			
AS031810JM-19B 19 Location: 2nd Floor	510041070-40	Yes	1.5 % (ELAP 198.1; 400pc) by Ivan H Reyes on 04/10/10
Analyst Description: Red, Homogeneous, Fibrous, Cementitious, Clay Floor Asbestos Types: Chrysotile 1.5 % Other Material: Cellulose 3 %, Non-fibrous 95.5 %			
AS031810JM-20A 20 Location: 1st Floor	510041070-41	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Black, Homogeneous, Non-Fibrous, Ceramic Tile Asbestos Types: Other Material: Non-fibrous 100 %			

PLM Bulk Asbestos Report

16433; ACCA; Broadway, Albany, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-20B 20 Location: 1st Floor	510041070-42	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Black, Homogeneous, Non-Fibrous, Ceramic Tile Asbestos Types: Other Material: Non-fibrous 100 %			
AS031810JM-21A 21 Location: 1st Floor	510041070-43	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, Cementitious, Ceramic Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-21B 21 Location: 1st Floor	510041070-44	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, Cementitious, Ceramic Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-22A 22 Location: 2nd Floor	510041070-45	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: White, Homogeneous, Fibrous, 1'x1' Ceiling Tile Asbestos Types: Other Material: Cellulose 90 %, Non-fibrous 10 %			
AS031810JM-22B 22 Location: 2nd Floor	510041070-46	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: White, Homogeneous, Fibrous, 1'x1' Ceiling Tile Asbestos Types: Other Material: Cellulose 90 %, Non-fibrous 10 %			
AS031810JM-23A 23 Location: 1st Floor	510041070-47	Yes	2.8 % (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, Wall Glue Asbestos Types: Chrysotile 2.8 % Other Material: Non-fibrous 25.6 %			

PLM Bulk Asbestos Report

16433; ACCA; Broadway, Albany, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-23B 23 Location: 1st Floor	510041070-48	Yes	3 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, Wall Glue Asbestos Types: Chrysotile 3.0 % Other Material: Non-fibrous 26.5 %			
AS031810JM-24A 24 Location: Storage Area	510041070-49	Yes	66.7 % (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Grey, Homogeneous, Fibrous, Ceiling Insulation Board Asbestos Types: Chrysotile 66.7 % Other Material: Non-fibrous 33.3 %			
AS031810JM-24B 24 Location: Storage Area	510041070-50	Yes	66.7 % (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Grey, Homogeneous, Fibrous, Ceiling Insulation Board Asbestos Types: Chrysotile 66.7 % Other Material: Non-fibrous 33.3 %			
AS031810JM-25A 25 Location: 1st Floor - Office	510041070-51	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Off-White/Tan, Homogeneous, Fibrous, Sheetrock Asbestos Types: Other Material: Cellulose 10 %, Fibrous glass 2 %, Non-fibrous 88 %			
AS031810JM-25B 25 Location: 1st Floor - Storage	510041070-52	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Off-White/Tan, Homogeneous, Fibrous, Sheetrock Asbestos Types: Other Material: Cellulose 15 %, Non-fibrous 85 %			
AS031810JM-26A 26 Location: 1st Floor - Office	510041070-53	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: White, Homogeneous, Non-Fibrous, Joint Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			

PLM Bulk Asbestos Report

16433; ACCA; Broadway, Albany, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-26B 26	510041070-54 Location: 1st Floor - Office	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: White, Homogeneous, Non-Fibrous, Joint Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-27A 27	510041070-55 Location: 1st Floor - Office	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Brown/White, Heterogeneous, Fibrous, Cementitious, Ceiling Plaster Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-27B 27	510041070-56 Location: 1st Floor - Office	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Brown/White, Heterogeneous, Fibrous, Cementitious, Ceiling Plaster Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-27C 27	510041070-57 Location: 1st Floor - Office	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Brown/White, Heterogeneous, Fibrous, Cementitious, Ceiling Plaster Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-27D 27	510041070-58 Location: 1st Floor - Office	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Brown/White, Heterogeneous, Fibrous, Cementitious, Ceiling Plaster Asbestos Types: Other Material: Cellulose 1 %, Non-fibrous 99 %			
AS031810JM-27E 27	510041070-59 Location: 1st Floor - Office	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Brown/White, Heterogeneous, Fibrous, Cementitious, Ceiling Plaster Asbestos Types: Other Material: Cellulose 1 %, Non-fibrous 99 %			

PLM Bulk Asbestos Report

16433; ACCA; Broadway, Albany, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-28A 28	510041070-60 Location: 1st Floor - Office	Yes	0.3 % (ELAP 198.1; 400pc) by Ivan H Reyes on 04/10/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Wall Plaster Asbestos Types: Chrysotile 0.3 % Other Material: Animal hair Trace, Cellulose Trace, Non-fibrous 99.7 %			
AS031810JM-28B 28	510041070-61 Location: 1st Floor - Office	Yes	Trace (<0.25 % pc) (ELAP 198.1; 400pc) by Ivan H Reyes on 04/10/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Wall Plaster Asbestos Types: Chrysotile <0.25 % pc Other Material: Animal hair Trace, Cellulose Trace, Non-fibrous 100 %			
AS031810JM-28C 28	510041070-62 Location: 1st Floor - Office	Yes	0.3 % (ELAP 198.1; 400pc) by Ivan H Reyes on 04/10/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Wall Plaster Asbestos Types: Chrysotile 0.3 % Other Material: Animal hair Trace, Cellulose Trace, Non-fibrous 99.7 %			
AS031810JM-28D 28	510041070-63 Location: 1st Floor - Office	Yes	0.3 % (ELAP 198.1; 400pc) by Ivan H Reyes on 04/10/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Wall Plaster Asbestos Types: Chrysotile 0.3 % Other Material: Animal hair 1 %, Cellulose Trace, Non-fibrous 98.7 %			
AS031810JM-28E 28	510041070-64 Location: 1st Floor - Office	Yes	0.3 % (ELAP 198.1; 400pc) by Ivan H Reyes on 04/10/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Wall Plaster Asbestos Types: Chrysotile 0.3 % Other Material: Animal hair 1 %, Cellulose Trace, Non-fibrous 98.7 %			
AS031810JM-29A 29	510041070-65 Location: 1st Floor	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: White, Homogeneous, Non-Fibrous, Structural Column Plaster Skim Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			

PLM Bulk Asbestos Report

16433; ACCA; Broadway, Albany, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-29B 29 Location: 1st Floor	510041070-66	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: White, Homogeneous, Non-Fibrous, Structural Column Plaster Skim Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-29C 29 Location: 1st Floor	510041070-67	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: White, Homogeneous, Non-Fibrous, Structural Column Plaster Skim Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS031810JM-30A 30 Location: 1st Floor	510041070-68	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Structural Column Plaster Sub Asbestos Types: Other Material: Animal hair 2 %, Cellulose Trace, Non-fibrous 98 %			
AS031810JM-30B 30 Location: 1st Floor	510041070-69	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Structural Column Plaster Sub Asbestos Types: Other Material: Animal hair 1 %, Cellulose Trace, Non-fibrous 99 %			
AS031810JM-30C 30 Location: 1st Floor	510041070-70	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Structural Column Plaster Sub Asbestos Types: Other Material: Animal hair 1 %, Cellulose Trace, Non-fibrous 99 %			
AS031810JM-31 Location: 1st Floor Storage	510041070-71	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Off-White/Tan, Homogeneous, Fibrous, Sheetrock Asbestos Types: Other Material: Cellulose 15 %, Non-fibrous 85 %			

PLM Bulk Asbestos Report

16433; ACCA; Broadway, Albany, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-32 Location: Basement	510041070-72	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Off-White/Tan, Homogeneous, Fibrous, Sheetrock Remnant On Ceiling Asbestos Types: Other Material: Cellulose 12 %, Fibrous glass 2 %, Non-fibrous 86 %			
AS031810JM-33A 33 Location: Basement	510041070-73	Yes	57.1 % (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Tan, Homogeneous, Non-Fibrous, Aircell Pipe Insulation Asbestos Types: Chrysotile 57.1 % Other Material: Cellulose 10 %, Non-fibrous 32.9 %			
AS031810JM-33B 33 Location: Basement	510041070-74	Yes	66.7 % (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Tan, Homogeneous, Fibrous, Aircell Pipe Insulation Asbestos Types: Chrysotile 66.7 % Other Material: Non-fibrous 33.3 %			
AS031810JM-33C 33 Location: Basement	510041070-75	Yes	66.7 % (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Tan, Homogeneous, Fibrous, Aircell Pipe Insulation Asbestos Types: Chrysotile 66.7 % Other Material: Non-fibrous 33.3 %			
AS031810JM-34A 34 Location: Basement	510041070-76	Yes	36.4 % (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Off-White, Homogeneous, Fibrous, Mudded Fitting Insulation Asbestos Types: Chrysotile 36.4 % Other Material: Non-fibrous 63.6 %			
AS031810JM-34B 34 Location: Basement	510041070-77	Yes	33.3 % (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Off-White, Homogeneous, Fibrous, Mudded Fitting Insulation Asbestos Types: Chrysotile 33.3 % Other Material: Non-fibrous 66.7 %			

PLM Bulk Asbestos Report

16433; ACCA; Broadway, Albany, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-34C 34 Location: Basement	510041070-78	Yes	36.4 % (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Off-White, Homogeneous, Fibrous, Mudded Fitting Insulation Asbestos Types: Chrysotile 36.4 % Other Material: Non-fibrous 63.6 %			
AS031810JM-35A 35 Location: Basement	510041070-79	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Tan/Black/Silver, Heterogeneous, Fibrous, Fiberglass Insulation Paper Asbestos Types: Other Material: Fibrous glass Trace, Non-fibrous 12.6 %			
AS031810JM-35B 35 Location: Basement	510041070-80	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Tan/Black/Silver, Heterogeneous, Fibrous, Fiberglass Insulation Paper Asbestos Types: Other Material: Fibrous glass Trace, Non-fibrous 12.2 %			
AS031810JM-35C 35 Location: Basement	510041070-81	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/10/10
Analyst Description: Tan/Black/Silver, Heterogeneous, Fibrous, Fiberglass Insulation Paper Asbestos Types: Other Material: Fibrous glass Trace, Non-fibrous 2.2 %			
AS031810JM-36A 36 Location: Basement - Boiler Room	510041070-82	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Grey, Homogeneous, Fibrous, Boiler Packing Insulation Asbestos Types: Other Material: Cellulose Trace, Fibrous glass 25 %, Non-fibrous 75 %			
AS031810JM-36B 36 Location: Basement - Boiler Room	510041070-83	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Analyst Description: Grey, Homogeneous, Fibrous, Boiler Packing Insulation Asbestos Types: Other Material: Cellulose Trace, Fibrous glass 30 %, Non-fibrous 70 %			

PLM Bulk Asbestos Report

16433; ACCA; Broadway, Albany, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-36C 36	510041070-84	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Location: Basement - Boiler Room Analyst Description: Grey, Homogeneous, Fibrous, Boiler Packing Insulation Asbestos Types: Other Material: Cellulose Trace, Fibrous glass 25 %, Non-fibrous 75 %			
AS031810JM-37A 37	510041070-85	Yes	66.7 % (by NYS ELAP 198.1) by Ivan H Reyes on 04/10/10
Location: Basement - Boiler Room Analyst Description: Off-White, Homogeneous, Fibrous, Mag Panel -Heat Shield Asbestos Types: Chrysotile 66.7 % Other Material: Non-fibrous 33.3 %			
AS031810JM-37B 37	510041070-86	Yes	66.7 % (by NYS ELAP 198.1) by Ivan H Reyes on 04/11/10
Location: Basement - Boiler Room Analyst Description: Off-White, Homogeneous, Fibrous, Mag Panel -Heat Shield Asbestos Types: Chrysotile 66.7 % Other Material: Non-fibrous 33.3 %			
AS031810JM-38A 38	510041070-87	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/11/10
Location: Basement - Boiler Room Analyst Description: Black, Homogeneous, Fibrous, Damp Proofing On Wall Asbestos Types: Other Material: Non-fibrous 0.8 %			
AS031810JM-38B 38	510041070-88	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/11/10
Location: Basement - Boiler Room Analyst Description: Black, Homogeneous, Fibrous, Damp Proofing On Wall Asbestos Types: Other Material: Non-fibrous 12.7 %			
AS031810JM-39A 39	510041070-89	Yes	14.4 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/11/10
Location: Basement - Boiler Room Analyst Description: Black, Homogeneous, Fibrous, Roof Field-Bottom Lyr Asbestos Types: Chrysotile 14.4 % Other Material: Non-fibrous 21.5 %			

PLM Bulk Asbestos Report

16433; ACCA; Broadway, Albany, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-39B 39	510041070-90 Location: Basement - Boiler Room	Yes	13 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/11/10
Analyst Description: Black, Homogeneous, Fibrous, Roof Field-3rd Lyr Asbestos Types: Chrysotile 13.0 % Other Material: Non-fibrous 25.9 %			
AS031810JM-39C 39	510041070-91 Location: Basement - Boiler Room	Yes	15.2 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/11/10
Analyst Description: Black, Homogeneous, Fibrous, Roof Field-2nd Lyr Asbestos Types: Chrysotile 15.2 % Other Material: Non-fibrous 19 %			
AS031810JM-39D 39	510041070-92 Location: Basement - Boiler Room	Yes	12.7 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/11/10
Analyst Description: Black, Homogeneous, Fibrous, Roof Field-Top Lyr Asbestos Types: Chrysotile 12.7 % Other Material: Non-fibrous 22.2 %			
AS031810JM-40A 40	510041070-93 Location: Basement - Boiler Room	Yes	1.9 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/11/10
Analyst Description: Black, Homogeneous, Fibrous, Roof Flashing-Btm Pitch Lyr Asbestos Types: Chrysotile 1.9 % Other Material: Non-fibrous 5.7 %			
AS031810JM-40B 40	510041070-94 Location: Basement - Boiler Room	Yes	13.5 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/11/10
Analyst Description: Black, Homogeneous, Fibrous, Roof Flashing-Btm BUR Asbestos Types: Chrysotile 13.5 % Other Material: Non-fibrous 20.2 %			
AS031810JM-40C 40	510041070-95 Location: Basement - Boiler Room	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/11/10
Analyst Description: Black, Homogeneous, Fibrous, Roof Flashing-3rd Lyr Asbestos Types: Other Material: Non-fibrous 8.3 %			

PLM Bulk Asbestos Report

16433; ACCA; Broadway, Albany, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS031810JM-40D 40	510041070-96 Location: Basement - Boiler Room	Yes	9.8 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/11/10
Analyst Description: Black, Homogeneous, Fibrous, Roof Flashing-2nd Lyr Asbestos Types: Chrysotile 9.8 % Other Material: Non-fibrous 14.6 %			
AS031810JM-40E 40	510041070-97 Location: Basement - Boiler Room	Yes	6.6 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/11/10
Analyst Description: Black, Homogeneous, Fibrous, Roof Flashing-Top Lyr Asbestos Types: Chrysotile 6.6 % Other Material: Non-fibrous 14.9 %			
AS031810JM-41A 41	510041070-98 Location: Basement - Boiler Room	Yes	5.1 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/11/10
Analyst Description: Black, Homogeneous, Fibrous, Flashing Sealant Asbestos Types: Chrysotile 5.1 % Other Material: Non-fibrous 12.6 %			
AS031810JM-41B 41	510041070-99 Location: Basement - Boiler Room	Yes	12.7 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/11/10
Analyst Description: Black, Homogeneous, Fibrous, Flashing Sealant Asbestos Types: Chrysotile 12.7 % Other Material: Non-fibrous 38.1 %			
AS031810JM-42A 42	510041070-100 Location: Parapet Wall	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/11/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Coping Stone Grout Asbestos Types: Other Material: Non-fibrous 100 %			
AS031810JM-42B 42	510041070-101 Location: Parapet Wall	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/11/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Coping Stone Grout Asbestos Types: Other Material: Non-fibrous 100 %			

PLM Bulk Asbestos Report

16433; ACCA; Broadway, Albany, NY

Reporting Notes:

Analyzed by: Ivan H Reyes ; Date Analyzed: 

NAD = no asbestos detected; CVES = Calibrated Visual Estimate; NA = not analyzed; NA/PS = not analyzed / positive stop; "Present" or NVA = "No Visible Asbestos" are observations made during a qualitative analysis; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #102079-0) or NY ELAP PLM Analysis Protocol 198.1 for New York friable samples (198.6 for NOB samples) (NY ELAP Lab # 10982); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. NAD or Trace results by PLM are inconclusive, TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). NIST Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested.

Reviewed By: _____

Relinquished By:
Received By:
Relinquished By:

Received By:

Signature

Date/Time:
Date/Time:
Date/Time:

Date/Time:

Project:

Scias #:

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

CHIA

CLIA CERTIFIED

510041070

Street Address: 3 Winners Circle

Project #:

City: Albany State: NY Zip: 12205

Project Address:
Project Manager:

Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: imoretz@che-ill.com Call: (315) 440-1670

Analysis: ☐ PLM Only ☐ TEM Only ☐ NY ELAP PLM/TEM with NOB Prep.
☐ ASTM Dust (microwave) ☐ ASTM Dust (Wipe)) Other (describe in comments)

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Material Type: ☐ Bulk ☐ Dust

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID

Location

Sample Description
(for dust= size of surface area sampled)

Homogenous Air
(HA #)

17	08A	Beige 12X12 Floor Tile		
18	08B	"		
19	09A	Underlayment to Beige Floor Tile		
20	09B	"		
21	10A	Floor Paper	3rd Floor	
22	10B	"	"	
23	11A	Gray 12X12 Floor Tile	4th Fl.	
24	11B	"	"	
25	12A	Green 12X12 Floor Tile	1st Fl.	
26	12B	"	"	
27	13A	4" Gray Cor. Base	"	
28	13B	"	"	
29	14A	Mastic to 4" Gray Cor. Base	"	
30	14B	"	"	

Relinquished By:
Received By:
Relinquished By:

Received By:

Debra H. Miller

Company:

CHIA

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12205

Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@chia-llp.com Cell: (315) 440-1670

Results to: Jim Morey 3 Winners Circle Albany, NY 12205
Special Instructions or Comments:

Date/Time:
Date/Time:
Date/Time:

Date/Time:

Project:

Scans #:

510041070



AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
www.AmeriSci.com

Project Address:

Project #:

Project Manager:

Analysis: ☐ PLM Only ☐ TEM Only ☐ NY ELAP PLM/TEM with NOB Prep.
☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe)) Other (describe in comment:

E-Mail Results: Yes

Turnaround Time:

Material Type: ☐ Bulk ☐ Dust

Sampled By:


Date Sampled:

Field ID	Location	Sample Description (for dusts size of surface area sampled)	Homogenous Air (HA #)
31	4" Brown Core Board	1 1/2" Fl.	
32	"	"	
33	MASTIC to 4" Brown Core Board	"	
34	"	"	
35	TAC Clay Tile	1 1/2" Fl.	
36	Brown Clay Tile		
37	Coat to TAC + Brown Tile	↓	
38	"		
39	Clay Floor	2nd Floor	
40	"		
41	Brown Ceramic Tile	1st Fl.	
42	"		
43	Coat to Ceramic Tile	↓	
44	"		
45	IX1 Ceiling Tile	2nd Fl.	
46	"	"	

Relinquished By:
Received By:
Relinquished By:

Date/Time:
Date/Time:
Date/Time:

Date/Time:



AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
www.AmeriSci.com

Received By: *Sept 10/04*



510041070

CHA CHA HARBOR & ASSOCIATES, LLC

Company:

Street Address: 3 Winners Circle

Project Address:

Project #:

City: Albany State: NY Zip: 12206

Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: info@echa-llp.com Cell: (518) 440-1670

Home/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Material Type: Bulk Dust

Results to: Jim Morey 3 Winners Circle Albany, NY 12206

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Air (HA #)
47	23A	Wall 6(02	1st Floor
48	23B	"	"
49	24A	Ceiling Insulation Board	Storage Area
50	24B	"	"
51	25A	Sheetrock	1st Floor - Office
52	25B	"	" - Storage
53	26A	Saint Compound	1st Floor - Office
54	26B	"	"
55	27A	Ceiling Plaster	"
56	27B	"	"
57	27C	"	"
58	27D	"	"
59	27E	"	"

Relinquished By:
Received By:
Relinquished By:

Date/Time:
Date/Time:
Date/Time:

Date/Time:

AmeriSci Boston
8 School Street
Weymouth, MA 02186
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
www.AmeriSci.com

Received By:

Date/Time:

Sept 16, 2004

Company:

CH2A

CH2A NATIONAL LABORATORY

Street Address: 3 Winners Circle

Project Address:

Project #:

City: Albany

State: NY

Zip: 12206

Project Manager:

Phone: (518) 463-3916

Fax: (518) 463-4773

E-Mail: lmory@ch2a-llp.com

Cell: (518) 440-1670

Analysis: ☐ PLM Only ☐ TEM Only ☐ NY ELAP PLM/TEM with NOB Prep.

☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe)) ☐ Other (describe in comments)

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Material Type: ☐ Bulk ☐ Dust ☐ Other

Results to: Jim Morey 3 Winners Circle Albany, NY 12206

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID	Location	Sample Description (for dusts - size of surface area sampled)	Homogenous Air (HA #)
00 28A	Wall Plaster		
01 28B			
02 28C			
03 28D			
04 28E			
05 29A	Structural Column Plaster-Skion	1st Fl.	
06 29B			
07 29C			
08 30A			
09 30B			
10 30C			
11 31			
12 32			
13 33A			
14 33B			
15 33C			

Sheetrock
Sheetrock Remnant (on Ceiling)
Air cell Pipe Insulation

1st Floor Storage
Document

Relinquished By:
Received By:
Relinquished By:

Date/Time:
Date/Time:
Date/Time:

Date/Time:

AmSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (888) 724-5221
WWW.AMERISCI.COM

Received By:

Date/Time:

Project:

SciLab #:

Company:

CHIA

510041070

Street Address: 3 Winners Circle

Project Address:

Project #:

City: Albany

State: NY

Zip: 12206

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jmorey@cha-llp.com

Cell: (315) 440-1670

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Material Type:

Bulk Dust

Results to: Jim Morey 3 Winners Circle Albany, NY 12206

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID	Location	Sample Description (for dusts size of surface area sampled)	Homogenous Air (HA #)
76	34A	Muddled Fitting Insulation	
77	34B	"	
78	34C	"	
79	35A	Fiberglass Insulation Paper	
80	35B	"	
81	35C	"	
82	36A	Boiler Packing Insulation	
83	36B	"	
84	36C	"	
85	37A	"Mag" Panel - Heat Shield	
86	37B	"	
87	38A	Black Damp Proofing on Wall	
88	38B	"	

Relinquished By:
Received By:
Relinquished By:

Date/Time:
Date/Time:
Date/Time:

Date/Time:

Received By: *Josephine Miller*

Project:

SciLab #:

Company:

CHA

CHACHAR HARBOR & MARCUTT LLP

Street Address: 3 Winners Circle

Project Address:

Project #:

510041070

City: Albany

State: NY

Zip: 12206

Phone: (518) 453-3915

Fax: (518) 453-4773

E-Mail: jmorey@cha-llp.com

Cell: (315) 440-1670

Site/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Material Type:

Material Type: Bulk Dust

Results to: Jim Morey 3 Winners Circle Albany, NY 12206

Sampled By:

Date Sampled:

Special Instructions or Comments:

Field ID

Location

Sample Description
(for dust size of surface area sampled)

Homogenous Air
(HA #)

39 39A
40 39B
41 39C
42 39D
43 40A
44 40B
45 40C
46 40D
47 40E
48 41A
49 41B
50 42A
51 42B

Roof - Field - Bottom Layer
" - 1st Layer
" - 2nd Layer
" - Top Layer
Roof Flashing - Bottom Pitch Layer
" - Bottom B.V.R.
" - 3rd Layer
" - 2nd Layer
" - Top Layer
Flashing Sealant
" -
Coping Stone Count
" - Parapet Wall

Table I
Summary of Bulk Asbestos Analysis Results

16433; ACCA; Broadway, Albany, NY

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
01 Location: 1st Floor	AS031810JM-01A	1	----	----	----	----	Chrysotile 44.4	NA
02 Location: 1st Floor	AS031810JM-01B	1	----	----	----	----	NA/PS	NA
03 Location: 1st Floor	AS031810JM-01C	1	----	----	----	----	NA/PS	NA
04 Location: 1st Floor	AS031810JM-02A	2	----	----	----	----	Chrysotile 18.2	NA
05 Location: 1st Floor	AS031810JM-02B	2	----	----	----	----	Chrysotile 22.2	NA
06 Location: 1st Floor	AS031810JM-02C	2	----	----	----	----	Chrysotile 20.0	NA
07 Location: 1st Floor	AS031810JM-03A	3	0.205	32.9	50.5	16.6	NAD	NAD
08 Location: 1st Floor	AS031810JM-03B	3	0.189	94.8	1.5	3.7	NAD	NAD
09 Location: Exterior Of Building	AS031810JM-04A	4	0.565	12.3	80.1	7.6	Chrysotile <0.25	NAD
10 Location: Exterior Of Building	AS031810JM-04B	4	0.421	14.2	76.6	9.2	NAD	NAD
11 Location: 4th Floor	AS031810JM-05A	5	----	----	----	----	NAD	NA
12 Location: 4th Floor	AS031810JM-05B	5	----	----	----	----	NAD	NA
13 Location: Stair Landing	AS031810JM-06A	6	0.184	81.8	15.2	3.0	NAD	NAD
14 Location: Stair Landing	AS031810JM-06B	6	0.172	82.0	15.1	2.9	NAD	NAD
15 Location: 4th Floor	AS031810JM-07A	7	0.367	33.2	26.3	35.6	Chrysotile 4.9	NA
16 Location: 4th Floor	AS031810JM-07B	7	0.219	32.8	20.7	39.3	Chrysotile 7.1	NA

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Broadway, Albany, NY

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
17 Location: 4th Floor	AS031810JM-08A	8	0.226	32.3	35.3	26.4	Chrysotile 5.9	NA
18 Location: 4th Floor	AS031810JM-08B	8	0.227	35.6	40.7	19.0	Chrysotile 4.7	NA
19 Location: 4th Floor	AS031810JM-09A	9	0.260	36.6	25.0	34.6	Chrysotile 3.8	NA
20 Location: 4th Floor	AS031810JM-09B	9	0.150	58.2	12.6	26.3	Chrysotile 2.9	NA
21 Location: 3rd Floor	AS031810JM-10A	10	0.247	88.0	6.0	6.0	NAD	NAD
22 Location: 3rd Floor	AS031810JM-10B	10	0.087	92.4	3.6	4.0	NAD	NAD
23 Location: 4th Floor	AS031810JM-11A	11	0.230	23.0	22.4	46.8	Chrysotile 7.8	NA
24 Location: 4th Floor	AS031810JM-11B	11	0.329	23.3	32.5	38.8	Chrysotile 5.4	NA
25 Location: 1st Floor	AS031810JM-12A	12	0.361	22.8	24.8	41.9	Chrysotile 10.5	NA
26 Location: 1st Floor	AS031810JM-12B	12	0.190	22.5	26.0	40.1	Chrysotile 11.4	NA
27 Location: 1st Floor	AS031810JM-13A	13	0.204	28.7	70.2	1.1	NAD	Chrysotile Trace
28 Location: 1st Floor	AS031810JM-13B	13	0.184	29.9	69.1	1.0	NAD	NAD
29 Location: 1st Floor	AS031810JM-14A	14	0.109	52.9	3.9	43.2	NAD	NAD
30 Location: 1st Floor	AS031810JM-14B	14	0.068	44.2	23.7	32.1	NAD	NAD
31 Location: 1st Floor	AS031810JM-15A	15	0.236	26.6	69.5	3.9	NAD	NAD
32 Location: 1st Floor	AS031810JM-15B	15	0.288	26.1	70.9	2.9	NAD	NAD

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results

16433; ACCA; Broadway, Albany, NY

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
33 Location: 1st Floor	AS031810JM-16A	16	0.237	53.8	15.1	31.0	NAD	NAD
34 Location: 1st Floor	AS031810JM-16B	16	0.141	69.9	3.4	26.7	NAD	NAD
35 Location: 1st Floor	AS031810JM-17A	17	---	---	---	---	NAD	NA
36 Location: 1st Floor	AS031810JM-17B	17	---	---	---	---	NAD	NA
37 Location: 1st Floor	AS031810JM-18A	18	---	---	---	---	NAD	NA
38 Location: 1st Floor	AS031810JM-18B	18	---	---	---	---	NAD	NA
39 Location: 2nd Floor	AS031810JM-19A	19	---	---	---	---	Chrysotile 1.3	NA
40 Location: 2nd Floor	AS031810JM-19B	19	---	---	---	---	Chrysotile 1.5	NA
41 Location: 1st Floor	AS031810JM-20A	20	---	---	---	---	NAD	NA
42 Location: 1st Floor	AS031810JM-20B	20	---	---	---	---	NAD	NA
43 Location: 1st Floor	AS031810JM-21A	21	---	---	---	---	NAD	NA
44 Location: 1st Floor	AS031810JM-21B	21	---	---	---	---	NAD	NA
45 Location: 2nd Floor	AS031810JM-22A	22	---	---	---	---	NAD	NA
46 Location: 2nd Floor	AS031810JM-22B	22	---	---	---	---	NAD	NA
47 Location: 1st Floor	AS031810JM-23A	23	0.102	55.6	16.0	25.6	Chrysotile 2.8	NA
48 Location: 1st Floor	AS031810JM-23B	23	0.080	58.0	12.5	26.6	Chrysotile 3.0	NA

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Broadway, Albany, NY

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
49	AS031810JM-24A Location: Storage Area	24	----	----	----	----	Chrysotile 66.7	NA
50	AS031810JM-24B Location: Storage Area	24	----	----	----	----	Chrysotile 66.7	NA
51	AS031810JM-25A Location: 1st Floor - Office	25	----	----	----	----	NAD	NA
52	AS031810JM-25B Location: 1st Floor - Storage	25	----	----	----	----	NAD	NA
53	AS031810JM-26A Location: 1st Floor - Office	26	----	----	----	----	NAD	NA
54	AS031810JM-26B Location: 1st Floor - Office	26	----	----	----	----	NAD	NA
55	AS031810JM-27A Location: 1st Floor - Office	27	----	----	----	----	NAD	NA
56	AS031810JM-27B Location: 1st Floor - Office	27	----	----	----	----	NAD	NA
57	AS031810JM-27C Location: 1st Floor - Office	27	----	----	----	----	NAD	NA
58	AS031810JM-27D Location: 1st Floor - Office	27	----	----	----	----	NAD	NA
59	AS031810JM-27E Location: 1st Floor - Office	27	----	----	----	----	NAD	NA
60	AS031810JM-28A Location: 1st Floor - Office	28	----	----	----	----	Chrysotile 0.3	NA
61	AS031810JM-28B Location: 1st Floor - Office	28	----	----	----	----	Chrysotile <0.25	NA
62	AS031810JM-28C Location: 1st Floor - Office	28	----	----	----	----	Chrysotile 0.3	NA
63	AS031810JM-28D Location: 1st Floor - Office	28	----	----	----	----	Chrysotile 0.3	NA
64	AS031810JM-28E Location: 1st Floor - Office	28	----	----	----	----	Chrysotile 0.3	NA

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Broadway, Albany, NY

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
65	AS031810JM-29A	29	----	-----	-----	-----	NAD	NA
Location:	1st Floor							
66	AS031810JM-29B	29	----	-----	-----	-----	NAD	NA
Location:	1st Floor							
67	AS031810JM-29C	29	----	-----	-----	-----	NAD	NA
Location:	1st Floor							
68	AS031810JM-30A	30	----	-----	-----	-----	NAD	NA
Location:	1st Floor							
69	AS031810JM-30B	30	----	-----	-----	-----	NAD	NA
Location:	1st Floor							
70	AS031810JM-30C	30	----	-----	-----	-----	NAD	NA
Location:	1st Floor							
71	AS031810JM-31		----	-----	-----	-----	NAD	NA
Location:	1st Floor Storage							
72	AS031810JM-32		----	-----	-----	-----	NAD	NA
Location:	Basement							
73	AS031810JM-33A	33	----	-----	-----	-----	Chrysotile 57.1	NA
Location:	Basement							
74	AS031810JM-33B	33	----	-----	-----	-----	Chrysotile 66.7	NA
Location:	Basement							
75	AS031810JM-33C	33	----	-----	-----	-----	Chrysotile 66.7	NA
Location:	Basement							
76	AS031810JM-34A	34	----	-----	-----	-----	Chrysotile 36.4	NA
Location:	Basement							
77	AS031810JM-34B	34	----	-----	-----	-----	Chrysotile 33.3	NA
Location:	Basement							
78	AS031810JM-34C	34	----	-----	-----	-----	Chrysotile 36.4	NA
Location:	Basement							
79	AS031810JM-35A	35	0.114	83.2	4.1	12.6	NAD	NAD
Location:	Basement							
80	AS031810JM-35B	35	0.172	83.0	4.8	12.2	NAD	NAD
Location:	Basement							

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Broadway, Albany, NY

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
81	AS031810JM-35C	35	0.148	87.0	10.8	2.2	NAD	NAD
Location:	Basement							
82	AS031810JM-36A	36	----	-----	-----	----	NAD	NA
Location:	Basement - Boiler Room							
83	AS031810JM-36B	36	----	-----	-----	----	NAD	NA
Location:	Basement - Boiler Room							
84	AS031810JM-36C	36	----	-----	-----	----	NAD	NA
Location:	Basement - Boiler Room							
85	AS031810JM-37A	37	----	-----	-----	----	Chrysotile 66.7	NA
Location:	Basement - Boiler Room							
86	AS031810JM-37B	37	----	-----	-----	----	Chrysotile 66.7	NA
Location:	Basement - Boiler Room							
87	AS031810JM-38A	38	0.273	98.0	1.2	0.8	NAD	NAD
Location:	Basement - Boiler Room							
88	AS031810JM-38B	38	0.242	86.4	0.9	12.7	NAD	NAD
Location:	Basement - Boiler Room							
89	AS031810JM-39A	39	0.162	56.3	7.8	21.5	Chrysotile 14.4	NA
Location:	Basement - Boiler Room							
90	AS031810JM-39B	39	0.151	54.8	6.3	25.9	Chrysotile 13.0	NA
Location:	Basement - Boiler Room							
91	AS031810JM-39C	39	0.148	59.3	6.4	19.0	Chrysotile 15.2	NA
Location:	Basement - Boiler Room							
92	AS031810JM-39D	39	0.184	58.8	6.2	22.2	Chrysotile 12.7	NA
Location:	Basement - Boiler Room							
93	AS031810JM-40A	40	0.156	89.3	3.1	5.7	Chrysotile 1.9	NA
Location:	Basement - Boiler Room							
94	AS031810JM-40B	40	0.271	59.9	6.3	20.2	Chrysotile 13.5	NA
Location:	Basement - Boiler Room							
95	AS031810JM-40C	40	0.226	85.5	6.3	8.3	NAD	NAD
Location:	Basement - Boiler Room							
96	AS031810JM-40D	40	0.258	70.2	5.4	14.6	Chrysotile 9.8	NA
Location:	Basement - Boiler Room							

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA; Broadway, Albany, NY

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
97	AS031810JM-40E	40	0.221	74.6	3.9	14.9	Chrysotile 6.6	NA
Location:	Basement - Boiler Room							
98	AS031810JM-41A	41	0.214	74.8	7.5	12.6	Chrysotile 5.1	NA
Location:	Basement - Boiler Room							
99	AS031810JM-41B	41	0.261	40.4	8.8	38.1	Chrysotile 12.7	NA
Location:	Basement - Boiler Room							
100	AS031810JM-42A	42	----	----	----	----	NAD	NA
Location:	Parapet Wall							
101	AS031810JM-42B	42	----	----	----	----	NAD	NA
Location:	Parapet Wall							

Reviewed by: _____ Date Reviewed: _____ Analyzed By: Sandhya Gunasekara *Sandhya* Date Analyzed: 4/13/2010

Semi-Quantitative Analysis: NAD = no asbestos detected; NA = not analyzed; NA/PS = not analyzed due to positive stop; Trace = <1%;
 PLM analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #102079-0) or NY ELAP 198.6 for New York NOB samples (NY ELAP Lab # 10982);
 TEM analysis by EPA 600/R-93/116 (not covered by NVLAP Bulk accreditation) or NY ELAP 198.4 for New York NOB samples (NY ELAP Lab # 10982);

** Warning Notes: Consider PLM fiber diameter limitation, only TEM will resolve fibers <0.25 micrometers in diameter. TEM bulk analysis is representative of the fine grained matrix material and may not be representative of non-uniformly dispersed debris, soils or other heterogeneous materials for which a combination PLM/TEM evaluation is recommended; Quantitation for beginning weights of <0.1 grams should be considered as qualitative only.

Relinquished By: [Signature]
Received By: [Signature]
Relinquished By: [Signature]

Received By: [Signature]

Company:

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12205
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@chs-llp.com Cell: (315) 440-1670

Site/Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

All samples received by: (AS0318105M)

E-Mail Results: Yes

Date/Time: 3/25/10
Date/Time:
Date/Time:
Date/Time: 4/5/10

Project:

CHA
CLASH HIRE OF & ASSOCIATES LLP

ACCA

Scilas #:

510041070

Project Address: Basking, Albany, NY.

Project Manager: Seth Faden

Analysis: PLM Only TEM Only NY ELAP PLM/TEM with NOB Prep.
ASTM Dust (microvac) ASTM Dust (Wipe) Other (describe in comments)

Turnaround Time: 5-DAY

Material Type: Bulk Dust

Date Sampled: 3/18/10

Sampled By: J. Morey

Field ID

Location

Sample Description

(for dust= size of surface area sampled)

Homogenous Air (HA #)

1 01A
2 01B
3 01C
4 02A
5 02B
6 02C
7 03A
8 03B
9 04A
10 04B
11 05A
12 05B
13 06A
14 06B
15 07A
16 07B

Arcecl Pipe Insulation

Mudded Fitting Insulation

Fiberglass Insulation Paper

Exterior Window Glazing Compound

Floor Leveling Compound

Green Linoleum Flooring

12x12 Floor Tile - white
12x12 Floor Tile - white

1st Floor

"

"

"

"

"

1st Fl.

"

4th Floor

"

4th Floor

Stair Landing

"

4th Floor

"

Positive Stop
↓

Relinquished By:
Received By:
Relinquished By:

Received By:

Signature

CHA

CHALLENGE HARDWARE & ASSOCIATES LLP

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12206
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670

Site/Secondary Fax #: E-Mail Results: Yes
Results to: Jim Morey 3 Winners Circle Albany, NY 12206
Special Instructions or Comments:

Date/Time:
Date/Time:
Date/Time:
Date/Time:

Project:

SCILAB #:

Project Address:

Project Manager:

Analysis: PLM Only TEM Only NY ELAP PLM/TEM with NOB Prep.

ASTM Dust (microvac) ASTM Dust (Wipe) Other (describe in comments)

Turnaround Time:

Sampled By:

Date Sampled:

Material Type: Bulk Dust

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

AMERISCI
BOSTON

510041070

Project #:

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Air (HA #)
17 08A	Beige 12X12 Floor Tile		
18 08B	"		
19 09A	Underlayment to Beige Floor Tile		
20 09B	"		
21 10A	Floor Paper	3 rd Floor	
22 10B	"	"	
23 11A	Gray 12X12 Floor Tile	4 th Fl.	
24 11B	"	"	
25 12A	Green 12X12 Floor Tile	1 st Fl.	
26 12B	"	"	
27 13A	4" Gray Cove Base	"	
28 13B	"	"	
29 14A	Mastic to 4" Gray Cove Base	"	
30 14B	"	"	

Date/Time: _____

Date/Time: _____

Date/Time: _____

Date/Time: _____

Received By:

Date/Time:

Project: _____

Company:

street Address: 3 Winners Circle

Project Address:

Project #:

ity: Albany

State: NY Zip: 12205

Project Hanger:

home: (518) 453-3915

Fax: (518) 463-4773

Analysis: PLM Only

Analysis: PLM Only TEM Only NY ELAP PLM/TEM with NOB Prep.
ASTM Dust (microvac) ASTM Dust (Wipe) Other (describe in comment)

-Mail: jmorey@cha-llp.com

Cell: (315) 440-1670

— **ASTM Dust (microv**

(Wipe)) Other (describe in comments)

Material Type: Bulk Dust

ite/Secondary Fax #:

E-Mail Results: Yes

Turnaround Time:

Results to: Jim Morey 3 Winners Circle Albany, NY 12206

Sampled By:

Special Instructions or Comments:

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Area (HA #)
31 15A	4" Brown Cove Base	1 st Fl.	
32 15B	"	"	
33 16A	MASTIC to 4" Brown Cove Base	"	
34 16B	"	"	
35 17A	TAN Clay Tile	1 st Fl.	
36 17B	Brown Clay Tile		
37 18A	Grout to TAN + Brown Tiles		
38 18B	"		
39 19A	Clay Floor	2 nd Floor	
40 19B	"		
41 20A	Brown Ceramic Tile	1 st Fl.	
42 20B	"		
43 21A	Grout to Ceramic Tile		
44 21B	"		
45 22A	IXL Ceiling Tile	2 nd Fl.	
46 22B	"	"	

Relinquished By:
Received By:
Relinquished By:

Received By:

Date/Time:
Date/Time:
Date/Time:
Date/Time:

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

CHA
CLIA CH NABOIR & ASSOCIATES LLP

SCILAB #:

510041070

Company:

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12205
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670

Site/Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

Project Address:

Project Manager:

Analysis: ☐ PLM Only ☐ TEM Only ☐ NY ELAP PLM/TEM with NOB Prep.
☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe) ☐ Other (describe in comments)

Turnaround Time:

Sampled By:

Material Type: ☐ Bulk ☐ Dust

Date Sampled:

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Air (HA #)
47 23A	WALL 6(U.C.	1st Floor	
48 23B	"	"	
49 24A	Ceiling Insulation Board	Storage Area	
50 24B	"	"	
51 25A	Sheetrock	1st Floor - office	
52 25B	"	" - storage	
53 26A	Joint Compound	1st Fl. - office	
54 26B	"	"	
55 27A	Ceiling Plaster	"	
56 27B	"	"	
57 27C	"	"	
58 27D	"	"	
59 27E	"	"	

Relinquished By:
Received By:
Relinquished By:

Received By:

Date/Time:
Date/Time:
Date/Time:
Date/Time:

Company:

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12205
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@cicha-llp.com Cell: (315) 440-1670

Site/Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

E-Mail Results: Yes

Turnaround Time:

Sampled By:

Date Sampled:

Project Address:

Project Manager:

Analysis: ☐ PLM Only ☐ TEM Only ☐ NY ELAP PLM/TEM with NOB Prep.
☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe) ☐ Other (describe in comments)

Material Type: ☐ Bulk ☐ Dust

Project:

SCILAS #:



CICHA NATIONAL ASSOCIATE LLP

510041070



AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (888) 724-5221
WWW.AMERISCI.COM

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Air (HA #)
28A	Wall Plaster		
28B			
28C			
28D			
28E			
29A	Structural Column Plaster-Skin	1st Fl.	
29B	"	"	
29C	"	"	
30A	-Sub	"	
30B	"	"	
30C	"	"	
31	Sheetrock	1st Floor Storage	
32	Sheetrock Remnant (on Ceiling)	Document	
33A	Air cell pipe insulation	"	
33B	"	"	
33C	"	"	

AmSci Boston
 8 School Street
 Weymouth, MA 02189
 Phone: (781) 337-9334
 Fax: (781) 337-7642
 TOLL FREE: (888) 724-5221
 WWW.AMERISCI.COM



Date/Time: _____
 Date/Time: _____
 Date/Time: _____
 Date/Time: _____

Signature
CHA
CHUGH NABOUR & ASSOCIATES LLP

Received By: _____ SciLab #: _____

Project: **510041070**

Project Address: _____ Project #: _____
 Project Manager: _____
 Analysis: PLM Only TEM Only NY ELAP PLM/TEM with NOB Prep.
ASTM Dust (microvac) ASTM Dust (Wipe) Other (describe in comments)
 Material Type: Bulk Dust
 Turnaround Time: _____ Date Sampled: _____
 Sampled By: _____
 E-Mail Results: Yes _____
 Results to: **Jim Morey 3 Winners Circle Albany, NY 12205**

Special Instructions or Comments: _____

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Ar (HA #)
76 34A	Insulated Fitting Insulation	Insulation	
77 34B	"	"	
78 34C	"	"	
79 35A	Fiberglass Insulation Paper	"	
80 35B	"	"	
81 35C	"	"	
82 36A	Boiler Packer Insulation	" - Bulk - Run	
83 36B	"	"	
84 36C	"	"	
85 37A	"Mag" Panel - Heat Shield	"	
86 37B	"	"	
87 38A	Black Damp - Roofing on Wall	"	
88 38B	"	"	

Relinquished By:
Received By:
Relinquished By:

Received By:

Date/Time:
Date/Time:
Date/Time:

Date/Time:



CITY OF ALBANY, ASSOCIATES LLP

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12205
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670

Site/Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

E-Mail Results: Yes

Turnaround Time:

Sampled By:

Date Sampled:

Project Address:

Project Manager:

Analysis: ☐ PLM Only ☐ TEM Only ☐ NY ELAP PLM/TEM with NOB Prep.
☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe) ☐ Other (describe in comments)

Material Type: ☐ Bulk ☐ Dust ☐

Project #:

Project:

SciLab #:

510041070



AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (888) 724-5221
WWW.AMERISCI.BOSTON

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Air (HA #)
89-39A	Roof - Field - Bottom Layer		
90-39B	" - 2nd Layer		
91-39C	" - 2nd Layer		
92-39D	" - Top Layer		
93-40A	Roof Flashing - Bottom Pitch Layer		
94-40B	" - Bottom B.V.R.		
95-40C	" - 3rd Layer		
96-40D	" - 2nd Layer		
97-40E	" - Top Layer		
98-41A	Flashing. Sealant		
99-41B	"		
100-42A	Coping Stone Groat	Parapet Wall	
101-42B	"	"	

PLM Bulk Asbestos Report

Clough, Harbour & Associates

Attn: Jim Morey

3 Winners Circle

Albany, NY 12205

Date Received 03/31/10

Date Examined 04/01/10

ELAP # 10982

RE: 16433; ACCA

AmeriSci Job # 510031331

P.O. #
Page 1 **of** 16

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032210JM-01A 1 Location: 2nd Floor	510031331-01	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Textured Ceiling Paint Asbestos Types: Other Material: Non-fibrous 39.4 %			
AS032210JM-01B 1 Location: 2nd Floor	510031331-02	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Textured Ceiling Paint Asbestos Types: Other Material: Non-fibrous 35.5 %			
AS032210JM-01C 1 Location: 2nd Floor	510031331-03	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Textured Ceiling Paint Asbestos Types: Other Material: Non-fibrous 33.1 %			
AS032210JM-02A 2 Location: 2nd Floor	510031331-04	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Ceiling Plaster - Skimcoat Asbestos Types: Other Material: Non-fibrous 100 %			
AS032210JM-02B 2 Location: 2nd Floor	510031331-05	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Ceiling Plaster - Skimcoat Asbestos Types: Other Material: Non-fibrous 100 %			

PLM Bulk Asbestos Report

16433; ACCA

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032210JM-02C 2 Location: 2nd Floor	510031331-06	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Ceiling Plaster - Skimcoat Asbestos Types: Other Material: Non-fibrous 100 %			
AS032210JM-02D 2 Location: 3rd Floor	510031331-07	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Ceiling Plaster - Skimcoat Asbestos Types: Other Material: Non-fibrous 100 %			
AS032210JM-02E 2 Location: 3rd Floor	510031331-08	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Ceiling Plaster - Skimcoat Asbestos Types: Other Material: Non-fibrous 100 %			
AS032210JM-03A 3 Location: 2nd Floor	510031331-09	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Ceiling Plaster - Subcoat Asbestos Types: Other Material: Animal hair 1 %, Cellulose Trace, Non-fibrous 99 %			
AS032210JM-03B 3 Location: 2nd Floor	510031331-10	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Ceiling Plaster - Subcoat Asbestos Types: Other Material: Animal hair 1 %, Cellulose Trace, Non-fibrous 99 %			
AS032210JM-03C 3 Location: 2nd Floor	510031331-11	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Ceiling Plaster - Subcoat Asbestos Types: Other Material: Animal hair 2 %, Cellulose Trace, Non-fibrous 98 %			

PLM Bulk Asbestos Report

16433; ACCA

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032210JM-03D 3 Location: 3rd Floor	510031331-12	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Ceiling Plaster - Subcoat Asbestos Types: Other Material: Animal hair 1 %, Cellulose Trace, Non-fibrous 99 %			
AS032210JM-03E 3 Location: 3rd Floor	510031331-13	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Ceiling Plaster - Subcoat Asbestos Types: Other Material: Animal hair 2 %, Cellulose Trace, Non-fibrous 98 %			
AS032210JM-04A 4 Location: 2nd Floor	510031331-14	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Wall Plaster - Skimcoat Asbestos Types: Other Material: Non-fibrous 100 %			
AS032210JM-04B 4 Location: 2nd Floor	510031331-15	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Wall Plaster - Skimcoat Asbestos Types: Other Material: Non-fibrous 100 %			
AS032210JM-04C 4 Location: 2nd Floor	510031331-16	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Wall Plaster - Skimcoat Asbestos Types: Other Material: Non-fibrous 100 %			
AS032210JM-04D 4 Location: 3rd Floor	510031331-17	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Wall Plaster - Skimcoat Asbestos Types: Other Material: Non-fibrous 100 %			

PLM Bulk Asbestos Report

16433; ACCA

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032210JM-04E 4 Location: 3rd Floor	510031331-18	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Wall Plaster - Skimcoat Asbestos Types: Other Material: Non-fibrous 100 %			
AS032210JM-04F 4 Location: 3rd Floor	510031331-19	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Wall Plaster - Skimcoat Asbestos Types: Other Material: Non-fibrous 100 %			
AS032210JM-04G 4 Location: 3rd Floor	510031331-20	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Wall Plaster - Skimcoat Asbestos Types: Other Material: Non-fibrous 100 %			
AS032210JM-05A 5 Location: 2nd Floor	510031331-21	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Wall Plaster - Subcoat Asbestos Types: Other Material: Cellulose 1 %, Non-fibrous 99 %			
AS032210JM-05B 5 Location: 2nd Floor	510031331-22	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Wall Plaster - Subcoat Asbestos Types: Other Material: Cellulose 1 %, Non-fibrous 99 %			
AS032210JM-05C 5 Location: 2nd Floor	510031331-23	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Wall Plaster - Subcoat Asbestos Types: Other Material: Cellulose 1 %, Non-fibrous 99 %			

PLM Bulk Asbestos Report

16433; ACCA

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032210JM-05D 5 Location: 3rd Floor	510031331-24	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Wall Plaster - Subcoat Asbestos Types: Other Material: Cellulose 1 %, Non-fibrous 99 %			
AS032210JM-05E 5 Location: 3rd Floor	510031331-25	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Wall Plaster - Subcoat Asbestos Types: Other Material: Cellulose 1 %, Non-fibrous 99 %			
AS032210JM-05F 5 Location: 3rd Floor	510031331-26	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Wall Plaster - Subcoat Asbestos Types: Other Material: Cellulose 2 %, Non-fibrous 98 %			
AS032210JM-05G 5 Location: 3rd Floor	510031331-27	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Brown, Homogeneous, Fibrous, Cementitious, Wall Plaster - Subcoat Asbestos Types: Other Material: Cellulose 1 %, Non-fibrous 99 %			
AS032210JM-06A 6 Location: 1st Floor	510031331-28	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Grey/Tan, Homogeneous, Fibrous, Sheetrock Asbestos Types: Other Material: Cellulose 7 %, Non-fibrous 93 %			
AS032210JM-06B 6 Location: 1st Floor	510031331-29	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Grey/Tan, Homogeneous, Fibrous, Sheetrock Asbestos Types: Other Material: Cellulose 10 %, Non-fibrous 90 %			

PLM Bulk Asbestos Report

16433; ACCA

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032210JM-07A 7 Location: 1st Floor	510031331-30	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Joint Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS032210JM-07B 7 Location: 1st Floor	510031331-31	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Joint Compound Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS032210JM-08A 8 Location: 3rd Floor - Bath	510031331-32	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Beige, Homogeneous, Fibrous, 2'x2' Ceiling Tile Asbestos Types: Other Material: Cellulose 50 %, Fibrous glass 20 %, Non-fibrous 30 %			
AS032210JM-08B 8 Location: 3rd Floor - Bath	510031331-33	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Beige, Homogeneous, Fibrous, 2'x2' Ceiling Tile Asbestos Types: Other Material: Cellulose 50 %, Fibrous glass 25 %, Non-fibrous 25 %			
AS032210JM-09A 9 Location: 1st Floor Kitchen	510031331-34	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Brick Red, Homogeneous, Non-Fibrous, Clay Floor Tile Asbestos Types: Other Material: Non-fibrous 100 %			
AS032210JM-09B 9 Location: 1st Floor Kitchen	510031331-35	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Brick Red, Homogeneous, Non-Fibrous, Clay Floor Tile Asbestos Types: Other Material: Non-fibrous 100 %			

PLM Bulk Asbestos Report

16433; ACCA

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032210JM-10A 10 Location: 1st Floor Kitchen	510031331-36	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Clay Floor Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS032210JM-10B 10 Location: 1st Floor Kitchen	510031331-37	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Clay Floor Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS032210JM-11A 11 Location: 2nd Floor Bathroom	510031331-38	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Ceramic Tile Floor Asbestos Types: Other Material: Non-fibrous 100 %			
AS032210JM-11B 11 Location: 2nd Floor Bathroom	510031331-39	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Ceramic Tile Floor Asbestos Types: Other Material: Non-fibrous 100 %			
AS032210JM-12A 12 Location: 2nd Floor Bathroom	510031331-40	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Ceramic Tile Floor Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS032210JM-12B 12 Location: 2nd Floor Bathroom	510031331-41	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Ceramic Tile Floor Grout Asbestos Types: Other Material: Non-fibrous 100 %			

PLM Bulk Asbestos Report

16433; ACCA

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032210JM-13A 13 Location: 3rd Floor	510031331-42	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Black, Homogeneous, Non-Fibrous, Ceramic Tile Asbestos Types: Other Material: Non-fibrous 100 %			
AS032210JM-13B 13 Location: 3rd Floor	510031331-43	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Black, Homogeneous, Non-Fibrous, Ceramic Tile Asbestos Types: Other Material: Non-fibrous 100 %			
AS032210JM-14A 14 Location: 3rd Floor	510031331-44	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Cementitious, Ceramic Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS032210JM-14B 14 Location: 3rd Floor	510031331-45	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, Cementitious, Ceramic Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS032210JM-15A 15 Location: 3rd Floor	510031331-46	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White/Brick Red, Homogeneous, Non-Fibrous, Clay Floor Tile Asbestos Types: Other Material: Non-fibrous 100 %			
AS032210JM-15B 15 Location: 3rd Floor	510031331-47	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: White/Brick Red, Homogeneous, Non-Fibrous, Clay Floor Tile Asbestos Types: Other Material: Non-fibrous 100 %			

Client Name: Clough, Harbour & Associates

PLM Bulk Asbestos Report

16433; ACCA

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032210JM-16A 16 Location: 3rd Floor	510031331-48	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, Cementitious, Clay Floor Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS032210JM-16B 16 Location: 3rd Floor	510031331-49	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, Cementitious, Clay Floor Tile Grout Asbestos Types: Other Material: Cellulose Trace, Non-fibrous 100 %			
AS032210JM-17A 17 Location: 1st Floor	510031331-50	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Off-White, Homogeneous, Fibrous, Sheetrock Tape Asbestos Types: Other Material: Cellulose 80 %, Non-fibrous 20 %			
AS032210JM-17B 17 Location: 3rd Floor	510031331-51	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Off-White, Homogeneous, Fibrous, Sheetrock Tape Asbestos Types: Other Material: Cellulose 80 %, Non-fibrous 20 %			
AS032210JM-18A 18 Location: 1st Floor	510031331-52	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: Cream, Homogeneous, Non-Fibrous, Wall Panel Glue Asbestos Types: Other Material: Non-fibrous 28.6 %			
AS032210JM-18B 18 Location: 1st Floor	510031331-53	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: Cream, Homogeneous, Non-Fibrous, Wall Panel Glue Asbestos Types: Other Material: Non-fibrous 28.1 %			

PLM Bulk Asbestos Report

16433; ACCA

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032210JM-19A 19	510031331-54 Location: 1st Floor - Check In	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Off-White, Homogeneous, Fibrous, Laminant Countertop Asbestos Types: Other Material: Cellulose 90 %, Non-fibrous 10 %			
AS032210JM-19B 19	510031331-55 Location: 1st Floor - Check In	No	NAD (by NYS ELAP 198.1) by Ivan H Reyes on 04/01/10
Analyst Description: Off-White, Homogeneous, Fibrous, Laminant Countertop Asbestos Types: Other Material: Cellulose 90 %, Non-fibrous 10 %			
AS032210JM-20A 20	510031331-56 Location: 1st Floor - Check In	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, 1'x1' Floor Tile-Textured Asbestos Types: Other Material: Non-fibrous 30.8 %			
AS032210JM-20B 20	510031331-57 Location: 1st Floor - Check In	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: White, Homogeneous, Non-Fibrous, 1'x1' Floor Tile-Textured Asbestos Types: Other Material: Non-fibrous 23.2 %			
AS032210JM-21A 21	510031331-58L1 Location: 1st Floor	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: Beige, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 22.6 % Comment: Tile			

PLM Bulk Asbestos Report

16433; ACCA

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032210JM-21A 21 Location: 1st Floor	510031331-58L2	Yes	Trace (<0.25 % pc) (ELAP 198.6; 400pc) by Ivan H Reyes on 04/01/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Chrysotile <0.25 % pc Other Material: Non-fibrous 14 % Comment: Mastic			
AS032210JM-21B 21 Location: 1st Floor	510031331-59L1	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: Beige, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 21.8 % Comment: Tile			
AS032210JM-21B 21 Location: 1st Floor	510031331-59L2	Yes	Trace (<0.25 % pc) (ELAP 198.6; 400pc) by Ivan H Reyes on 04/01/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Chrysotile <0.25 % pc Other Material: Non-fibrous 3.7 % Comment: Mastic			
AS032210JM-22A 22 Location: 1st Floor	510031331-60L1	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 0.8 % Comment: Tile			
AS032210JM-22A 22 Location: 1st Floor	510031331-60L2	Yes	Trace (<0.25 % pc) (ELAP 198.6; 400pc) by Ivan H Reyes on 04/01/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Chrysotile <0.25 % pc Other Material: Non-fibrous 2.7 % Comment: Mastic			

PLM Bulk Asbestos Report

16433; ACCA

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032210JM-22B 22 Location: 1st Floor	510031331-61L1	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 0.7 % Comment: Tile			
AS032210JM-22B 22 Location: 1st Floor	510031331-61L2	Yes	Trace (<0.25 % pc) (ELAP 198.6; 400pc) by Ivan H Reyes on 04/01/10
Analyst Description: Black, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Chrysotile <0.25 % pc Other Material: Non-fibrous 1.2 % Comment: Mastic			
AS032210JM-23A 23 Location: 2nd Floor	510031331-62	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 6.6 %			
AS032210JM-23B 23 Location: 1st Floor	510031331-63	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 6.6 %			
AS032210JM-24A 24 Location: 2nd Floor	510031331-64	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 24.6 %			

PLM Bulk Asbestos Report

16433; ACCA

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032210JM-24B 24 Location: 2nd Floor	510031331-65	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, 12"x12" Floor Tile Asbestos Types: Other Material: Non-fibrous 25.5 %			
AS032210JM-25A 25 Location: Bathroom	510031331-66	Yes	10 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: Brown, Homogeneous, Fibrous, Linoleum Flooring Asbestos Types: Chrysotile 10.0 % Other Material: Non-fibrous 17.6 %			
AS032210JM-25B 25 Location: Bathroom	510031331-67	Yes	8.4 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: Brown, Homogeneous, Fibrous, Linoleum Flooring Asbestos Types: Chrysotile 8.4 % Other Material: Non-fibrous 12.6 %			
AS032210JM-26A 26 Location: 3rd Floor Bathroom	510031331-68	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Linoleum Flooring Asbestos Types: Other Material: Non-fibrous 1.5 %			
AS032210JM-26B 26 Location: Bathroom	510031331-69	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: Grey, Homogeneous, Non-Fibrous, Linoleum Flooring Asbestos Types: Other Material: Non-fibrous 1.6 %			
AS032210JM-27A 27 Location: 2nd Floor Bath	510031331-70	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/01/10
Analyst Description: White/Grey, Homogeneous, Non-Fibrous, Linoleum Flooring Asbestos Types: Other Material: Non-fibrous 3.2 %			

PLM Bulk Asbestos Report

16433; ACCA

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032210JM-27B 27 Location: 2nd Floor Bath	510031331-71	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/02/10
Analyst Description: White/Grey, Homogeneous, Non-Fibrous, Linoleum Flooring Asbestos Types: Other Material: Non-fibrous 3.4 %			
AS032210JM-28A 28 Location: 2nd Floor Bath	510031331-72	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/02/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, Ext. Window Glazing Compound Asbestos Types: Other Material: Non-fibrous 12.6 %			
AS032210JM-28B 28 Location: 2nd Floor Bath	510031331-73	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/02/10
Analyst Description: Off-White, Homogeneous, Non-Fibrous, Ext. Window Glazing Compound Asbestos Types: Other Material: Non-fibrous 36.4 %			
AS032210JM-29A 29 Location: Exterior	510031331-74	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/02/10
Analyst Description: Grey/Green/Cream, Homogeneous, Non-Fibrous, Stucco Finish Asbestos Types: Other Material: Non-fibrous 29.9 %			
AS032210JM-29B 29 Location: Exterior	510031331-75	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/02/10
Analyst Description: Grey/Green/Cream, Homogeneous, Non-Fibrous, Stucco Finish Asbestos Types: Other Material: Non-fibrous 34 %			
AS032210JM-29C 29 Location: Exterior	510031331-76	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/02/10
Analyst Description: Grey/Green/Cream, Homogeneous, Non-Fibrous, Stucco Finish Asbestos Types: Other Material: Non-fibrous 31.9 %			

PLM Bulk Asbestos Report

16433; ACCA

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032210JM-29D 29 Location: Exterior	510031331-77	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/02/10
Analyst Description: Grey/Green/Cream, Homogeneous, Non-Fibrous, Stucco Finish Asbestos Types: Other Material: Non-fibrous 30.8 %			
AS032210JM-29E 29 Location: Exterior	510031331-78	No	NAD (by NYS ELAP 198.6) by Ivan H Reyes on 04/02/10
Analyst Description: Grey/Green/Cream, Homogeneous, Non-Fibrous, Stucco Finish Asbestos Types: Other Material: Non-fibrous 29.3 %			
AS032210JM-30A 30 Location: High Roof	510031331-79	Yes	Trace (<0.25 % pc) (ELAP 198.6; 400pc) by Ivan H Reyes on 04/02/10
Analyst Description: Silver/Black, Heterogeneous, Fibrous, Built-up Roofing Asbestos Types: Chrysotile <0.25 % pc Other Material: Non-fibrous 43.2 %			
AS032210JM-30B 30 Location: Low Roof	510031331-80	Yes	Trace (<0.25 % pc) (ELAP 198.6; 400pc) by Ivan H Reyes on 04/02/10
Analyst Description: Silver/Black, Heterogeneous, Fibrous, Built-up Roofing Asbestos Types: Chrysotile <0.25 % pc Other Material: Non-fibrous 26.1 %			
AS032210JM-31A 31 Location: Low Roof	510031331-81	Yes	1.9 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/02/10
Analyst Description: Silver/Black, Heterogeneous, Fibrous, Roof Tar Asbestos Types: Chrysotile 1.9 % Other Material: Non-fibrous 16.8 %			
AS032210JM-31B 31 Location: Low Roof	510031331-82	Yes	3.1 % (by NYS ELAP 198.6) by Ivan H Reyes on 04/02/10
Analyst Description: Silver/Black, Heterogeneous, Fibrous, Roof Tar Asbestos Types: Chrysotile 3.1 % Other Material: Non-fibrous 9.1 %			

Client Name: Clough, Harbour & Associates

PLM Bulk Asbestos Report

16433; ACCA

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
AS032210JM-32A 32 Location: Low Roof	510031331-83	Yes	Trace (<0.25 % pc) (ELAP 198.6; 400pc) by Ivan H Reyes on 04/02/10
Analyst Description: Silver, Homogeneous, Fibrous, Silver Coat Asbestos Types: Chrysotile <0.25 % pc Other Material: Non-fibrous 41 %			
AS032210JM-32B 32 Location: Low Roof	510031331-84	Yes	Trace (<0.25 % pc) (ELAP 198.6; 400pc) by Ivan H Reyes on 04/01/10
Analyst Description: Silver, Homogeneous, Fibrous, Silver Coat Asbestos Types: Chrysotile <0.25 % pc Other Material: Non-fibrous 30 %			

Reporting Notes:Analyzed by: Ivan H Reyes ; Date Analyzed: 4/1/10

NAD = no asbestos detected; CVES = Calibrated Visual Estimate; NA = not analyzed; NA/PS = not analyzed / positive stop; "Present" or NVA = "No Visible Asbestos" are observations made during a qualitative analysis; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #102079-0) or NY ELAP PLM Analysis Protocol 198.1 for New York friable samples (198.6 for NOB samples) (NY ELAP Lab # 10982); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. NAD or Trace results by PLM are inconclusive, TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). NIST Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested.

Reviewed By: _____

Relinquished By:  Date/Time: 3/23/10
 Received By:  Date/Time: 3/31/10
 Relinquished By:  Date/Time: 3/31/10

AMERISCI
 BOSTON
 AmeriSci Boston
 8 School Street
 Weymouth, MA 02189
 Phone: (781) 337-9334
 Fax: (781) 337-7642
 TOLL FREE: (800) 724-5221
 WWW.AMERISCI.COM

Company: **CHA** Project: **ACCA** SciLab #: **510031331**
 Street Address: 3 Winners Circle Project Address: Project #: 16433

City: Albany State: NY Zip: 12205
 Phone: (518) 453-3915 Fax: (518) 453-4773
 E-Mail: imorey@cha-llp.com Cell: (315) 440-1670
 E-Mail Results: Yes Turnaround Time: 5-DAY Material Type: ☒ Bulk ☐ Dust
 Site/Secondary Fax #: Sampled By: J. Morey Date Sampled: 03/22/10
 Results to: Jim Morey 3 Winners Circle Albany, NY 12205
 Special Instructions or Comments: ALL SAMPLES RECEIVED BY: AS032210JMN-

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Ar (HA #)
1 01A	Textured Ceiling Paint	2 nd Fl.	
2 01B	"	2 nd Fl.	
3 01C	"	2 nd Fl.	
4 02A	Ceiling Plaster - Skimcoat	2 nd Fl.	
5 02B	"	"	
6 02C	"	2 nd Fl.	
7 02D	"	"	
8 02E	"	2 nd Fl.	
9 03A	Subcoat	2 nd Fl.	
10 03B	"	"	
11 03C	"	"	
12 03D	"	3 rd Fl.	
13 03E	"	"	
14 04A	Wall Plaster - Skimcoat	2 nd Fl.	
15 04B	"	"	
16 04C	"	"	

[Signature]

Date/Time: 03/23/10
Date/Time:
Date/Time: 7/21/10
Date/Time: 10/15

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM



SCILAS #:

510031331

CLUB HARBOR ASSOCIATES LLP

Street Address: 3 Winners Circle

City: Albany State: NY Zip: 12205
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670

ite/Secondary Fax #:

Results to: Jim Morey 3 Winners Circle Albany, NY 12205

Special Instructions or Comments:

Project Address:

Project Manager:

Analysis: PLM Only TEM Only NY ELAP PLM/TEM with NOB Prep.
ASTM Dust (microvac) ASTM Dust (Wipe) Other (describe in comment)

Turnaround Time: 5-DAY

Material Type: Bulk Dust

Sampled By: J. Morey

Date Sampled: 03/22/10

Homogenous Ar (HA #)

Sample Description (for dust= size of surface area sampled)

Location

Field ID

17-04D	Wall Plaster - Skimcoat	3rd Fl.	
18-01E	"		
19-01F	"		
20-04G	"		
21-05A	Subsoil	2nd Floor	
22-05B	"		
23-05C	"		
24-05D	"		
25-05E	"		
26-05F	"		
27-05G	"		
28-06A	Sheetrock	3rd Floor	
29-06B	"		
30-07A	Joint Compound		
31-07B	"		
32-08A	2x2' Ceiling Tile	3rd Fl. Data	

Relinquished By: 
 Received By: 
 Relinquished By: 

Date/Time: 3/23/10
 Date/Time:
 Date/Time: 3/23/10
 Date/Time: 10/5

AMERISCI
 BOSTON
 AmeriSci Boston
 8 School Street
 Weymouth, MA 02189
 Phone: (781) 337-9334
 Fax: (781) 337-7642
 TOLL FREE: (800) 724-5221
 WWW.AMERISCI.COM

Received By:
 Company: **CHA**
 CHA CHAMBER & ASSOCIATES LLP
 Street Address: 3 Winners Circle
 City: Albany State: NY Zip: 12205
 Phone: (518) 453-3915 Fax: (518) 453-4773
 E-Mail: jmorey@chs-llp.com Cell: (315) 440-1670

Project: 510031331
 Project Address:
 Project Manager:
 Analysis: PLM Only TEM Only NY ELAP PLM/TEM with NOB Prep.
 ASTM Dust (microvac) ASTM Dust (Wipe) Other (describe in comments)
 Turnaround Time: 5-DAY Material Type: Bulk Dust
 Sampled By: J. Morey Date Sampled: 03/22/10

Special Instructions or Comments:
 Field ID
 33-08B
 34-09A
 35-09B
 36-10A
 37-10B
 38-11A
 39-11B
 40-12A
 41-12B
 42-13A
 43-13B
 44-14A
 45-14B
 46-15A
 47-15B

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Ar (HA #)
33-08B	2'x2' Ceiling Tile	3rd Fl. Bathroom	
34-09A	Clay Floor Tile	1st Floor - Kitchen	
35-09B	GROUT to Clay Floor Tile		
36-10A	"		
37-10B	White Ceramic Tile - Floor	2nd Fl. Bathroom	
38-11A	"	"	
39-11B	GROUT to White Ceramic Tile	"	
40-12A	"	"	
41-12B	Black Ceramic Tile	Third Fl.	
42-13A	"		
43-13B	GROUT to Ceramic Tile		
44-14A	"		
45-14B	Clay Floor Tile		
46-15A	"		
47-15B	"		

Relinquished By:  Date/Time: 3/23/10
 Received By:  Date/Time: 3/23/10
 Relinquished By:  Date/Time: 3/23/10
 Received By:  Date/Time: 3/23/10



AmeriSci Boston
 8 School Street
 Weymouth, MA 02189
 Phone: (781) 337-9334
 Fax: (781) 337-7642
 TOLL FREE: (800) 724-5221
 WWW.AMERISCI.COM



CLUB CHAIRMAN & ASSOCIATES LLP

Project #: 510031331

Project #: 16433

Project Address:
 Project Manager:
 Analysis: ☐ PLM Only ☒ TEM Only ☒ NY ELAP PLM/TEM with NOB Prep.
☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe) ☐ Other (describe in comment)
 Turnaround Time: 5-Day Material Type: ☒ Bulk ☐ Dust
 E-Mail Results: Yes Turnaround Time: 5-Day Date Sampled: 03/22/10
 Sampled By: J. Morey

Special Instructions or Comments:

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Air (HA #)
48 16A	Grout to Ceramic Tile	Third Fl.	
49 16B		"	
50 17A	Sheetrock TAPE	First Floor	
51 17B		Third Floor	
52 18A	Wall Panel Glue	First Floor	
53 18B		"	
54 19A	Laminate Countertop	First Fl. - Check-in	
55 19B	"	"	
56 20A	1'x1' Floor Tile - Textured	"	
57 20B		"	
58 21A	Beige 12x12 Floor Tile	First Floor	
59 21B		"	
60 22A	White 12x12 Floor Tile	↓	
61 22B		"	
62 23A	Gray 12x12 Floor Tile	2nd Fl.	
63 23B		"	

Relinquished By: 
 Received By: 
 Relinquished By: 
 Received By:

Date/Time: 3/23/10
 Date/Time:
 Date/Time:
 Date/Time: 3/31/10
 Date/Time: 10/15

AMERISCI
 BOSTON
 AmeriSci Boston
 8 School Street
 Weymouth, MA 02189
 Phone: (781) 337-9334
 Fax: (781) 337-7642
 TOLL FREE: (800) 724-5221
 WWW.AMERISCI.COM



Company: CHA
 CHA, CH HARRISON & ASSOCIATES LLP

Project: 510031331
 Project #: 16433

Project Address:
 Project Manager:
 Analysis: ☐ PLM Only ☐ TEM Only ☒ NY ELAP PLM/TEM with NOB Prep.
☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe) ☐ Other (describe in comment)
 Material Type: ☒ Bulk ☐ Dust
 Turnaround Time: 5-Day
 Date Sampled: 03/22/10
 Sampled By: J. Morey
 E-Mail Results: Yes
 Zip: 12205
 State: NY
 City: Albany
 Phone: (518) 453-3915
 Fax: (518) 453-4773
 Cell: (315) 440-1870
 E-Mail: jmorey@cha-llp.com
 Results to: Jim Morey 3 Winners Circle Albany, NY 12205
 E-Mail Results: Yes

Special Instructions or Comments:

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Air (HA #)
+ 64-24A	Streetside 12x12 Floor Tile	2nd Fl.	
+ 65-24B	"	"	
+ 66-25A	Linoleum Flooring - Brown	Bathroom	
+ 67-25B	"	"	
- 68-26A	Grog Linoleum Flooring	3rd Fl. Bathrooms	
+ 69-26B	"	"	
+ 70-27A	Linoleum Flooring	2nd Fl. Bath	
+ 71-27B	"	"	
+ 72-28A	Exterior Window Glazing Compound		
+ 73-28B	"		
- 74-29A	Stucco Finish	Exterior	
+ 75-29B			
+ 76-29C			
+ 77-29D			
+ 78-29E			

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
01 Location: 2nd Floor	AS032210JM-01A	1	0.595	21.0	39.6	39.4	NAD	NAD
02 Location: 2nd Floor	AS032210JM-01B	1	0.311	17.4	47.0	35.5	NAD	NAD
03 Location: 2nd Floor	AS032210JM-01C	1	0.238	24.3	42.6	33.1	NAD	NAD
04 Location: 2nd Floor	AS032210JM-02A	2	---	---	---	---	NAD	NA
05 Location: 2nd Floor	AS032210JM-02B	2	---	---	---	---	NAD	NA
06 Location: 2nd Floor	AS032210JM-02C	2	---	---	---	---	NAD	NA
07 Location: 3rd Floor	AS032210JM-02D	2	---	---	---	---	NAD	NA
08 Location: 3rd Floor	AS032210JM-02E	2	---	---	---	---	NAD	NA
09 Location: 2nd Floor	AS032210JM-03A	3	---	---	---	---	NAD	NA
10 Location: 2nd Floor	AS032210JM-03B	3	---	---	---	---	NAD	NA
11 Location: 2nd Floor	AS032210JM-03C	3	---	---	---	---	NAD	NA
12 Location: 3rd Floor	AS032210JM-03D	3	---	---	---	---	NAD	NA
13 Location: 3rd Floor	AS032210JM-03E	3	---	---	---	---	NAD	NA
14 Location: 2nd Floor	AS032210JM-04A	4	---	---	---	---	NAD	NA
15 Location: 2nd Floor	AS032210JM-04B	4	---	---	---	---	NAD	NA
16 Location: 2nd Floor	AS032210JM-04C	4	---	---	---	---	NAD	NA

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
17 Location: 3rd Floor	AS032210JM-04D	4	---	----	----	----	NAD	NA
18 Location: 3rd Floor	AS032210JM-04E	4	---	----	----	----	NAD	NA
19 Location: 3rd Floor	AS032210JM-04F	4	---	----	----	----	NAD	NA
20 Location: 3rd Floor	AS032210JM-04G	4	---	----	----	----	NAD	NA
21 Location: 2nd Floor	AS032210JM-05A	5	---	----	----	----	NAD	NA
22 Location: 2nd Floor	AS032210JM-05B	5	---	----	----	----	NAD	NA
23 Location: 2nd Floor	AS032210JM-05C	5	---	----	----	----	NAD	NA
24 Location: 3rd Floor	AS032210JM-05D	5	---	----	----	----	NAD	NA
25 Location: 3rd Floor	AS032210JM-05E	5	---	----	----	----	NAD	NA
26 Location: 3rd Floor	AS032210JM-05F	5	---	----	----	----	NAD	NA
27 Location: 3rd Floor	AS032210JM-05G	5	---	----	----	----	NAD	NA
28 Location: 1st Floor	AS032210JM-06A	6	---	----	----	----	NAD	NA
29 Location: 1st Floor	AS032210JM-06B	6	---	----	----	----	NAD	NA
30 Location: 1st Floor	AS032210JM-07A	7	---	----	----	----	NAD	NA
31 Location: 1st Floor	AS032210JM-07B	7	---	----	----	----	NAD	NA
32 Location: 3rd Floor - Bath	AS032210JM-08A	8	---	----	----	----	NAD	NA

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
33	AS032210JM-08B Location: 3rd Floor - Bath	8	----	-----	-----	-----	NAD	NA
34	AS032210JM-09A Location: 1st Floor Kitchen	9	----	-----	-----	-----	NAD	NA
35	AS032210JM-09B Location: 1st Floor Kitchen	9	----	-----	-----	-----	NAD	NA
36	AS032210JM-10A Location: 1st Floor Kitchen	10	----	-----	-----	-----	NAD	NA
37	AS032210JM-10B Location: 1st Floor Kitchen	10	----	-----	-----	-----	NAD	NA
38	AS032210JM-11A Location: 2nd Floor Bathroom	11	----	-----	-----	-----	NAD	NA
39	AS032210JM-11B Location: 2nd Floor Bathroom	11	----	-----	-----	-----	NAD	NA
40	AS032210JM-12A Location: 2nd Floor Bathroom	12	----	-----	-----	-----	NAD	NA
41	AS032210JM-12B Location: 2nd Floor Bathroom	12	----	-----	-----	-----	NAD	NA
42	AS032210JM-13A Location: 3rd Floor	13	----	-----	-----	-----	NAD	NA
43	AS032210JM-13B Location: 3rd Floor	13	----	-----	-----	-----	NAD	NA
44	AS032210JM-14A Location: 3rd Floor	14	----	-----	-----	-----	NAD	NA
45	AS032210JM-14B Location: 3rd Floor	14	----	-----	-----	-----	NAD	NA
46	AS032210JM-15A Location: 3rd Floor	15	----	-----	-----	-----	NAD	NA
47	AS032210JM-15B Location: 3rd Floor	15	----	-----	-----	-----	NAD	NA
48	AS032210JM-16A Location: 3rd Floor	16	----	-----	-----	-----	NAD	NA

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
49 Location: 3rd Floor	AS032210JM-16B	16	---	---	---	---	NAD	NA
50 Location: 1st Floor	AS032210JM-17A	17	---	---	---	---	NAD	NA
51 Location: 3rd Floor	AS032210JM-17B	17	---	---	---	---	NAD	NA
52 Location: 1st Floor	AS032210JM-18A	18	0.454	38.8	32.5	28.6	NAD	NAD
53 Location: 1st Floor	AS032210JM-18B	18	0.279	39.8	32.1	28.1	NAD	NAD
54 Location: 1st Floor - Check In	AS032210JM-19A	19	---	---	---	---	NAD	NA
55 Location: 1st Floor - Check In	AS032210JM-19B	19	---	---	---	---	NAD	NA
56 Location: 1st Floor - Check In	AS032210JM-20A	20	0.758	36.5	32.8	30.8	NAD	NAD
57 Location: 1st Floor - Check In	AS032210JM-20B	20	0.455	38.0	38.8	23.2	NAD	NAD
58L1 Location: 1st Floor	AS032210JM-21A	21	0.275	28.9	48.5	22.6	NAD	NAD
58L2 Location: 1st Floor	AS032210JM-21A	21	0.038	48.7	37.3	13.9	Chrysotile <0.25	Chrysotile Trace
59L1 Location: 1st Floor	AS032210JM-21B	21	0.299	28.0	50.2	21.8	NAD	NAD
59L2 Location: 1st Floor	AS032210JM-21B	21	0.016	51.6	44.7	3.6	Chrysotile <0.25	Chrysotile Trace
60L1 Location: 1st Floor	AS032210JM-22A	22	0.379	17.9	81.2	0.8	NAD	NAD
60L2 Location: 1st Floor	AS032210JM-22A	22	0.018	68.5	28.8	2.6	Chrysotile <0.25	Chrysotile Trace
61L1 Location: 1st Floor	AS032210JM-22B	22	0.276	17.8	81.6	0.7	NAD	NAD

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
61L2	AS032210JM-22B	22	0.017	58.3	40.5	1.1	Chrysotile <0.25	Chrysotile Trace
Location: 1st Floor								
62	AS032210JM-23A	23	0.451	18.5	74.9	6.6	NAD	NAD
Location: 2nd Floor								
63	AS032210JM-23B	23	0.360	18.5	74.9	6.6	NAD	NAD
Location: 1st Floor								
64	AS032210JM-24A	24	0.343	23.3	52.1	24.6	NAD	NAD
Location: 2nd Floor								
65	AS032210JM-24B	24	0.446	23.1	51.4	25.5	NAD	NAD
Location: 2nd Floor								
66	AS032210JM-25A	25	0.200	67.9	4.6	17.6	Chrysotile 10.0	NA
Location: Bathroom								
67	AS032210JM-25B	25	0.150	75.2	3.8	12.6	Chrysotile 8.4	NA
Location: Bathroom								
68	AS032210JM-26A	26	0.316	23.6	74.9	1.5	NAD	NAD
Location: 3rd Floor Bathroom								
69	AS032210JM-26B	26	0.444	24.4	73.9	1.6	NAD	NAD
Location: Bathroom								
70	AS032210JM-27A	27	0.233	21.8	75.0	3.2	NAD	NAD
Location: 2nd Floor Bath								
71	AS032210JM-27B	27	0.300	21.8	74.7	3.4	NAD	NAD
Location: 2nd Floor Bath								
72	AS032210JM-28A	28	0.627	10.6	76.8	12.6	NAD	NAD
Location: 2nd Floor Bath								
73	AS032210JM-28B	28	0.890	8.7	54.9	36.4	NAD	NAD
Location: 2nd Floor Bath								
74	AS032210JM-29A	29	0.277	47.5	22.6	29.9	NAD	NAD
Location: Exterior								
75	AS032210JM-29B	29	0.273	46.6	19.5	34.0	NAD	NAD
Location: Exterior								
76	AS032210JM-29C	29	0.333	48.5	19.6	31.9	NAD	NAD
Location: Exterior								

See Reporting notes on last page

Table I
Summary of Bulk Asbestos Analysis Results
 16433; ACCA

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
77 Location: Exterior	AS032210JM-29D	29	0.232	51.9	17.2	30.8	NAD	NAD
78 Location: Exterior	AS032210JM-29E	29	0.241	48.8	21.9	29.3	NAD	NAD
79 Location: High Roof	AS032210JM-30A	30	0.521	45.1	11.7	34.6	Chrysotile <0.25	Chrysotile 8.64
80 Location: Low Roof	AS032210JM-30B	30	0.331	61.4	12.5	20.9	Chrysotile <0.25	Chrysotile 5.22
81 Location: Low Roof	AS032210JM-31A	31	0.244	76.3	5.0	16.8	Chrysotile 1.9	NA
82 Location: Low Roof	AS032210JM-31B	31	0.297	84.0	3.7	9.2	Chrysotile 3.1	NA
83 Location: Low Roof	AS032210JM-32A	32	0.389	54.4	4.6	32.8	Chrysotile <0.25	Chrysotile 8.2
84 Location: Low Roof	AS032210JM-32B	32	0.422	53.0	17.0	27.0	Chrysotile <0.25	Chrysotile 3.0

Reviewed by: _____

Date Reviewed: _____

Analyzed By: Sandhya Gunasekara

Date Analyzed: 4/5/2010

Semi-Quantitative Analysis: NAD = no asbestos detected; NA = not analyzed; NA/PS = not analyzed due to positive stop; Trace = <1%;
 PLM analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #102079-0) or NY ELAP 198.6 for New York NOB samples (NY ELAP Lab # 10982);
 TEM analysis by EPA 600/R-93/116 (not covered by NVLAP Bulk accreditation) or NY ELAP 198.4 for New York NOB samples (NY ELAP Lab # 10982);

** Warning Notes: Consider PLM fiber diameter limitation, only TEM will resolve fibers <0.25 micrometers in diameter. TEM bulk analysis is representative of the fine grained matrix material and may not be representative of non-uniformly dispersed debris, soils or other heterogeneous materials for which a combination PLM/TEM evaluation is recommended; Quantitation for beginning weights of <0.1 grams should be considered as qualitative only.

Relinquished By:  Date/Time: 3/23/10
 Received By:  Date/Time:
 Relinquished By:  Date/Time: 3/31/10 10:15
 Received By:  Date/Time:

AMERISCI BOSTON
 AmeriSci Boston
 8 School Street
 Weymouth, MA 02189
 Phone: (781) 337-9334
 Fax: (781) 337-7642
 TOLL FREE: (888) 724-5221
 WWW.AMERISCI.COM

CHA CHARTER HARBOR & ASSOCIATES LLP
 Project: ACCA SciLab #: 510031331
 Company: 16473

Street Address: 3 Winners Circle
 City: Albany State: NY Zip: 12205
 Phone: (518) 453-3915 Fax: (518) 453-4773
 E-Mail: jmorey@cha-llp.com E-Mail Results: Yes
 Site/Secondary Fax #: 3 Winners Circle Albany, NY 12205
 Results to: Jim Morey
 Special Instructions or Comments: All samples preceded by: A5032210JM-

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Air (HA #)
1 01A	Textured Ceiling Paint	2 nd Fl.	
2 01B	"	2 nd Fl.	
3 01C	"	2 nd Fl.	
4 02A	Ceiling Plaster - Skimcoat	2 nd Fl.	
5 02B	"	"	
6 02C	"	2 nd Fl.	
7 02D	"	"	
8 02E	"	2 nd Fl.	
9 03A	Subcoat	2 nd Fl.	
10 03B	"	"	
11 03C	"	3 rd Fl.	
12 03D	"	"	
13 03E	"	2 nd Fl.	
14 04A	Wall Plaster - Skimcoat	"	
15 04B	"	"	
16 04C	"	"	


[Signature]

Date/Time: 03/23/10
Date/Time:
Date/Time:
Date/Time: 7/21/10
Date/Time: 10/5

AMERISCI
BOSTON

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM

Received By:



Project:

SciLab #: 510031331

Company:

CHACH HANCOCK & ASSOCIATES LLP

Project #: 16433

Street Address: 3 Winners Circle

Project Address:

City: Albany State: NY Zip: 12206
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670

Project Manager:
Analysis: PLM Only TEM Only X NY ELAP PLM/TEM with NOB Prep.
ASTM Dust (microvac) ASTM Dust (Wipe) Other (describe in comments)

Site/Secondary Fax #:

E-Mail Results: Yes

Material Type: Bulk Dust

Results to: Jim Morey

3 Winners Circle Albany, NY 12206

Turnaround Time: 5-DAY
Sampled By: J. Morey
Date Sampled: 03/22/10

Special Instructions or Comments:

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Air (HA #)
17-04D	Wall Plaster - Skim-coat	3rd Fl.	
18-01E	"		
19-01F	"		
20-04G	"		
21-05A	Sub-coat	2nd Floor	
22-05B	"		
23-05C	"		
24-05D	"	3rd Fl.	
25-05E	"		
26-05F	"		
27-05G	"	1st Floor	
28-06A	Sheetrock		
29-06B	"		
30-07A	Joint Compound		
31-07B	"		
32-08A	2x2' Ceiling Tile	3rd Fl. Data	

Relinquished By: *[Signature]* Date/Time: 3/23/10
 Received By: *[Signature]* Date/Time: 3/23/10
 Relinquished By: *[Signature]* Date/Time: 3/23/10
 Received By: *[Signature]* Date/Time: 3/23/10

AMERISCI
 BOSTON
 AmeriSci Boston
 8 School Street
 Weymouth, MA 02189
 Phone: (781) 337-9334
 Fax: (781) 337-7642
 TOLL FREE: (800) 724-5221
 WWW.AMERISCI.COM

Company: **CHA**
 CHA GROUP HARBOR & ASSOCIATES LLP
 Street Address: 3 Winners Circle
 Albany, NY State: NY Zip: 12205
 Phone: (518) 453-3915 Fax: (518) 453-4773
 E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670
 E-Mail Results: Yes
 Project Address: *[Blank]*
 Project Manager: *[Blank]*
 Analysis: ☐ PLM Only ☒ TEM Only ☒ NY ELAP PLM/TEM with NOB Prep.
☐ ASTM Dust (microvac) ☐ ASTM Dust (Wipe) ☐ Other (describe in comments)

Material Type: ☒ Bulk ☐ Dust
 Turnaround Time: 5-DAY
 Sampled By: J. Morey
 Date Sampled: 03/22/10
 Project #: 16433
 SciLab #: 510031331

Special Instructions or Comments:

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Air (HA #)
33-08B	2'x2' Ceiling Tile	3rd Fl. Bathroom	
34-09A	Clay Floor Tile	1st Floor - Kitchen	
35-09B	GROUT to Clay Floor Tile		
36-10A	"		
37-10B	White Ceramic Tile - Floor	2nd Fl. Bathroom	
38-11A	"	"	
39-11B	GROUT to White Ceramic Tile	"	
40-12A	"	"	
41-12B	Black Ceramic Tile	Third Fl.	
42-13A	"		
43-13B	GROUT to Ceramic Tile		
44-14A	"		
45-14B	Clay Floor Tile		
46-15A	"		
47-15B	"		

Relinquished By: 
 Received By: 
 Relinquished By: 
 Received By:

Date/Time: 3/23/10
 Date/Time:
 Date/Time:
 Date/Time: 3/31/10
 Date/Time: 10/5

AMERISCI
 BOSTON
 AmeriSci Boston
 8 School Street
 Weymouth, MA 02189
 Phone: (781) 337-9334
 Fax: (781) 337-7642
 TOLL FREE: (800) 724-5221
 WWW.AMERISCI.COM

CHA
 CLIAUGH HANCOCK & ASSOCIATES LLP

Project: **510031331**
 Project #: **16433**
 Project Address:
 Project Manager:
 Analysis: PLM Only TEM Only NY ELAP PLM/TEM with NOB Prep.
ASTM Dust (microvac) ASTM Dust (Wipe) Other (describe in comments)
 Turnaround Time: 5-Day Material Type: Δ Bulk Dust
 Sampled By: J. Morrey Date Sampled: 03/22/10

City: Albany State: NY Zip: 12206
 Phone: (518) 453-3916 Fax: (518) 453-4773
 E-Mail: jmorey@cha-llp.com E-Mail Results: Yes
 Results to: Jim Morrey 3 Winners Circle Albany, NY 12206
 Special Instructions or Comments:

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Air (HA #)
+ 64-24A	Streeted 12x12 Floor Tile	2nd Fl.	
65-24B	"	"	
+ 66-25A	Linoleum Flooring - Brown	Bathroom	
67-25B	"	"	
- 68-26A	Gray Linoleum Flooring	3rd Fl. Bathroom	
69-26D	"	"	
+ 70-27A	Linoleum Flooring	2nd Fl. Bath	
71-27B	"	"	
72-28A	Exterior Window Glazing Compound		
73-28B	"		
- 74-29A	Stucco Finish	Exterior	
75-29B			
76-29C			
77-29D			
78-29E			

Relinquished By: 
Received By: 
Relinquished By: 
Received By:

Date/Time: 3/23/10
Date/Time:
Date/Time:
Date/Time: 3/23/10

AmeriSci Boston
8 School Street
Weymouth, MA 02189
Phone: (781) 337-9334
Fax: (781) 337-7642
TOLL FREE: (800) 724-5221
WWW.AMERISCI.COM



Project: 510031331
Project #: 16433

Company: CHA
Street Address: 3 Winners Circle
City: Albany State: NY Zip: 12206
Phone: (518) 453-3915 Fax: (518) 453-4773
E-Mail: jmorey@cha-llp.com Cell: (315) 440-1670
Turnaround Time: 5-DAY
Material Type: Bulk
Date Sampled: 03/22/10

Special Instructions or Comments:

Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Air (HA #)
79 30A	Built-up Roofing	High Roof	
80 30B		Low Roof	
81 31A	Roof TAR	Low Roof	
82 31B	"	"	
83 32A	Silvercoat	"	
84 32B	"	"	

APPENDIX B
Personnel and Laboratory Certifications

NEW YORK STATE - DEPARTMENT OF LABOR

DIVISION OF SAFETY AND HEALTH
LICENSE AND CERTIFICATE UNIT
STATE CAMPUS BUILDING 12
ALBANY, NY 12240

ASBESTOS HANDLING LICENSE

Clough, Harbour & Associates LLP
III Winners Circle
Albany, NY 12205

FILE NUMBER: 99-0054
LICENSE NUMBER: 29056
LICENSE CLASS: RESTRICTED
DATE OF ISSUE: 06/19/2009
EXPIRATION DATE: 06/30/2010

Duly Authorized Representative – Margaret M Rudzinski:

This license has been issued in accordance with applicable provisions of Article 30 of the Labor Law of New York State and of the New York State Codes, Rules and Regulations (12 NYCRR Part 56). It is subject to suspension or revocation for a (1) serious violation of state, federal or local laws with regard to the conduct of an asbestos project, or (2) demonstrated lack of responsibility in the conduct of any job involving asbestos or asbestos material.

This license is valid only for the contractor named above and this license or a photocopy must be prominently displayed at the asbestos project worksite. This license verifies that all persons employed by the licensee on an asbestos project in New York State have been issued an Asbestos Certificate, appropriate for the type of work they perform, by the New York State Department of Labor.




Maureen A. Cox, Director
FOR THE COMMISSIONER OF LABOR

STATE OF NEW YORK - DEPARTMENT OF LABOR
ASBESTOS CERTIFICATE



JAMES N MOREY
CLASS (EXPIRES)
D/INSP (08/10)



CERT# 00-11983
DMV# 589756376

MUST BE CARRIED ON ASBESTOS PROJECTS

NEW YORK STATE DEPARTMENT OF HEALTH
WADSWORTH CENTER
RICHARD F. DAINES, M.D.



Expires 12:01 AM April 01, 2010
Issued April 01, 2009

CERTIFICATE OF APPROVAL FOR LABORATORY SERVICE

Issued in accordance with and pursuant to section 502 Public Health Law of New York State

MS. NICOLE CORTESE
AMERISCI BOSTON
8 SCHOOL STREET
EAST WEYMOUTH, MA 02189

NY Lab Id No: 10982
EPA Lab Code: MA00069

*is hereby APPROVED as an Environmental Laboratory for the category
ENVIRONMENTAL ANALYSES SOLID AND HAZARDOUS WASTE
All approved subcategories and/or analytes are listed below:*

Miscellaneous

Asbestos in Friable Material	EPA 600/M4/82/020
	Item 198.1 of Manual
Asbestos in Non-Friable Material-PLM	Item 198.6 of Manual (NOB by PLM)
Asbestos in Non-Friable Material-TEM	ITEM 198.4 OF MANUAL

Serial No.: 39859

Property of the New York State Department of Health. Valid only at the address shown. Must be conspicuously posted. Valid certificates have a raised seal. Continued accreditation depends on successful ongoing participation in the Program. Consumers are urged to call (518) 485-5570 to verify laboratory's accreditation status.